5PE.5957

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

| (OAHP use | only) | Rev. 9/98 |
|------------|--|-----------|
| Date | Initials | |
| Determin | ed Eligible-National Register | |
| Determin | | |
| Determin | | |
| Determin | ed Not Eligible - State Register | |
| Need Dat | a | |
| Contributi | ing to eligible National Register District | |

Parcel number(s):

525215009



I. IDENTIFICATION

1. Resource number: 5PE.5957

2. Temporary resource number:

3. County: Pueblo4. City: Pueblo

Historic building name: 1712 Craig Street
 Current building name: 1712 Craig Street
 Building address: 1712 Craig Street

8. Owner name: Gina R. Gonzales Salazar and Jim C. Salazar

Owner organization:

Owner address: 1712 Craig St

Pueblo, CO 81003

| 44. | National Register eligibility field assessment: | ☐ Individually eligible | Not eligible | ☐ Need data |
|-----|---|-------------------------|--------------|-------------|
| | Local landmark eligibility field assessment: | Individually eligible | Not eligible | ■ Need data |

1712 Craig Street 5PE.5957

(Resource number)

Architectural Inventory Form

Page 2

| plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. A saddition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (veinght, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. We shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It has wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The post the principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the | | | | | | | | | | ATION | RMA | NFO | HIC IN | API | :OGR | I. GE |
|--|--|---|--------------|-----------|---------|--------|---------|---------|--------|------------|--------------------|---------|-----------|--------|--------|--------|
| Lot(s) : South 56 feet of Lots 5 and 5; Block 19 | 65W | 65W | e: 65 | Rang | | | 20S | 2 | nship: | Tow | | | 6th | (| P.M.: | 9. |
| Easting: 533485 Northing: 4237099 11. USGS quad name: Northeast Pueblo Scale: 7.5 Year: 1961 (Photorevised 1970 and 1974) 12. Lot(s): South 56 feet of Lots 5 and 5; Block 19 Addition: Craig's Addition Year of addition: 1871 13. Boundary description and justification: The boundary, as described above, contains but does not exceed the land historically associated with this proper Metes and bounds exist: III. ARCHITECTURAL DESCRIPTION | ion 25 | ion 25 | of Section | 4 | NW | of | 1/4 | SE | of | 1/4 | NE | of | 1/4 | NE | | |
| 11. USGS quad name: Northeast Pueblo Scale: 7.5 Year: 1961 (Photorevised 1970 and 1974) 12. Lot(s): South 56 feet of Lots 5 and 5; Block 19 Addition: Craig's Addition Year of addition: 1871 13. Boundary description and justification: The boundary, as described above, contains but does not exceed the land historically associated with this proper Metes and bounds exist: III. ARCHITECTURAL DESCRIPTION 14. Building plan (footprint, shape): Rectangular Plan Other building plan descriptions: 15. Dimensions in feet (length x width): 636 square feet 16. Number of stories: 1 17. Primary external wall material(s): Synthetics/Vinyl Other wall materials: Wood/Plywood/Particle Board 18. Roof configuration: Gabled Roof/Front Gabled Roof Other roof configurations: 19. Primary external roof material: Asphalt Roof/Composition Roof Other roof materials: 20. Special features: Car Port Porch 21. General architectural description: Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. As a addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (velight, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. W shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It h wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The porther principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the froof, and the rafter and perlin ends are exposed but capped by a fascia board. | | | | | | | | | | 13 | | one: | ence z | refer | UTM | 10. |
| Year: 1961 (Photorevised 1970 and 1974) 12. Lot(s): South 56 feet of Lots 5 and 5; Block 19 Addition: Craig's Addition Year of addition: 1871 13. Boundary description and justification: The boundary, as described above, contains but does not exceed the land historically associated with this proper Metes and bounds exist: III. ARCHITECTURAL DESCRIPTION | 4237099 | 4237099 | | Northing: | | | | | ; | 533485 | | | | ng: | Eastir | |
| 1974) 12. Lot(s): South 56 feet of Lots 5 and 5; Block 19 Addition: Craig's Addition Year of addition: 1871 13. Boundary description and justification: The boundary, as described above, contains but does not exceed the land historically associated with this proper Metes and bounds exist: | 7.5 | 7.5 | | Scale: | | | | ueblo | ast P | Northe | | e: | ıd nam | G qua | USGS | 11. |
| Addition: Craig's Addition Year of addition: 1871 13. Boundary description and justification: The boundary, as described above, contains but does not exceed the land historically associated with this proper Metes and bounds exist: | | | | | | 0 and | ed 197 | revise | hoto | • | | | | | Year: | |
| 13. Boundary description and justification: The boundary, as described above, contains but does not exceed the land historically associated with this proper Metes and bounds exist: Metes and bounds exist: | | | | 19 | Block | and 5 | ots 5 | et of L | 56 fe | South | | | | : | Lot(s) | 12. |
| The boundary, as described above, contains but does not exceed the land historically associated with this proper Metes and bounds exist: | 1871 | 1871 | ddition: | ear of a | | | | ition | Add | Craig's | | | | on: | Additi | |
| III. ARCHITECTURAL DESCRIPTION 14. Building plan (footprint, shape): Rectangular Plan Other building plan descriptions: 15. Dimensions in feet (length x width): 636 square feet 16. Number of stories: 1 17. Primary external wall material(s): Synthetics/Vinyl Other wall materials: Wood/Plywood/Particle Board 18. Roof configuration: Gabled Roof/Front Gabled Roof Other roof configurations: 19. Primary external roof material: Asphalt Roof/Composition Roof Other roof materials: 20. Special features: Car Port Porch 21. General architectural description: Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. A s addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (velight, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. W shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It h wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The pothe principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the froroof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | | | | | | | | | on: | ıstificati | and ju | tion a | descrip | dary | Bound | 13. |
| III. ARCHITECTURAL DESCRIPTION 14. Building plan (footprint, shape): Rectangular Plan Other building plan descriptions: 15. Dimensions in feet (length x width): 636 square feet 16. Number of stories: 1 17. Primary external wall material(s): Synthetics/Vinyl Wood/Plywood/Particle Board 18. Roof configuration: Gabled Roof/Front Gabled Roof Other roof configurations: 19. Primary external roof material: Asphalt Roof/Composition Roof Other roof materials: 20. Special features: Car Port Porch 21. General architectural description: Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. As addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (we light, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. W shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It h wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The pothe principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the for roof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | torically associated with this property. | torically asso | nd histo | ed the la | not exc | loes i | s but (| ntain | ve, co | ed abo | cribe | s des | dary, a | oun | The b | |
| 14. Building plan (footprint, shape): Other building plan descriptions: 15. Dimensions in feet (length x width): 636 square feet 16. Number of stories: 17. Primary external wall material(s): Wood/Plywood/Particle Board 18. Roof configuration: Other roof configurations: 19. Primary external roof material: Other roof materials: Asphalt Roof/Composition Roof Other roof materials: 20. Special features: Car Port Porch 21. General architectural description: Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. As addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (ve light, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. W shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It h wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The porther principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the for roof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | | | | | | | | | | | st: | ds exi | d boun | s and | Mete | |
| Other building plan descriptions: 15. Dimensions in feet (length x width): 636 square feet 16. Number of stories: 17. Primary external wall material(s): 8 Synthetics/Vinyl Other wall materials: Wood/Plywood/Particle Board 18. Roof configuration: Other roof configurations: 19. Primary external roof material: Other roof materials: 20. Special features: Car Port Porch 21. General architectural description: Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. As addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (veilight, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. W shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It h wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The po the principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the for roof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | | | | | | | | | ION | CRIPT | ESC | AL D | TUR | ГЕС | RCHIT | II. AF |
| 15. Dimensions in feet (length x width): 16. Number of stories: 17. Primary external wall material(s): 18. Roof configuration: Other roof configurations: 19. Primary external roof material: Other roof materials: 20. Special features: Car Port Porch 21. General architectural description: Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. A s addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (velight, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. W shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It h wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The pop the principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the frozof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | | | | | an | lar Pl | tangı | Rec | | pe): | , sha _l | tprint | an (foc | ng pl | Buildi | 14. |
| 16. Number of stories: 17. Primary external wall material(s): 18. Roof configuration: 19. Other roof configurations: 19. Primary external roof material: 19. Other roof materials: 20. Special features: 21. General architectural description: 22. Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. A s addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (velight, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. W shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It h wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The pothe principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the frozof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | | | | | | | | | | ions: | script | an des | ding pla | build | Other | |
| 17. Primary external wall material(s): Synthetics/Vinyl Wood/Plywood/Particle Board | | | | | t | e fee | squa | 636 | | width): | igth x | et (len | s in fe | nsion | Dime | 15. |
| Wood/Plywood/Particle Board 18. Roof configuration: Gabled Roof/Front Gabled Roof Other roof configurations: 19. Primary external roof material: Asphalt Roof/Composition Roof Other roof materials: 20. Special features: Car Port Porch 21. General architectural description: Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. A s addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (veilight, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. W shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It h wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The porthe principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the frozof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | | | | | | | | 1 | | | | 3: | stories | er of | Numb | 16. |
| Other roof configurations: 19. Primary external roof material: Car Port Porch 21. General architectural description: Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. A s addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (we light, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. W shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It h wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The port the principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the frozof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | Other wall materials: | Other | | Board | | | | - | | al(s): | nateri | wall m | ternal | ıry ex | Prima | 17. |
| 19. Primary external roof material: Asphalt Roof/Composition Roof Other roof materials: 20. Special features: Car Port Porch 21. General architectural description: Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. As addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (velight, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. W shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It h wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The porthe principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the front of, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | | | f | led Roo | ont G | oof/F | oled R | Gal | | | | n: | guratio | confi | Roof | 18. |
| Other roof materials: 20. Special features: Car Port Porch 21. General architectural description: Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. A s addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (ve light, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. W shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It h wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The porthe principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the frozof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | | | | | | | | | | | ns: | uratio | config | roof | Other | |
| 20. Special features: Car Port Porch 21. General architectural description: Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. A s addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (velight, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. We shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It he wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The post the principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the frozof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | | | f | tion Roc | ompo | oof/C | halt F | Asp | | ial: | nateri | roof n | ternal | ıry ex | Prima | 19. |
| Porch 21. General architectural description: Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. A s addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (ve light, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. W shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It h wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The porthe principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the free roof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | | | | | | | | | | | | als: | | | | |
| 21. General architectural description: Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. As addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (velight, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. We shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It has wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The post the principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the frozof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | | | | | | | Port | Car | | | | | atures: | al fea | Speci | 20. |
| Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of w plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. A s addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (velight, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. W shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It h wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The pothe principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the frozof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | | | | | | | ch | Por | | | | | | | | |
| plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. A saddition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (veight, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. We shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It has wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The post the principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the from the roof, and the rafter and perlin ends are exposed but capped by a fascia board. 22. Architectural style: Late 19th And Early 20th Century American Movements | | | | | | | | | | ption: | lescri | ural d | chitect | ral ar | Gene | 21. |
| Zate 19th And Early 20th Century American Movements | I siding clads the exterior walls. A shed-roofed d walls. Windows are generally 5 (vertical)-over-1-aluminum-frame storm windows. White, louvered southwest corner of the house. It has a single, round-arch decorative cape. The porch shelters oorway opens in the east end of the north g, gray asphalt shingles cover the front-gabled | Oriented to the west, this house rests on a concrete foundation. A basement stairwell bulkhead, constructed of white-paint plywood, protrudes from the south end of the rear (east) elevation. Green vinyl siding clads the exterior walls. A shed-roofe addition to the north end of the east elevation has white-painted, particleboard walls. Windows are generally 5 (vertical)-ov light, double-hung sash, with white-painted wood frames and surrounds, and aluminum-frame storm windows. White, low shutters flank most window openings. An integral porch is situated within the southwest corner of the house. It has a sing wood support at its northwest corner and white-painted brick knee wall, with round-arch decorative cape. The porch shelte the principal doorway, which opens in the south face of the corner. Another doorway opens in the east end of the north elevation. A shed-roof carport spans much of the south elevation. Interlocking, gray asphalt shingles cover the front-gable roof, and the rafter and perlin ends are exposed but capped by a fascia board. | | | | | | | | | | | | | | |
| Other architectural styles: | erican Movements | erican Move | ıry Amer | th Cent | Early | n And | te 19tl | La | | | | э: | ral style | ectu | Archit | 22. |
| Sand Artificial Crystol. | | | | | | | | | | | es: | al styl | itectur | arch | Other | |
| Building type: | | | | | | | | | | | | | pe: | ng ty | Buildi | |
| 23. Landscape or special setting features: | | | | | | | | | es: | g featui | ettin | ecial s | or spe | саре | Lands | 23. |

1712 Craig Street 5PE.5957

(Resource number)

Architectural Inventory Form

Page 3

This property is located on terrain sloping downward from northeast to southwest, with an elevation of around 4,700 feet above mean sea level. The neighborhood features large, two-story houses. Setbacks from Craig Street are generally the same on this block. This property is situated on the east side of Craig Street, between an east-west-oriented alley to the south and 1718-1720 Craig Street to the north. A planted-grass yard, mature landscaping, covers the lot. Encircling the yard is a chain-link fence. A concrete driveway connects West Street to and through the carport along the south elevation of the house.

Associated buildings, features or objects:

No associated buildings identified.

IV. ARCHITECTURAL HISTORY

Date of Construction: Estimate: Actual: 1928

Source of Information: Pueblo County Office of Tax Assessor. Property information card [internet].

Architect: unknown

Source of information:

27. Builder: unknown

Source of information:

28. Original Owner: unknown

Source of information:

29. Construction history:

> According to Pueblo County Tax Assessor records, this building was constructed in 1928. An analysis of the style and materials corroborates this date. However, this building does not appear at this location on Sanborn maps through 1952; as well, the address does not appear in city directories. This suggests that the house was most likely moved here from somewhere else. Notable alterations since then have been the installation of vinyl siding and the construction of the rear addition.

Location: moved Date of move(s): After 1952

V. HISTORICAL ASSOCIATIONS

Single Dwelling Original use(s): Intermediate use(s): Single Dwelling 32. 33. Current use(s): Single Dwelling Residence

Historical background:

Site type(s):

34.

According to Pueblo County Tax Assessor records, this building was constructed in 1928. However, this building does not appear at this location on Sanborn maps through 1952, suggesting that it may have been moved here from elsewhere.

Ray H. and Louis McKnight purchased this property prior to 1970; they sold it to Jess and Helen Martinez in 1987. In 1994, Jess Martinez shared ownership with A. Villanueva. They sold the house and lot to Gina R. Gonales Salazar and Jim C. Salazar in 2001. They remain the current owners and residents.

Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory, Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

1712 Craig Street

Architectural Inventory Form

Page 4

| VI. | SIGNIFICANCE | | | | | | | | | | |
|-----|---|--|--|--|--|--|--|--|--|--|--|
| 37 | 7. Local landmark designation: Yes No Designation authority: | | | | | | | | | | |
| | Date of designation: | | | | | | | | | | |
| 38 | 3. Applicable National Register criteria: | | | | | | | | | | |
| | A. Associated with events that have made a significant contribution to the broad pattern of our history. B. Associated with the lives of persons significant in our past. C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose components may lack individual distinction. D. Has yielded, or may be likely to yield, information important in history or prehistory. Qualifies under Criteria Considerations A through G (see manual). Does not meet any of the above National Register criteria. | | | | | | | | | | |
| | Pueblo Standards for Designation: | | | | | | | | | | |
| | 1a. History Have direct association with the historical development of the city, state, or nation; or 1b. History Be the site of a significant historic event; or 1c. History Have direct and substantial association with a person or group of persons who had influence on society. 2a. Architecture Embody distinguishing characteristics of an architectural style or type; or | | | | | | | | | | |
| | Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a significant or influential innovation; 2d. Architecture Portray the environment of a group of people or physical development of an area of the city in an era of history | | | | | | | | | | |
| | characterized by a distinctive architectural style. 3a. Geography Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or 3b. Geography Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or 3c. Geography Make a special contribution to Pueblo's distinctive character. Not Applicable Does not meet any of the above Pueblo landmark criteria. | | | | | | | | | | |
| 3 | 9. Area(s) of Significance: Architecture | | | | | | | | | | |
| 4 | 0. Period of Significance: 1928 | | | | | | | | | | |
| 4 | 1. Level of significance: National: State Local | | | | | | | | | | |

(Resource number)

Architectural Inventory Form

Page 5

Statement of significance:

This property is architecturally significant under National Register criterion C (Pueblo Local Landmark Criterion 2A) as an example of a style derived from the Late-19th and Early 20th Century American Movements. However, the levels of architectural and historical significance, combined with physical integrity, are not to the extent that this property would qualify for individual listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a City of Pueblo Landmark. Given its low level of physical integrity, this property should not be considered a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed in 1928, this house exhibits a low level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. This house appears to have been moved, compromising its integrity of location. Thus, this property does not retain sufficient physical integrity to convey its architectural and historical significance.

| VII. | NATIONAL | REGISTER ELIGIBILITY AS | SSESSMENT | | | | | | | |
|------|----------------|---|---|----------------|--------------|----------|--------|--------|---------|------|
| 44. | National Re | gister eligibility field assessment: | ☐ Individually eligi | ible | Not e | eligible | | Need | data | |
| | Local landm | nark eligibility field assessment: | ☐ Individually elig | ible | Not eligible | | | | Need | data |
| 45. | Is there Nat | ional Register district potential? | Yes 🔝 No 🗖 | | | | | | | |
| | Discuss: | Pueblo's North Side Neighborho classes. Its diversity of architect cultural climates. As well, the ne the area's dominant industry, st | tural styles and forms dire eighborhood is distinctive | ctly represent | s the ci | ty's cl | nangin | g econ | omic an | |
| | If there is N | ational Register district potential, is t | his building contributing: | Yes | ■ N | | N/A | | | |
| 46. | If the buildir | ng is in existing National Register dis | trict, is it contributing: | Yes | ■ N | | N/A | | | |

VIII. RECORDING INFORMATION

47. Photograph numbers): CD-ROM Photo Disc: North Side Photos

File Name(s): craigst1712

Negatives filed at: Special Collections

Robert Hoag Rawlings Public Library

100 East Abriendo Avenue Pueblo, CO 81004-4290

48. Report title: Pueblo North Side Neighborhood Survey

49. Date(s): **08/30/06**

50. Recorder(s): Adam Thomas

51. Organization: Historitecture, L.L.C.

52. Address: **PO Box 419**

Estes Park, CO 80517-0419


53. Phone number(s): (970) 586-1165

1712 Craig Street 5PE.5957
(Resource number)

Architectural Inventory Form

Page 6

SITE SKETCH MAP




1712 Craig Street 5PE.5957

(Resource number)

Architectural Inventory Form

Page 7

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)