COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

This survey form represents an UNOFFICIAL COPY and is provided for informational purposes only. All information, particularly determinations of eligibility for the National Register, the State Register, or as a local landmark, can and will change. Please contact the Colorado Historical Society Office of Archaeology and Historic Preservation for an official copy of this document.



I. IDENTIFICATION

.DL.	11110/111011						
1.	Resource number:	5BL.10495			Parce	I number:	158320008001
2.	Temporary resource number:						
3.	County:	Boulder					
4.	City:	Eldora					
5.	Historic building name:	Rumley Cab	in; Marron Cabin; "Bor	nita Casa" Cabir	n		
6.	Current building name:	Tasaday Cab	in				
7.	Building address:	902 Klondyke Avenue					
8.	Owner name:	Laurence Tasaday					
	Owner organization:						
	Owner address:	PO Box 1449	9				
		Pahoa, HI 9	6778				
44.	National Register eligibility field	assessment:	☐ Individually eligible	☑ Not eligible	☐ Need data	☐ Previou	usly listed
	State Register eligibility field assessment:		☐ Individually eligible	☑ Not eligible	☐ Need data	☐ Previou	usly listed
	Local landmark eligibility field assessment:		☐ Individually eligible	☑ Not eligible	☐ Need data	☐ Previou	usly listed

Architectural Inventory Form

5BL.10495 UNOFFICIAL COPY

Page 2

II. GEOGRAPHIC INFORMATION

9. P.M.: 6th Township: 1S Range: 73W

NE 1/4 NW 1/4 SE 1/4 NE 1/4 of section 20 Grid aligned on northwest corner of section.

10. UTM Reference Zone: 13

Easting: **450808** Northing: **4422180**11. USGS quad name: **Nederland** Scale: **7.5**

Year: 1972

12. Lot(s): Lots 1 through 7 inclusive; Blcok 41. Also half of an adjacent vacated alley.

Addition: Eldora Year of addition: 1898

13. Boundary description and justification: The boundary, as described above, contains but does not exceed the land historically associated with this property.

III. ARCHITECTURAL DESCRIPTION

14. Building Plan (footprint, shape): Irregular Plan

Other building plan descriptions:

15. Dimensions in feet: 646 square feet

16: Number of stories:

17: Primary external wall material(s): Wood/Vertical Siding

Other wall materials:

18: Roof configuration: Gabled Roof/Side Gabled Roof

Other roof configuration:

19: Primary external roof material: Metal Roof

Other roof materials:

20: Special features: Car Port

Chimney Fence

21: General architectural description:

This cabin is oriented to the east. Because of the snow cover, the nature of the foundation could not be determined. Unpainted, vertical board-and-batten siding clads the exterior walls. Windows vary widely, but are most often single-light fixed frame and 1-beside-1-light, sliding sash. Some have wood frames, others have aluminum frames. They have green-painted wood surrounds. The principal doorway opens in the east elevation of a front-gabled wing protruding from the north end of the east elevation. It hosts a green-painted wood slab door, with a single light. A stone and concrete stoop approaches the doorway. A side-gabled carport extends southward from the south elevation. Another doorway appears to open within this carport. Engaged to the northern half of the rear (west) elevation are a brick hearth and chimney, encased in concrete. The chimney has an arched cap. Sheets of corrugated metal cover the side-gabled main roof and all other roof surfaces. The rafter ends are exposed but capped by a fascia board.

22. Architectural style: No Style

Other architectural style:

Building type:

23. Landscape or special setting features:

This property is located in mountainous terrain sloping downward from north to south, at an elevation of around 8,600 feet above mean sea level. Houses are irregularly spaced along Eldorado Avenue, a secondary east-west thoroughfare through the village of Eldora. This cabin is located on the southwest corner of Klondyke Avenue and 9th Street and has a relatively shallow setback from both streets. The landscape is largely open, with spruces and aspens surrounding the main cabin. A wood privacy fence encloses the area between the main cabin and guest cabin 2.

24. Associated building, features or objects:

GUEST CABIN 1

A guest cabin is located south of the main cabin and southeast of guest cabin 2. Oriented to the east, the building appears to rest on a concrete slab. Unpainted, vertical board-and-batten siding clads the exterior walls. Windows very greatly in size and description. Spanning the front-gabled wing attached to the front (east) elevation are a trio of 1-

Eldora Survey

Page 3

beside-1-light, sliding-sash windows, with aluminum frames. Above them, in the gable, are fixed-frame, triangular clerestory windows. The south elevation of the wing hosts a pair of 9-light, fixed-frame windows, with green-painted wood frame. Opening low, near the center of the south elevation are a pair of 4-beside-4-light, sliding-sash windows, with green-painted wood frames. West of these windows is a single-light, floor-to-ceiling window or door; west of it is a another small window. The west and north elevations host an array of fixed-frame and sliding sash windows, with aluminum frames. The principal doorway opens in the north elevation of the attached front-gabled wing, and hosts a single-light, glass-in-wood-frame door, painted green. Corrugated sheets of metal cover the front-gabled main roof and all other roof surfaces. The rafter ends are exposed.

GUEST CABIN 2

Another guest cabin is located west of the main cabin and northwest of guest cabin 1. Oriented to the south, the building rests on a concrete slab. Unpainted, vertical board-and-batten siding clad the exterior walls. Windows are generally tall, single-light, fixed-frame and casement. The principal doorway opens near the center of the south elevation. It hosts a single-light, glass-in-wood-frame door, painted green. Sheets of corrugated metal cover the side-gabled roof, and the eaves are boxed, with wood fascia and soffit.

PRIVY

A privy is located immediately west of guest cabin 1. Oriented to the east, the building lacks a permanent foundation. Unpainted sheets of plywood clad the exterior walls. A plywood door opens in the center of the east elevation. Sheets of corrugated metal cover the shed roof.

IV. ARCHITECTURAL HISTORY

25.	Date of	Construction:	1924	X Actual	□ Estimate

Source of information: Boulder County Assessor Records. Current records available on-line.

26. Architect: Unknown

Source of information:

27. Builder: Unknown

Source of information:

28. Original Owner: William J. Rumley

Source of information: Warranty Deed 90222722. From the Earl Wilcox and the Henry Wilcox Estate, 15 September 1925.

Boulder County Clerk and Recorder, book 533, p. 250.

29. Construction history:

According to Boulder County Assessor records, this cabin was constructed in 1924. An analysis of the style, materials, and historical records corroborates this date. This cabin appears to have consisted originally of a small, L-shaped plan building, with the inside corner facing southeast. Additions were then made extending the cabin southward. The construction of the large car port and the installation of the hearth and chimney occurred around 1968, based on assessor records. The windows were replaced in the 1970s or '80s. Guest cabin 1 was originally a single-car garage constructed in 1924. Its modification into a cabin, occurring in the 1980s, resulted in the construction of the front-gabled wing and the installation of more windows. Guest cabin 2 was constructed in 1981.

30. Location: **Original Location** Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Domestic/Cabin
32. Intermediate use(s): Domestic/Cabin
33. Current use(s): Domestic/Cabin

34. Site type(s): Rental Property; Vacation Residence

35. Historical background:

The original owner of this cabin, constructed in 1925, was William J. Rumley. He was born in Virginia around 1868. His wife, the former Anna Klein, was born around 1876 in Kansas. They were married around 1897. By 1910, William Rumley was the manager of a lumberyard in Mount Pleasant, Kansas. He moved to Frederick, Colorado, where he also worked at a lumberyard. He sold this property in 1929, prior to moving to Abilene, Texas.

Eldora Survey

Architectural Inventory Form

5BL.10495 UNOFFICIAL COPY

Page 4

Purchasing the property from Rumley was Nebraska physician Dr. James G. Marron, who christened the cabin "Bonita Casa." He was born in New York state around 1865. His wife, Frances Mary Marron, was born in England around 1876. She immigrated to the United States in 1909. They had two children: Winifred Marron and Alfred K. Marron. Dr. Marron settled in Butler County, Nebraska, around 1910, opening a practice in Brainard, Oak Creek Township. In 1938, Dr. Marron transferred this property to his wife, Frances, who, in 1949, transferred the property to their children and their respective spouses: Alfred K. and F. June Marron, and John F. and Winifred Marron Zimmer. By 1954, Winifred Zimmer was the sole owner.

That year, Zimmer sold the property to Hampton F. Shirer, who owned only briefly, transferring the buildings and lots less than year later to Sarah E. MacNeil; she later married George W. Figgs. Both were residents of Kansas. By 1972, Sarah Figgs became the sole owner. She transferred the property to John R. and Michael MacNeil in 1996. In 1998, Michael MacNeil and Laurence Tasaday owned the property. Tasaday became the sole owner in 1999. He is a resident of Pahoa, Hawaii, and appears to operate the property as at least one rental unit.

36. Sources of information:

Boulder County Assessor Records.

Applicable Boulder County landmark criteria:

Boulder County Assessor Cards. Carnegie Branch Library for Local History, Boulder Public Library System. Record dates vary from 1949 to 1975.

"Eldora Sweethearts: Al and June Marron." In the Eldora Civic Association Newsletter, 1995-1999.

- Deeds 90222722, 90265833, 90349181, 904848037, 90507909, 90544843, 90558160, 90945793, 40287, 1632187, 1836929, 1836931, and 1932815. Boulder County Clerk and Recorder.
- U.S. Census of 1910. Mt. Pleasant, Atchison County, Kansas. Roll: T624_432; Page: 1A; Enumeration District: 17; Image: 94.
- U.S. Census of 1920. Frederick, Weld County, Colorado. Roll: T625_172; Page: 18A; Enumeration District: 228; Image: 263.
- U.S. Census of 1930. Abilene, Taylor County, Texas. Roll: 2399; Page: 13B; Enumeration District: 15; Image: 1042.0.
- U.S. Census of 1920. Oak Creek, Butler County, Nebraska. Roll: T625_982; Page: 2B; Enumeration District: 9; Image: 124
- U.S. Census of 1930. Brainard, Butler County, Nebraska. Roll: 1267; Page: 3A; Enumeration District: 9; Image: 678.0.

VI. SIGNIFICANCE 37. Local landmark designation: ☐ Yes 🛛 No Designation authority: Date of designation: 38. Applicable National Register criteria: A. Associated with events that have made a significant contribution to the broad patterns of our history. ☐ B. Associated with the lives of persons significant in our past. ☐ C. Embodies the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction. D. Has yielded, or may be likely to yield, information important in prehistory or history. Qualifies under Criteria Considerations A through G (see manual). Does not meet any of the above National Register criteria. Applicable Colorado State Register criteria: A. Associated with events that have made a significant contribution to history. ☐ B. Connected with persons significant in history. ☐ C. Has distinctive characteristics of a type, period, method of construction or artisan. ☐ D. Is of geographic importance. ☐ E. Contains the possibility of important discoveries related to prehistory or history. Does not meet any of the above Colorado State Register criteria.

Architectural Inventory Form Page 5

5BL.10495 **UNOFFICIAL COPY**

		■ 1. the character, interest, or value of the proposed landmark as part of the development, heritage, or cultural characteristics of				
		the county;				
		2. the proposed landmark as a location of a significant local, county, state, or national event;				
		☐ 3. the identification of the proposed landmark with a person or persons significantly contributing to the local, county, state, or national history;				
		☐ 4. the proposed landmark as an embodiment of the distinguishing characteristics of an architectural style valuable for the study				
		of a period, type, method of construction, or the use of indigenous materials;				
		☐ 5. the proposed landmark as identification of the work of an architect, landscape architect, or master builder whose work has				
		influenced development in the county, state, or nation;				
		☐ 6. the proposed landmark's archaeological significance;				
		☐ 7. the proposed landmark as an example of either architectural or structural innovation; and				
		a. the relationship of the proposed landmark to other distinctive structures, districts, or sites which would also be determined to				
		be of historic significance.				
		☐ Does not meet any of the above Boulder County landmark criteria.				
	39.	Areas of significance: Social History				
	40.	Period(s) of Significance: 1924-1958				
	41.	Level of Significance: ☐ National ☐ State ☒ Local				
	42.	Statement of Significance:				
		This property is significant for its association with the development of Eldora as a summer tourist retreat, particularly				
		for midwestern professionals such as Dr. James Marron. However, because of the principal building's low level of				
		physical integrity, this property should not be considered individually eligible for listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a Boulder County Landmark.				
	12					
	43.	Assessment of historic physical integrity related to significance: Constructed in 1924, this cabin exhibits a low level of physical integrity relative to the seven aspects of integrity as				
		defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials,				
		workmanship, feeling, and association. Additions have significantly altered the original form and the replacement of				
		windows removed a key character-defining feature. This building does not retain sufficient physical integrity to convey				
		its architectural and historical significance.				
VII.	NA	TIONAL REGISTER ELIGIBILITY ASSESSMENT				
	44.	National Register eligibility field assessment:				
		State Register eligibility field assessment:				
		Local landmark eligibility field assessment:				
	45.	Is there National Register district potential:				
		Discuss: This survey inventoried properties surrounding but not included within the Eldora National Register District				
		(5BL.758). Moreover, this inventory was conducted as an intensive-level selective survey and therefore lacks the				
		continuity of resource data necessary to determine any expansion of the existing district boundaries or to recommend the creation of a new district.				
		If there is National Register district potential, is this building contributing:				
		a and to to treatenant register district potential, is this building contributing.				
		Eldora Survey				

Architectural Inventory Form

5BL. 10495 UNOFFICIAL COPY

Page 6

46. If the building is in existing National Register district, is it contributing:	☐ Yes ☐ No N/A

VIII. RECORDING INFORMATION

47. Digital photograph file name(s): klondykeave0902 - 1 to - 11

Digital photographs filed at: Boulder County Parks and Open Space

5201 St. Vrain Rd Longmont, CO 80503

48. Report title: Eldora Historical and Architectural Survey, 2007-08

49. Date(s): **2/27/2008**

50: Recorder(s): Adam Thomas, Jeffrey DeHerrera, and Sierra Standish

51: Organization: Historitecture, LLC

52: Address: **PO Box 419**

Estes Park, CO 80517-0419

53: Phone number(s): (970) 586-1165


Architectural Inventory Form Page 7

SKETCH MAP



Page 8

LOCATION MAP



Source: U.S. Geological Survey 7.5' Nederland - 1972