### COLORADO CULTURAL RESOURCE SURVEY

# **Architectural Inventory Form**

Page 1

This survey form represents an UNOFFICIAL COPY and is provided for informational purposes only. All information, particularly determinations of eligibility for the National Register, the State Register, or as a local landmark, can and will change. Please contact the Colorado Historical Society Office of Archaeology and Historic Preservation for an official copy of this document.



### I. IDENTIFICATION

Resource number:	5WL.5638	Parcel number:	080716307003
Temporary resource number:	Not Applicable		
County:	Weld		
City:	Windsor		
Historic building name:	Bartz Garage; Service Garage; Charles A. Flinn Agency; St	ar Lite Café	
Current building name:	Duke of Windsor Sports Bar & Grill; Moonlight Grille		
Building address:	522-526 Main Street		
Owner name:	Windsor Enterprises, Inc		
Owner organization:			
Owner address:	526 Main St		
	Windsor, CO 80550		
	County: City: Historic building name: Current building name: Building address: Owner name: Owner organization:	Temporary resource number:  County:  Weld  City:  Windsor  Historic building name:  Bartz Garage; Service Garage; Charles A. Flinn Agency; St  Current building name:  Duke of Windsor Sports Bar & Grill; Moonlight Grille  Building address:  522-526 Main Street  Owner name:  Windsor Enterprises, Inc  Owner organization:  Owner address:  526 Main St	Temporary resource number:  County:  Weld  City:  Windsor  Historic building name:  Bartz Garage; Service Garage; Charles A. Flinn Agency; Star Lite Café  Current building name:  Duke of Windsor Sports Bar & Grill; Moonlight Grille  Building address:  522-526 Main Street  Owner name:  Windsor Enterprises, Inc  Owner organization:  Owner address:  526 Main St

44. National Register eligibility field assessment:	☐ Individually eligible	Not eligible	■ Need data	☐ Previously listed
State Register eligibility field assessment:	☐ Individually eligible	■ Not eligible	■ Need data	☐ Previously listed
Local landmark eligibility field assessment:	☐ Individually eligible	Not eligible	☐ Need data	☐ Previously listed

5WL.5638
UNOFFICIAL COPY

Page 2

#### II. GEOGRAPHIC INFORMATION

9. P.M.: **6th** Township: **6N** Range: **67W** 

SE 1/4 SW 1/4 SW 1/4 SW 1/4 of section 16

10. UTM Reference Zone: 13

Easting: **508015** Northing: **4481065**11. USGS quad name: **Windsor** Scale: **7.5** 

Year: 1969

12. Lot(s): Lots 23, 25, and 27; Block 6

Addition: Windsor Original Town Year of addition: 1882

13. Boundary description and justification: The boundary, as described above, contains but does not exceed the land historically associated with this property.

■ Metes and bounds exist

### **III. ARCHITECTURAL DESCRIPTION**

14. Building Plan (footprint, shape): Rectangular Plan

Other building plan descriptions:

15. Dimensions in feet: 13,090 square deet

16: Number of stories: 1

17: Primary external wall material(s): Brick
Stucce

Other wall materials:

18: Roof configuration: Flat Roof

Other roof configuration:

19: Primary external roof material: Asphalt Roof/Composition Roof

Other roof materials:

20: Special features: Chimney

**Roof Treatment/Decorative Cornice** 

#### 21: General architectural description:

Oriented to the south, this building appears to rest on a concrete foundation. The walls consist of red, pressed bricks, set in a 7-over-1 common bond. Cladding the front (south) façade is a tan, pressed-brick veneer. All window openings in the façade have brick sills. Unpainted stucco covers portions of the rear (north) elevation. Large window and door openings across the façade have all been enclosed with tan-painted sheets of plywood. Windows opening within the plywood are narrow, single-light fixed-frame. Plate-glass doors opening in the center of the eastern third, between the eastern and center thirds, near the center of the western third, and within a recess at the western end of the building. Three, small, single-light clerestory windows punctuate the façade. Above them is a shallowly protruding, corbelled cornice. Windows in the side elevations have concrete sills and have all been boarded shut. Three doorways open in the rear elevation. One opens in the center of the eastern third of the building. The other two open in either face of the northeast-facing corner of the central third of the building. The east-facing door hosts a gray-painted wood slab door. Just south of it is another doorway that has been boarded shut. The north-facing door hosts a white-painted, three-panel metal door. A large garage doorway in the north elevation has been enclosed with concrete blocks. Gray sheets of asphalt cover the nearly flat roof, and the parapets above the side elevation are stepped. A large, red-brick chimney protrudes from near the center of the eastern third of the building.

22. Architectural style: Late 19th And Early 20th Century American Movements/Commercial Style

Other architectural style:

Building type:

23. Landscape or special setting features:

This commercial building is located on Main Street, the principal east-west thoroughfare through downtown Windsor. It is situated on the north side of the street, between 520 Main Street to the east and 530 Main Street to the west. Separating the building's front (south) facade from the street is a concrete sidewalk. Packed earth and concrete cover the area behind (north of) the building.

24. Associated building, features or objects:

There are no other buildings associated with this property.

#### IV. ARCHITECTURAL HISTORY

5WL.5638
UNOFFICIAL COPY

Page 3

25. Date of Construction: 1910 (eastern third); ca. 1920 Actual Estimate

Source of information: Ray, Roy. Highlights in the History of Windsor, Colorado: Golden Jubilee Edition. Windsor: Press

of The Poudre Valley, 1940, p. 87.

Sanborn Fire Insurance Maps (for Windsor, Colorado). New York: Sanborn Map and Publishing Co.,

December 1900 and January 1906.

26. Architect: Unknown

Source of information:

27. Builder: Unknown

Source of information:

28. Original Owner: Phillip A. Bartz

Source of information: Ray, Roy. Highlights in the History of Windsor, Colorado: Golden Jubilee Edition. Windsor: Press

of The Poudre Valley, 1940, p. 87.

29. Construction history:

According to Weld County Tax Assessor records, this building was constructed in 1920. However, Roy Ray's *History of Windsor* and Sanborn maps reveal that the building was actually constructed in two sections. The eastern third was completed in 1910. The western two-thirds date to around 1920. Alterations since that time include the enclosure of all windows and nearly all door openings. These modifications appear to date to after 1980.

30. Location: Original Location Date of move(s):

#### V. HISTORICAL ASSOCIATIONS

31. Original use(s): Commerce and Trade/Business

32. Intermediate use(s): Commerce and Trade/Specialty Store

 ${\bf Commerce\ and\ Trade/Professional}$ 

Commerce and Trade/Restaurant

33. Current use(s): Commerce and Trade/Bar

Commerce and Trade/Restaurant

- 34. Site type(s):
- 35. Historical background:

What is now the eastern third of this building was originally constructed in 1910 as an automobile repair garage for mechanic Phillip A. Bartz. He was born around 1872 in Missouri. His wife, Rose L. Bartz, was also born in Missouri, around 1874. They had two children: Raymond and Gladys. Around 1920 Bartz purchased the adjacent two lots to the west and demolished the house that stood on them to triple the size of his garage. He turned the original, eastern third of the building into an automobile showroom and battery service department. The rest of the building was used as a repair garage.

In 1933 Charles "Charlie" Flinn purchased the building and operated it as Service Garage. Two years later he opened a Chrysler-Plymouth dealership in the building. In 1942 the business became a Kaiser-Frazer dealership. Flinn also operated a filling station and a milk route. Then in 1953, the entrepreneur changed businesses again when he opened an insurance brokerage and real estate firm, the Charles A. Flinn Agency, in the old garage portion (western two-thirds) of the building. Occupying the former showroom (eastern third, then addressed as 522 Main Street) was the Star Lite Café, operated by Flinn's wife, Inez. Between 1960 and 1964, Inez Flinn wanted to expand her restaurant with a bar and lounge. Thus, Charlie Flinn moved his agency to 408 Main Street (5WL.5608), leaving the entire building for Inez's Star Lite Lounge, which she continued to operate until 1968. Purchasing the restaurant and lounge that year were Robert and Hazel Johnson, who renamed it the Duke of Windsor. Calvin and Marie Ruedemann acquired the bar and restaurant in 1977, operating it as the Stock Exchange. Around 1980, Manuel and John Cruz, with their wives, purchased the business. They operated the restaurant portion of the building as San Cruz's Restaurant, specializing in Mexican food, while they restored the name Duke of Windsor for the bar.

Windsor Enterprises, Inc., the current owner, acquired this property from Bill and Mary Farmer in 1982. At the time of this survey, it hosted the Duke of Windsor Sports Bar & Grill and well as the Moonlight Grille.

36. Sources of information:

5WL.5638 **UNOFFICIAL COPY** 

Page 4

Weld County Assessor Property Profile.

Deed 1882343. Weld County Clerk and Recorder.

Sanborn Fire Insurance Maps (for Windsor, Colorado). New York: Sanborn Map and Publishing Co., December 1900, January 1906, May 1911, and November 1921.

Mountain States Telephone and Telegraph Company. Telephone Directory [for Weld County]. Consulted 1927-28, 1929 -30, Summer 1936, November 1941, November 1945, June 1950, Winter 1954-55, Summer 1960, and 1964.

Ray, Roy. Highlights in the History of Windsor, Colorado: Golden Jubilee Edition. Windsor: Press of The Poudre Valley, 1940, p. 87.

Lindblad, Mary Alice. A Walk Through Windsor: 1940-1980. Windsor, Colo.: by the author, 1980, pp. 139, 143.

U.S. Census of 1920. Windsor, Weld County, Colorado. Roll: T625\_172; Page: 4A; Enumeration District: 231; Image: 337.

### VI.

SIG	NIFICANCE					
37.	Local landmark designation: Designation authority: Date of designation:	☐ Yes	⊠ No			
38.	Applicable National Register criter	ria:				
	<ul> <li>A. Associated with events that have made a significant contribution to the broad patterns of our history.</li> <li>B. Associated with the lives of persons significant in our past.</li> <li>C. Embodies the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction.</li> <li>D. Has yielded, or may be likely to yield, information important in prehistory or history.</li> <li>Qualifies under Criteria Considerations A through G (see manual).</li> <li>Does not meet any of the above National Register criteria.</li> </ul>					
	<ul><li>□ B. Connected with persons sig</li><li>☑ C. Has distinctive characteristi</li><li>□ D. Is of geographic importance</li></ul>	have manificant incest of a type.  mportant	de a significant contribution to history.  n history.  pe, period, method of construction or artisan.  discoveries related to prehistory or history.			
	<ul> <li>□ 1. Architectural: b) Example of or locally.</li> <li>□ 1. Architectural: c) Demonstrat</li> <li>□ 1. Architectural: d) Represents</li> <li>□ 1. Architectural: e) Style is par</li> <li>□ 1. Architectural: f) Represents</li> <li>□ 1. Architectural: g) Pattern or g</li> <li>□ 1. Architectural: h) Significant</li> <li>□ 2. Social: a) Site of historic ever</li> </ul>	specific the work es super an innov ticularly a a built en grouping historic r	elements of an architectural style or period.  c of an architect or builder who is recognized for expertise nationally, statewide, regionally ior craftsmanship or high artistic value.  vation in construction, materials or design. associated with the Windsor/Northern Colorado area.  evironment of a group of people in an era of history.  of elements representing at least one (1) of the above criteria.  emodel.  ad an effect upon society.			
	<ul><li>2. Social: c) An association wit</li><li>3. Geographic/Environmental:</li></ul>	h a notak a) Enhan	al, economic or social heritage of the community. Die person or the work of a notable person. Dies the sense of identity of the community. Diablished and familiar natural setting or visual feature of the community.			

5WL.5638
UNOFFICIAL COPY


Page 5

	Physical Integrity 1. Shows c		est or value as part of the	developm	ient, hei	ritage or	cultur	al characteristics of th	.e
	community, region, state or i		footuuroo mootoriolo omd/s		_				
	<ul><li>☐ Physical Integrity 2. Retains o</li><li>☐ Physical Integrity 3. Original</li></ul>					d			
	☐ Physical Integrity 4. Has been								
	Does not meet any of the abo	•			Journen	tation.			
	Does not meet any of the abo	ove rown or w	masor fandmark criteria.						
39.	Areas of significance: <b>Comme</b>	rce							
	Archite	cture							
40.	Period(s) of Significance: Con	nmerce, 1910	-1958; Architecture, 1	<b>910, ca.</b> 1	1920				
41.	Level of Significance:	lational 🗌 St	ate 🛛 Local 🔲 Not Ap	plicable					
42.	Statement of Significance:								
	This property is significant for its association with the commercial development of downtown Windsor, particularly as automobile-related shops pushed Main Street westward. It was also a longtime restaurant and bar. The building is also architecturally significant as an example of a late nineteenth and early twentieth century American Commercial Style storefront. However, the levels of architectural and historical significance, combined with physical integrity, are not to the extent that this property would qualify for individual listing in the National Register of Historic Places, the								
40	Colorado State Register of Hi	-		andmark.					
43.	Assessment of historic physical in Constructed in 1910 and trip		-	ercial bui	lding e	vhihite :	9 mor	lerately low level of	
	physical integrity relative to Historical Society: location, s retains much of its original 1 and doorways removed impor to conveys its historical and	the seven asp setting, design 920 form and tant characte	pects of integrity as de n, materials, workmans l exterior wall cladding er-defining features. Th	fined by t ship, feeli materials	he Nating, and	ional Pa 1 associ enclosur	rk Se ation e of t	rvice and the Colora . While the building he façade's show wi	ado ndows
II. NA	TIONAL REGISTER ELIGIBI	ILITY ASSES	SSMENT						
44.	National Register eligibility field	assessment:	☐ Individually eligible	<b>⊠</b> Not eli	gible	☐ Need	data	☐ Previously listed	
	State Register eligibility field ass	sessment:	☐ Individually eligible	Not eli	gible	☐ Need	data	☐ Previously listed	
	Local landmark eligibility field as	ssessment:	☐ Individually eligible	Not eli	gible	☐ Need	data	☐ Previously listed	
45.	Is there National Register district	t potential:	☐ Yes						
	Discuss: Windsor's downtown possessing a significant concedevelopment of the communi association because more that German Old-World style.	entration of b ity. However,	ouildings united by the the district lacks arch	ir historic	cal asso integri	ciation ty and,	s, par there	ticularly the comme fore, architectural	
	If there is National Register distr	ict potential, is	this building contributing	g:	☐ Yes	☐ No	<b>⊠</b> N	/A	
46.	If the building is in existing Nation	onal Register d	istrict, is it contributing:		☐ Yes	□No	⊠ N/	/A	
III. RE	CORDING INFORMATION								
47.	Digital photograph file name(s):	mainst522-5	526 - 1 to mainst522-5	26 - 5					
	Digital photographs filed at:	Town of Win 301 Walnut S Windsor, CO	St						
48.	Report title:	Downtown W	indsor Survey Report						
49.	, ,	4/15/2008							
	Recorder(s):		as, Jeffrey DeHerrera,	and Rach	el Kline	е			
	Organization:	Historitectus	re, LLC						
52:	Address:	PO Box 419 Estes Park. 0	CO 80517-0419						
53:	Phone number(s):	(970) 586-11							

### **SKETCH MAP**



### **LOCATION MAP**



Source: U.S. Geological Survey 7.5' Windsor - 1969