
COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

(OAHP use on	ly)
Date	Initials
Determined	Eligible-National Register
Determined	Not Eligible - National Register
Determined	Eligible - State Register
Determined	Not Eligible - State Register
Need Data	
Contributing	to eligible National Register District
	e e caracte in the second



I. IDENTIFICATION

Resource number: 5PE.5601 Temporary resource number: 023

3. County: Pueblo 4. City: **Pueblo**

Historic building name: Glenn, Edmund C., House Current building name: Sutherland, Kyle A., House

7. 409 W 12th Street Building address: Kyle A. Sutherland Owner name:

Owner organization:

Owner address: 409 W 12th St

Local landmark eligibility field assessment:

Pueblo, CO 81003

National Register eligibility field assessment: ☐ Individually eligible

Individually eligible

Not eligible

Parcel number(s):

525418012

■ Need data

Not eligible

■ Need data

(Resource number)

Architectural Inventory Form

Page 2

II. G	EOGF	RAP	HIC IN	NFOF	RMA	TION	l												
9.	P.M.:	:	6th			Tow	nship:		208			R	ange:	65V	v				
		NE	1/4	of	SE	1/4	of	NW	1/4	of	SE	1/4	of S	ection	25				
10.	UTM	refer	ence zo	one:		13													
	Easti	Easting: 533964										Northi	ng:		4236540				
11.	USGS quad name: Northeast								•			Scale	:		7.5				
	Year: 1961 (I						Photo	revis	ed 197	0 and	t								
12.	Lot(s	s):				Lot 14	; Bloc	k 26											
	Addit	tion:				County Addition						Year o	of additi	ion:	1869				
13.	Boun	ndary	descrip	tion a	nd ju	stificati	ion:												
	The	boun	dary, a	s des	cribe	ed abo	ve, co	ntair	s but	does	not e	ceed th	e land	histori	cally associated with this property.				
	Mete	es an	d bound	ds exi	st:														
III. A	RCHI	TEC	TURA	AL D	ESC	RIPT	ION												
14.	Build	Building plan (footprint, shape):						Re	Rectangular Plan										
	Othe	r buil	ding pla	an des	cripti	ions:													
15.	Dimensions in feet (length x width):					72	4 squa	re fee	et										
16.	Number of stories:					1 1	/2												
17.	Primary external wall material(s):					St	ıcco					Other wall materials:							
18.	Roof configuration:							Gabled Roof/Front Gabled Roof											
	Other roof configurations:																		
19.	Primary external roof material:								Asphalt Roof/Composition Roof										
	Othe	r roof	materi	als:															
20.	Spec	Special features:						Chimney											
								Porch											
								Wi	ndow/	Segm	nental	Arch							
21.	Gene	eral a	rchitect	ural d	escri	ption:													
	walls They hung keys	s. Wing operations operated with the second	ndows n betwo h wind s. A sin	are 4 een p ows, igle-s	-over rotru with tory,	r-4-ligh iding, s white, canted	nt, dou stucce vinyl d bay	uble-l o-cov fram protr	nung s ered s es. The udes f	ash, v ills ar e pair rom t	with g nd seg ed wi the no	reen-pa gmental ndows i rth end	inted warches arches n the fr	ood fra s. The r ont- (s east ele	n. Tan-tinted stucco also clads the exterior ames and aluminum-frame storm windows. ear (north) elevation has 1-over-1-light, double outh-) facing gable have protruding evation. It features elaborate, scrolled brackets cont (south) elevation. It has a concrete floor.				

They open between protruding, stucco-covered sills and segmental arches. The rear (north) elevation has 1-over-1-light, double-hung sash windows, with white, vinyl frames. The paired windows in the front- (south-) facing gable have protruding keystones. A single-story, canted bay protrudes from the north end of the east elevation. It features elaborate, scrolled brackets beneath its eaves. A small, shed-roofed porch is attached to the east end of the front (south) elevation. It has a concrete floor and green-painted, turned porch supports. The porch provides access to the principal (south) doorway, which hosts a 4-panel, white, metal door. The edges of the doorway are rounded. A white, metal slab door also opens on the west end of the rear (north) elevation. Attached to the eastern two-thirds of this same elevation is a deck constructed of pressure-treated lumber. A shed-roofed structure, consisting of wrought-iron supports and sheets of green, translucent fiberglass, covers a concrete patio on the south end of the east elevation. Gray, interlocking asphalt shingles cover the front-gabled roof, and the eaves are boxed with green-painted wood fascia and soffit. Stucco-covered chimneys protrude from the roof ridge, at the center and at the north end of the house.

22. Architectural style: Other Style

(Resource number)

Architectural Inventory Form

Page 3

Other architectural styles: Front-Gabled, Masonry Box

Building type:

23. Landscape or special setting features:

This property is located on terrain sloping downward from north to south, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest, one- and two-story houses. A grass strip separates the sidewalk from the street. This property is located on the north side of West 12th Street, an east-west-oriented thoroughfare. It is situated between 405 West 12th Street, to the east, and 411-415 West 12th Street, to the west. A packed-earth yard surrounds the house. A chain-link fence delimits portions of the property boundary.

Associated buildings, features or objects: No associated buildings identified.

IV. ARCHITECTURAL HISTORY

Date of Construction: Estimate: 1885 Actual:

Source of Information: Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and

Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

26. Architect: n/a

Source of information:

27. Builder: unknown

Source of information:

28. Original Owner: Edmund C. Glenn

Source of information: Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk &

Co, consulted 1886 through 2003.

29. Construction history:

According to Pueblo County tax records and other sources, this house was constructed in 1900. However, city directories and Sanborn insurance maps reveal that this house existed by 1885. An analysis of the form, style, and materials corroborates a circa 1885 date of construction. The most notable alteration has been the application of stucco over the original brick, which appears to have occurred within that last 20 years. Remarkably, no apparent additions have been made to this house since its construction.

30. Location: **original** Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Single Dwelling
32. Intermediate use(s): Single Dwelling
33. Current use(s): Single Dwelling
34. Site type(s): Residence

35. Historical background:

This house appears to have been constructed in 1885. Its first owner and resident was most likely attorney Edmund C. Glenn and his family. Glenn was born in December 1856, in lowa. He lived here with his unmarried sisters Lucretia M., a clerk at the Wilson & Barnard Dry Goods Company, and Hanna, a teacher at the nearby Centennial School. Edmund Glenn also resided here with a Mrs. S.A. Glenn, who appears to have been his widowed mother.

Census records and city directories indicate that in 1900, three families occupied this property. The owner was Robert Corkish, Jr., a salesman for J.E. Tyler & Company. He lived here with his wife, Hattie. Robert was born in December 1868 and Hattie in July 1879. Boarding with them was James E. Downey, who was involved in mining. He lived here with three daughters, Rebecca, Mary, and Martha, and a son, Edgar J. The other family consisted of Lafayette F. Cornwell, proprietor of the Cornwell Jewelry Company, and his wife Hattie S. (not to be confused with the property owner's wife of the same name). A few years later, the Corkish family moved to the home of Robert's father, two houses east, at 401 West 12th Street.

(Resource number)

Architectural Inventory Form

Page 4

By 1909, the owner was William C. Holser, who resided here with his wife, Maria. William was born in Pennsylvania in 1865. Maria came from Kansas, where she was born in 1872. The Holsers resided here with Hannah Page, Maria's mother, and Victor Chapman, a boarder. William Holser was a printer for the Franklin Press, then located at 518 North Santa Fe Avenue. The Holsers remained here through 1920.

In 1925, the owner and resident was William G. Hacker, who remained here for the next 30 years. With his wife, Helen Wallace Hacker, William had one son, Sidney G. Hacker. William and Helen Hacker resided at this address until their deaths, only a month apart, in 1955.

In 1960 the resident was Hillis Parmelee. In 1970, Patricia J. and William Jones purchased the property. Patricia sold it to Paul and Carrie Mitchell in 1999. Later that year, Kyle A. Sutherland, the current owner and resident, purchased the property.

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

"Hacker (William G.)" [obituary]. Pueblo Chieftain, 12 May 1955, p. 11.

U.S. Census of 1910. Precinct 3, Pueblo, Pueblo County, Colorado. Series T624, roll 124, p. 122.

U.S. Census of 1900. Precinct 1, Pueblo, Pueblo County, Colorado. Series T623, roll 128, p. 20.

5PE.5601

Architectural Inventory Form

Page 5

VI.	SIGNIFIC	CANCE											
37	. Local I	landmark designation: Yes 🔲 No 💽											
	Desigr	Designation authority:											
	Date o	of designation:											
38	. Applica	Applicable National Register criteria:											
		A. Associated with events that have made a significant contribution to the broad pattern of our history.B. Associated with the lives of persons significant in our past.											
		C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose components may lack individual distinction.											
		Has yielded, or may be likely to yield, information important in history or prehistory.											
	Qualifies under Criteria Considerations A through G (see manual).Does not meet any of the above National Register criteria.												
		Bood not most any of the above National Register Unional											
	Pueb	lo Standards for Designation:											
		1a. History Have direct association with the historical development of the city, state, or nation; or											
		1b. History											
		Be the site of a significant historic event; or											
		1c. History											
		Have direct and substantial association with a person or group of persons who had influence on society.											
	_	2a. Architecture											
		Embody distinguishing characteristics of an architectural style or type; or											
		2b. Architecture Be a significant example of the work of a recognized architect or master builder, or											
		2c. Architecture											
		Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a significant or influential innovation;											
	_	2d. Architecture											
		Portray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style.											
		3a. Geography											
		Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or											
	0	3b. Geography Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or											
		3c. Geography											
		Make a special contribution to Pueblo's distinctive character.											
	_	Not Applicable											
		Does not meet any of the above Pueblo landmark criteria.											
39	9. Area(s)	of Significance: Architecture											
40). Period o	of Significance: ca. 1885											
41	I. Level of	significance: National:											

(Resource number)

Architectural Inventory Form

Page 6

42. Statement of significance:

This property is historically significant under Pueblo Local Landmark criterion 1A for its association with the initial development of Pueblo's North Side Neighborhood. This house was one earliest dwellings constructed in this neighborhood. As well, the house is architecturally significant under National Register criterion C (Pueblo Local Landmark criterion 2A) as an intact example of a front-gabled, masonry form once common to the area and among the earliest domiciles constructed in this neighborhood. However, the levels of architectural and historical significance, combined with physical integrity, are not to the extent that this property would qualify for individual listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a City of Pueblo Landmark. It is, nonetheless, a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed around 1885, the principal building on this property exhibits a moderately low level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. The most notable alteration has been the application of stucco over the original masonry walls, which conceals a character-defining feature. However, there have been no substantial additions made to this house.

'II. I	NATIONAL	REGISTER ELIGIBILITY AS	SSESSI	ΛEN ⁻	Т											
44.	National Re	gister eligibility field assessment:		Indi	vidually	eligible	(Need data							
	Local landm	nark eligibility field assessment:		Ind	ividually	eligible		gible		Need data						
45.	Is there Nat	ional Register district potential?	Yes	Yes No												
	Discuss:	Pueblo's North Side Neighborho classes. Its diversity of architect cultural climates. As well, the ne the area's dominant industry, st	ural style	s and	l forms disting	directly re	epresent	ts the	city	's ch	angin	g eco	non	nic an		f
	If there is N	ational Register district potential, is t	his buildin	ng con	tributin	g:	Yes		No		N/A					
46.	If the buildir	ng is in existing National Register dis	trict, is it o	contrib	outing:		Yes		No		N/A	4				

VIII. RECORDING INFORMATION

47. Photograph numbers): CD-ROM Photo Disc: North Side Photos

File Name(s): 12thstw409

Negatives filed at: Special Collections

Robert Hoag Rawlings Public Library

100 East Abriendo Avenue Pueblo, CO 81004-4290

48. Report title: Pueblo North Side Neighborhood Survey

49. Date(s): **06/08/05**

50. Recorder(s): Adam Thomas

51. Organization: Historitecture, L.L.C.

52. Address: **PO Box 419**


Estes Park, CO 80517-0419

53. Phone number(s): (970) 586-1165

409 W 12th Street 5PE.5601
(Resource number)

Architectural Inventory Form

Page 7




(Resource number)

Architectural Inventory Form

Page 8

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)