### COLORADO CULTURAL RESOURCE SURVEY

# **Architectural Inventory Form**

Page 1

| Official Elig | OAHP14<br>Rev. 9/98                         |     |
|---------------|---|-----|
| Date          | Initials                                    |     |
| Determine     | ed Eligible-National Register               |     |
| Determine     | ed Not Eligible - National Register         |     |
| Determine     | ed Eligible - State Register                |     |
| Determine     | ed Not Eligible - State Register            |     |
| Need Dat      | a   |     |
| Contributi    | ing to eligible National Register Distric   | t   |
| Managara      | Section to elimina National Designation Di- | 4!4 |

Parcel number(s):

525311008



#### I. IDENTIFICATION

Resource number: 5PE.5632

Temporary resource number: 3. County: **Pueblo** 

4. City: Pueblo

Historic building name: 727 West Twelfth Street Current building name: 727 West Twelfth Street 727 W 12th Street Building address:

**Housing Authority of Pueblo** Owner name:

Owner organization:

Owner address: 1414 N Santa Fe Ave

**Pueblo, CO 81003** 

National Register eligibility field assessment: ☐ Individually eligible Not eligible ■ Need data Local landmark eligibility field assessment: Individually eligible Not eligible ■ Need data

(Resource number)

# **Architectural Inventory Form**

Page 2

| II.  | GE  | OGR   | RAPI                                      | HIC IN  | IFOR  | MA   | TION                                    |  |   |  |  |   |  |  |   |  |  |
|------|-----|---|---|---|---|--|---|--|---|--|--|---|--|--|---|--|--|
|      | 9.  | P.M.:   | •   | 6th   |   |  | Towr                                    | nship:   | 2   | 20S  |  |   | ı  | Range:   | 65V   | V  |  |
|      |     |   | NE  | 1/4   | of  | SE   | 1/4                                     | of   | NE  | 1/4  | of   | SW  | 1/4  | of S   | ection  | 25   |  |
|      | 10. | UTM   | refer                                     | ence zo   | ne:   | 1  | 13                                      |  |   |  |  |   |  |  |   |  |  |
|      |     | Eastir  | ng:                                       |   |   | 5  | 33497                                   | •  |   |  |  |   | North  | hing:  |   | 4236544  |  |
|      | 11. | USGS  | S qua                                     | ad name   | e:  | N  | Northe                                  | ast Pu   | ieblo   |  |  |   | Scal   | e:   |   | 7.5  |  |
|      |     | Year:   |   |   |   |  | 1961 (F<br>1974)                        | hotor  | evised 1970 and                                 |  |  |   |  |  |   |  |  |
|      | 12. | Lot(s)  | ):  |   |   | L  | _ot 7; I                                | 7; Block 2   |   |  |  |   |  |  |   |  |  |
|      |     | Additi  | ion:                                      |   |   | C  | Craig's                                 | Addit  | ion   |  |  |   | Year   | of additi  | ion:  | 1871   |  |
| 1    | 3.  | Bound   | Boundary description and justification:   |   |   |  |   |  |   |  |  |   |  |  |   |  |  |
|      |     | The p   | oarce                                     | ıl, as de   | escrib  | ed al  | bove, d                                 | contai   | ns bı   | ut doe   | s not  | exce  | ed the   | land his   | toricall  | y associated with this property.   |  |
|      |     | Mete  | es and                                    | d bound   | ds exis   | it:  |   |  |   |  |  |   |  |  |   |  |  |
| III. | AF  | RCHI  | TEC                                       | TURA  | AL DE   | ESC  | RIPT                                    | ION  |   |  |  |   |  |  |   |  |  |
| 1    | 4.  | Buildi  | ing pl                                    | an (foo   | tprint,   | shap   | e):                                     |  | Rectangular Plan                                |  |  |   |  |  |   |  |  |
|      |     | Other   | build                                     | ding pla  | n desc  | criptic  | ons:                                    |  |   |  |  |   |  |  |   |  |  |
| 1    | 5.  | Dimensions in feet (length x width):                |   |   |   |  | 980 square feet                         |  |   |  |  |   |  |  |   |  |  |
| 1    | 6.  | Numb  | Number of stories:                        |   |   |  | 1                                       |  |   |  |  |   |  |  |   |  |  |
| 1    | 7.  | Primary external wall material(s):                  |   |   |   | Wood/Weatherboard Other wall materials:                  |   |  |   |  |  |   |  |  |   |  |  |
| 1    | 8.  | Roof  | confi                                     | guratior  | า:  |  |   |  | Gabled Roof/Front Gabled Roof                   |  |  |   |  |  |   |  |  |
|      |     | Other   | roof                                      | configu   | ıration   | s:   |   |  |   |  |  |   |  |  |   |  |  |
| 1    | 9.  | Prima   | ary ex                                    | ternal r  | oof ma  | ateria   | al:                                     |  | Asphalt Roof/Composition Roof                   |  |  |   |  |  |   |  |  |
|      |     | Other   | roof                                      | materia   | als:  |  |   |  |   |  |  |   |  |  |   |  |  |
| 2    | 20. | Speci   | ial fea                                   | atures:   |   |  |   |  | Fen   | ice  |  |   |  |  |   |  |  |
|      |     |   |   |   |   |  |   |  | Por   | ch   |  |   |  |  |   |  |  |
| 2    | 21. | Gene  | ral ar                                    | chitect   | ural de   | scrip  | tion:                                   |  |   |  |  |   |  |  |   |  |  |
|      |     | protre<br>corne<br>vinyl,<br>has a<br>open<br>south | udes<br>erboa<br>, louv<br>i con<br>ing b | from t<br>ards, cl<br>vered s<br>crete fl<br>pehind | he cei<br>ads th<br>hutter<br>loor ai<br>a brov<br>east e | nter one ex<br>s fland<br>si<br>ond si<br>wn, a<br>eleva | of the terior nk mo mple, luminution. A | west e<br>walls.<br>st win<br>blue-p<br>um-fra<br>Approa | elevar<br>Windows<br>Dainte<br>Dame s<br>Dachin | tion. E<br>dows<br>s. A fr<br>ed, sq<br>storm<br>g it is | Blue-p<br>are 1-<br>ont-g<br>uare v<br>door. | painted<br>besid<br>abled<br>wood<br>A pla<br>ngle, c | d, horiz<br>e-1-lig<br>porch<br>suppo<br>te-glas<br>oncret | zontal, v<br>ht, slidir<br>protrud<br>rts. Ben<br>ss sliding<br>e stoop. | vooden<br>ng-sash<br>es from<br>eath the<br>g door, | bay, cantilevered over the foundation,<br>-composition weatherboard, with 1-by-4-inch<br>n, with brown aluminum frames. Dark-blue,<br>n the west half of the front (south) façade. It<br>e porch roof is a white, 6-panel, metal door,<br>with a brown, aluminum-frame, opens on the<br>asphalt shingles cover the front-gabled main |  |
| 2    | 22. | Archit  | tectui                                    | ral style   | ):  |  |   |  | No  | Style  | )  |   |  |  |   |  |  |
|      |     | Other   | arch                                      | itectura  | al style  | s:   |   |  |   |  |  |   |  |  |   |  |  |
|      |     | Buildi  | ing ty                                    | pe:   |   |  |   |  |   |  |  |   |  |  |   |  |  |
| 2    | 23. | Lands   | scape                                     | e or spe  | cial se   | etting   | featur                                  | es:  |   |  |  |   |  |  |   |  |  |

(Resource number)

## **Architectural Inventory Form**

Page 3

This property is located on terrain sloping downward from north to south, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest, one- and two-story houses. This property is situated on the northeast corner of West 12th and Craig streets. A grass-covered strip separates the sidewalk from the Street. Surrounding the house is a planted-grass yard, with mature landscaping. Encircling the backyard is a chain-link fence.

24. Associated buildings, features or objects:

1: Type: Shed

Describe: A kit-built or modular shed is located on the northeast corner of the lot. Oriented to the south,

the building rests on a concrete pad. The walls consist of blue-painted, particleboard sheets, with white, 1-by-4-inch cornerboards. Dominating the front (south) elevation is a particleboard door, with star-shaped bracing, opening on metal strap hinges. Gray asphalt shingles cover the front-gambreled roof.

#### IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: Actual: 1992

Source of Information: Pueblo County Office of Tax Assessor. Property information card [internet].

26. Architect: unknown

Source of information:

27. Builder: unknown

Source of information:

28. Original Owner: Housing Authority of Pueblo

Source of information: Pueblo County Office of Tax Assessor. Property information card [internet].

29. Construction history:

According to Pueblo County tax records, this building was constructed in 1992. An analysis of the form, style, and materials corroborates this date. It entirely replaced a house dating to 1900. There have been no notable alterations to the current house since its construction.

30. Location: original Date of move(s):

#### V. HISTORICAL ASSOCIATIONS

31. Original use(s): Single Dwelling
32. Intermediate use(s): Single Dwelling
33. Current use(s): Single Dwelling
34. Site type(s): Residence

35. Historical background:

The Housing Authority of Pueblo constructed this house in 1992 on the site of a dwelling dating to 1900. The housing authority continues to operate this property as a low-income rental unit.

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

# **Architectural Inventory Form**

Page 4

| ı. Sı | GNIFI                                     | CANCE   |  |  |  |  |  |  |  |  |  |  |  |
|-------|---|---|--|--|--|--|--|--|--|--|--|--|--|
| 37.   | Desig                                     | Local landmark designation:  Yes No  Designation authority:  Date of designation:   |  |  |  |  |  |  |  |  |  |  |  |
| 38.   | 3. Applicable National Register criteria: |   |  |  |  |  |  |  |  |  |  |  |  |
|       |   | <ul> <li>A. Associated with events that have made a significant contribution to the broad pattern of our history.</li> <li>B. Associated with the lives of persons significant in our past.</li> <li>C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose components may lack individual distinction.</li> <li>D. Has yielded, or may be likely to yield, information important in history or prehistory.</li> <li>Qualifies under Criteria Considerations A through G (see manual).</li> <li>Does not meet any of the above National Register criteria.</li> </ul> |  |  |  |  |  |  |  |  |  |  |  |
|       | Puel                                      | eblo Standards for Designation:   |  |  |  |  |  |  |  |  |  |  |  |
|       | <b>2</b>                                  | 1a. History Have direct association with the historical development of the city, state, or nation; or  1b. History Be the site of a significant historic event; or  |  |  |  |  |  |  |  |  |  |  |  |
|       | 0   | 1c. History   |  |  |  |  |  |  |  |  |  |  |  |
|       |   | Have direct and substantial association with a person or group of persons who had influence on society.  2a. Architecture   |  |  |  |  |  |  |  |  |  |  |  |
|       |   | Embody distinguishing characteristics of an architectural style or type; or   |  |  |  |  |  |  |  |  |  |  |  |
|       |   | 2b. Architecture  Be a significant example of the work of a recognized architect or master builder, or  |  |  |  |  |  |  |  |  |  |  |  |
|       |   | 2c. Architecture  Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a significant or influential innovation;   |  |  |  |  |  |  |  |  |  |  |  |
|       | 0   | 2d. Architecture  Portray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style.  |  |  |  |  |  |  |  |  |  |  |  |
|       |   | 3a. Geography  Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or  |  |  |  |  |  |  |  |  |  |  |  |
|       | 0   | 3b. Geography  Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or  |  |  |  |  |  |  |  |  |  |  |  |
|       | 0   | 3c. Geography  Make a special contribution to Pueblo's distinctive character.   |  |  |  |  |  |  |  |  |  |  |  |
|       |   | Not Applicable  Does not meet any of the above Pueblo landmark criteria.  |  |  |  |  |  |  |  |  |  |  |  |
| 39.   | Area(s)                                   | of Significance: Not Applicable   |  |  |  |  |  |  |  |  |  |  |  |
| 40.   | Period                                    | of Significance: n/a  |  |  |  |  |  |  |  |  |  |  |  |
| 41.   | Level o                                   | significance: National: State Local   |  |  |  |  |  |  |  |  |  |  |  |

(Resource number)

## **Architectural Inventory Form**

Page 5

42. Statement of significance:

Because this property is less than 50 years old and does not meet any of criteria considerations A through G, it is ineligible for listing in the National Register of Historic Places. Moreover, the architectural and historical significance are not to the extent that the property would qualify for individual listing in the Colorado State Register of Historic Properties or as a City of Pueblo landmark. Given its age, the property should not be considered a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed in 1992, this house exhibits a high level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. It has not been notably altered since its construction. The building retains sufficient physical integrity to convey its significance.

|      | conveyits  | s significance.                            |                            |              |              |     |             |  |  |  |  |  |  |  |
|------|--|--|----------------------------|--------------|--------------|-----|-------------|--|--|--|--|--|--|--|
| /II. | . NATIONAL REGISTER ELIGIBILITY ASSESSMENT   |  |                            |              |              |     |             |  |  |  |  |  |  |  |
| 44.  | National Re  | egister eligibility field assessment:      | ☐ Individually eligible    | Not eligible |              |     | ■ Need data |  |  |  |  |  |  |  |
|      | Local landn  | nark eligibility field assessment:         | Individually eligible      |              | Not eligible | le  | ■ Need data |  |  |  |  |  |  |  |
| 45.  | Is there Na  | tional Register district potential?        | Yes 🔝 No 🗖                 |              |              |     |             |  |  |  |  |  |  |  |
|      | Discuss: Pueblo's North Side Neighborhood represents the evolution of the city's professional middle and upper classes. Its diversity of architectural styles and forms directly represents the city's changing economic and cultural climates. As well, the neighborhood is distinctive because it appears to have evolved independently the area's dominant industry, steel manufacturing. |  |                            |              |              |     |             |  |  |  |  |  |  |  |
|      | If there is N  | lational Register district potential, is t | his building contributing: | Yes          | No 🕝         | N/A |             |  |  |  |  |  |  |  |
| 46.  | If the building  | ng is in existing National Register dis    | trict, is it contributing: | Yes          | No 🗖         | N/A |             |  |  |  |  |  |  |  |
|      |  |  |                            |              |              |     |             |  |  |  |  |  |  |  |

#### **VIII. RECORDING INFORMATION**

47. Photograph numbers): CD-ROM Photo Disc: North Side Photos

File Name(s): 12thstw727

Negatives filed at: Special Collections

**Robert Hoag Rawlings Public Library** 

100 East Abriendo Avenue Pueblo, CO 81004-4290

48. Report title: Pueblo North Side Neighborhood Survey

49. Date(s): **06/20/05** 

50. Recorder(s): Adam Thomas

51. Organization: Historitecture, L.L.C.

52. Address: PO Box 419


Estes Park, CO 80517-0419

53. Phone number(s): (970) 586-1165

727 W 12th Street 5PE.5632 (Resource number)

## **Architectural Inventory Form**

Page 6




(Resource number)

# **Architectural Inventory Form**

Page 7

### **LOCATION MAP**



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)