Official Eligibility Determination

(OAHP use only)

OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

Date	e Initials
	_Determined Eligible-National Register
	_Determined Not Eligible - National Register
	_Determined Eligible - State Register
	_Determined Not Eligible - State Register
	_Need Data
	_Contributing to eligible National Register District
	Noncontributing to eligible National Register District

Parcel number(s):

525311001



I. IDENTIFICATION

I. Resource number: 5PE.5656

2. Temporary resource number:

3. County: Pueblo4. City: Pueblo

5. Historic building name: Footman, Lawrence and John, House

6. Current building name: Duran, Xavier J., House
7. Building address: 712 W 13th Street
8. Owner name: Xavier J. Duran

Owner organization:

Owner address: 1630 Moore Ave., Ste. 1

Pueblo, CO 81005

4.	National Register eligibility field assessment:	☐ Individually eligible	Not eligible	☐ Need data
	Local landmark eligibility field assessment:	Individually eligible	Not eligible	■ Need data

(Resource number)

Architectural Inventory Form

Page 2

II. GE	EOGRAPHIC INFO	RMA	TION									
9.	P.M.: 6th		Tow	nship:	2	208			R	ange:	65V	v
	SW 1/4 of	NE		of I	NE	1/4	of	sw	1/4	•	ection	25
10.	UTM reference zone:		13									
	Easting:		533563	3					Northi	ng:		4236602
11.	USGS quad name:		Northe	ast Pu	eblo	ı			Scale			7.5
	Year:		1961 (F 1974)	Photore	evise	ed 197	0 and	I				
12.	Lot(s):		Lot 1;	Block 2	2							
	Addition:		Craig's	Additi	ion				Year	of additi	on:	1871
13.	Boundary description a	and ju	stificati	on:								
	The boundary, as des	scribe	ed abov	ve, con	tain	s but	does	not ex	ceed th	e land	histori	cally associated with this property.
	Metes and bounds ex	dist:										
III. Al	RCHITECTURAL D	DESC	RIPT	ION								
14.	Building plan (footprint	t, shar	oe):		Irre	gular	Plan					
	Other building plan des					•						
15.	Dimensions in feet (ler				1.1	55 sqı	uare fe	eet				
16.	Number of stories:	3	,		1							
17.	Primary external wall n	materi	al(s):			ссо						Other wall materials:
	•											
18.	Roof configuration:				Hip	ped R	Roof/G	able-	on-hip F	Roof		
	Other roof configuratio	ns:										
19.	Primary external roof r	materi	al:		Asp	ohalt F	Roof/C	Comp	osition I	Roof		
	Other roof materials:											
20.	Special features:				wir	ndow/	Segm	ental	Arch			
					Fer	nce						
					Chi	imney	,					
					Por	rch						
21.	General architectural of	descri	ption:									
	exterior walls. Windo storm windows. They brown. A front-gable windows, with multi- windows and a band access to the princip transom. Another do	ows a y ope d bay light of clo oal do orway shing	re gene n bene protru sidelig erestor orway, y opens les cov	erally 1 ath seg des fro hts and y wind which s in the ver the	omer om ti d tra lows ope sou gab	er-1-lightal are sound in the sound in the end of the e	ght, donches, uth en s. End enclose the ea evation	ouble, some of to closing sed from the contract factors.	hung sa e of which he west g the fro ont porce ce of the he front- oxing th	ash, with are personal control	th brow project ion. It h ch is a the ins r. It hos I bay p	concrete and stucco. Tan stucco clads the vn-painted wood frames and aluminum-frame ting, and dressed sandstone sills, painted nosts a pair single-light hopper or awning pair of 1-over-1-light, double-hung sash side (northeast-facing) corner. It provides sts a 4-panel, white-painted wood door, with rojecting from the west elevation. Brown, rown-painted wood fascia and soffit. A stucco-
22.	Architectural style:				La	te Vic	torian	1				
	Other architectural styl	les:										

(Resource number)

Architectural Inventory Form

Page 3

Building type:

23. Landscape or special setting features:

This property is located on terrain sloping downward from north to south, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest, one- and two-story houses and commercial buildings. Setbacks from West 13th Street, the busy, principal east-west thoroughfare through this area, are generally the same on this block. This property is situated on the south side of West 13th Street, between 706 West 13th Street to the east and 714 West 13th Street to the west. Grass covers the strip separating the sidewalk from the street. A planted-grass yard, with mature landscaping, covers the lot. Obscuring the front (north) façade of the house a pair of huge cedars. A wood privacy fence encircles the backyard.

24. Associated buildings, features or objects:

1: Type: Garage

Describe: A single-car garage is located on the southwest corner of the lot. Oriented to the south, the

building rests on a concrete slab. Unpainted sheets of particleboard clad the exterior walls. Dominating the front (south) elevation are paired, gray-and-white-painted, beadboard doors. While they once opened on metal strap hinges, they have now been fixed shut. Appearing in the center of the east elevation is a single-light awning window. A 2-panel, brown-painted wood door opens in the south end of the east elevation. The north end of the same elevation hosts a 5-panel, brown-painted wood door. An open, shed-roofed structure spans the east

elevation. Brown, interlocking asphalt shingles cover the front-gabled roof.

IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: 1890 Actual:

Source of Information: Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk &

Co, consulted 1886 through 2003.

26. Architect: unknown

Source of information:

27. Builder: unknown

Source of information:

28. Original Owner: Lawrence and John Footman

Source of information: Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk &

Co, consulted 1886 through 2003.

29. Construction history:

According to Pueblo County Tax Assessor records, this building was constructed in 1900. However it appears on an 1893 Sanborn map, and city directory listings for this address date to 1890, suggesting a circa 1890 date of construction. The front porch and a porch on the south end of east elevation have been enclosed, while another open porch was constructed on the north end of the east elevation. The front-gabled bay on the south end of the west elevation is also an addition. Based on Sanborn maps, these modifications appear to date to after 1952. The stucco, which covers the original brick wall cladding, dates to after 1952 or even more recently.

30. Location: **original** Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Single Dwelling
32. Intermediate use(s): Single Dwelling
33. Current use(s): Single Dwelling
34. Site type(s): Residence

35. Historical background:

The first residents of this house, constructed around 1890, were brothers John and Lawrence J. Footman, house painters. They

(Resource number)

Architectural Inventory Form

Page 4

resided here with their widowed mother, Elizabeth Footman. The family came to Colorado from Ohio. Lawrence was born in September 1838. John was born in 1843 and served in the Civil War with Company I of the 60th Ohio Volunteers Infantry. Another brother, Lewis E. Footman, was a Pueblo-area farmer.

By 1900, the owner and resident was druggist Charles Wells. He was born in Indiana in May 1859. He was widowed only a few years into his marriage, leaving him to raise two young daughters, Hazel D. and Gladys I. Assisting him was a domestic servant, Margaret Schiller. The family lived here through 1909.

Charles E. Johnson owned this property and resided in the house beginning around 1914. He was born around 1871 and, with his wife, had three children: Pearl, Helen, and Kendall Johnson. Charles Johnson was an engineer at the Pope Block. Charles Johnson died on February 16, 1921.

Around 1925, Paul W. Jones, a lifetime resident of Pueblo, purchased this property and resided here for approximately 50 years. He had two children, Harold L. Jones and Pauline M. Somes. Shortly before his death, on July 24, 1978, Paul Jones moved to the University Heights Nursing Home.

Mike J. and Aurora T. Gonzales purchased this property in 1978, selling it to Xavier J. Duran, the current owner, in 2002. Duran operates the property as a rental unit.

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

U.S. Census of 1900. Precinct 15, Pueblo, Pueblo County, Colorado. Series T623, roll 128, p. 151.

U.S. Census of 1900. Precinct 3, Pueblo, Pueblo County, Colorado. Series T623, roll 128, p. 15.

"Paul W. Jones" [obituary]. Pueblo Chieftain, 26 July 1978, p. 8B.

"John Footman" [obituary]. Pueblo Chieftain, 11 September 1922, p. 8.

"Charles E. Johnson" [obituary]. Pueblo Chieftain, 17 February 1921, p. 10.

(Resource number)

Architectural Inventory Form

Page 5

VI.	SIGNIFICANCE	
37.	. Local landmark designation: Yes 🔲 No 💽	
	Designation authority:	
	Date of designation:	
38.	. Applicable National Register criteria:	
	 A. Associated with events that have made a significant contribution to the broad pattern of our history. B. Associated with the lives of persons significant in our past. 	
	C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose components may lack individual distinction.	
	D. Has yielded, or may be likely to yield, information important in history or prehistory.	
	Qualifies under Criteria Considerations A through G (see manual).	
	Does not meet any of the above National Register criteria.	
	Pueblo Standards for Designation:	
	1a. History	
	Have direct association with the historical development of the city, state, or nation; or	
	1b. History	
	Be the site of a significant historic event; or	
	1c. History	
	Have direct and substantial association with a person or group of persons who had influence on society.	
	2a. Architecture	
	Embody distinguishing characteristics of an architectural style or type; or	
	2b. Architecture	
	Be a significant example of the work of a recognized architect or master builder, or	
	 2c. Architecture Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a significant or influential innovation; 	
	2d. Architecture	
	Portray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style.	
	3a. Geography	
	Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or	
	 3b. Geography Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or 	
	3c. Geography	
	Make a special contribution to Pueblo's distinctive character.	
	Not Applicable	
	Does not meet any of the above Pueblo landmark criteria.	
39	9. Area(s) of Significance: Architecture	
40	D. Period of Significance: ca. 1890	
41	1. Level of significance: National: State Local	

(Resource number)

Architectural Inventory Form

Page 6

42. Statement of significance:

This property is historically significant under Pueblo Local Landmark criterion 1A for its association with the development of Pueblo's North Side Neighborhood, when more architecturally sophisticated buildings like this one joined the smaller, plainer dwellings originally constructed here. As well, the house is architecturally significant under National Register criterion C (Pueblo Local Landmark criterion 2A) as an example of late Victorian-era domestic architecture. However, the levels of architectural and historical significance, combined with physical integrity, are not to the extent that this property would qualify for individual listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a City of Pueblo Landmark. It is, nonetheless, a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed around 1890, this house exhibits a moderate level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. While additions and modifications probably date to within the period significance, they have removed or concealed some important character-defining features, particularly the front porch and brickwork. Nonetheless, the building remains in its basic form, retaining sufficient physical integrity to convey its architectural and historical significance.

VII.	NATIONAL	KEGIS I E	K ELIGIBIL	.IIY A55E5	SIVI EN I

44.	. National Register eligibility field assessment:		☐ Individually eligible	Not eligible	■ Need data
	Local landma	ark eligibility field assessment:	Individually eligible	Not eligible	Need data
45.	Is there Natio	onal Register district potential?	Yes 🐼 No 🗖		
Discuss: Pueblo's North Side Neighborhood represents the evolution of the city's professional middle and upper classes. Its diversity of architectural styles and forms directly represents the city's changing economic and cultural climates. As well, the neighborhood is distinctive because it appears to have evolved independent the area's dominant industry, steel manufacturing.					

If there is National Register district potential, is this building contributing:

Yes No
N/F

46. If the building is in existing National Register district, is it contributing:

Yes No N/A

VIII. RECORDING INFORMATION

47. Photograph numbers): CD-ROM Photo Disc: North Side Photos

File Name(s): 13thstw712

Negatives filed at: Special Collections

Robert Hoag Rawlings Public Library

100 East Abriendo Avenue Pueblo, CO 81004-4290

48. Report title: Pueblo North Side Neighborhood Survey

49. Date(s): **06/28/05**

50. Recorder(s): Adam Thomas

51. Organization: Historitecture, L.L.C.

52. Address: **PO Box 419**


Estes Park, CO 80517-0419

53. Phone number(s): (970) 586-1165

712 W 13th Street 5PE.5656 (Resource number)

Architectural Inventory Form

Page 7




(Resource number)

Architectural Inventory Form

Page 8

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)