COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

Official Eligi (OAHP use o	bility Determination only)	OAHP1403 Rev. 9/98
Date	Initials	
Determine	ed Eligible-National Register	
Determine	d Not Eligible - National Register	
Determine	ed Eligible - State Register	
Determine	ed Not Eligible - State Register	
Need Data	a	
Contributir	ng to eligible National Register Distr	rict
Noncontrib	outing to eligible National Register [District

Parcel number(s):

525311004



I. IDENTIFICATION

Resource number: 5PE.5662

Temporary resource number: 3. County: **Pueblo** 4. City: **Pueblo**

Historic building name: Cleghorn, John, House Current building name: 722 West 13th Street 7. 722 W 13th Street Building address:

JP Morgan Chase Bank (Trustee) Owner name:

Owner organization:

Owner address: 9350 Waxie Way

San Diego, CA 92123

National Register eligibility field assessment: ☐ Individually eligible Not eligible ■ Need data Local landmark eligibility field assessment: Individually eligible Not eligible ■ Need data

(Resource number)

Architectural Inventory Form

Page 2

II. GEOGRAPHIC INFORMATION																			
9.	P.M.:	•	Sth			Tow	nship	:	20S			F	Range:	65\	N				
		sw	1/4	of	NE	1/4	of	NE	1/4	of	sw	1/4	of	Section	25				
10.	10. UTM reference zone: 13 Easting: 533521																		
												North	ing:		4236602				
11.	USGS quad name: Northeast Pu							ueblo)			Scale) :	7.5					
	Year: 1961 (Photo 1974)							orevis	ed 197	0 and	i								
12.	12. Lot(s): East 40 feet								ot 4; Bl	ock 2	2								
	Additi	ion:				Craig's	s Add	lition				Year	of addi	1871					
13.	Boun	dary	descri	ption a	ınd ju	ıstificat	ion:												
	The b	ooun	dary, a	as des	cribe	ed abo	ve, c	ontair	s but	does	not e	ceed tl	he land	d histori	ically associated with this property.				
	Mete	es and	d bour	nds exi	st:														
			T	41 5		\D.ID.T													
III. A							ION												
14.				otprint.				Irre	egular	Plan									
4.5				an des					_										
15.					igth x	width)	:	925 square feet											
16.			storie			- 1/ -)		D						Otherwell materials					
17.	Prima	ary ex	ternai	wall m	nateri	iai(s):			ick ood/Plv	woo	d/Part	icle Bo	ard	Other wall materials:					
18.	Roof	confi	guratio	on:					-			Gabled							
			_	juratio	ns:														
19.	Primary external roof material:						As	phalt F	Roof/0	Comp	osition	Roof							
	Other	roof	mater	ials:															
20.	Speci	ial fea	atures					Fe	nce										
								Ga	rage/A	ttach	ed Ga	rage							
									imney			J							
									rch										
								Wi	ndow/	Stain	ed Gla	ass							
								Wi	ndow/	Segm	ental	Arch							

21. General architectural description:

Oriented to the north, this house rests on a buff-colored, rock-faced sandstone foundation arranged as coursed ashlar. The walls consist of cream-painted brick. Plywood sheets, pressed into a vertical-plank pattern, cover the exterior walls of an enclosed porch wrapping around the house's northeast corner. The plywood is painted cream, with green-painted cornerboards. Windows are generally 1-over-1-light, double-hung sash, with white vinyl frames. These windows open between green-painted, rock-faced sandstone sills and segmental arches. The segmental arch above the window opening in the second story of the front (north) elevation, beneath the gable, has a sandstone keystone and springers. Above it, in the gable, is a corbelled pattern of rounded bricks. The enclosed porch hosts 1-beside-1-light, sliding-sash windows, with brown aluminum frames. Near the center of the east elevation's first floor is a stained-glass hopper window. A pair of doorways opens into the porch, on the east side of the north elevation and the south side of the east elevation. Both host 4-panel, metal doors, with fanlights. The door in the north elevation is white, approached by a single concrete step. The door in the east elevation is

(Resource number)

Architectural Inventory Form

Page 3

painted green and is approached by a two-step wood stoop, sheltered beneath a shed roof. Another doorway opens in the north elevation of a gabled wing protruding from the south end of the east elevation. It hosts a 6-panel, white-painted wood door, opening behind a white, aluminum-frame storm door. Approaching it are 2 concrete steps. A doorway opens near the center of the rear (south) elevation. It hosts a 2-panel, 1-light, white-painted metal door, opening behind an aluminum-frame storm door. Approaching it is a small, uncovered wood deck, with simple wood balustrade. A shed-roofed, 1-car garage is attached to the southwest corner of the house. A gravel driveway approaches it from West 13th Street. Dominating its front (south) elevation are paired, three-panel wood doors, painted cream. A 16-panel, white, steel, overhead retractable garage door consumes the rear (south) elevation of the garage. Gray, interlocking asphalt shingles cover the cross-gabled roof, and green-painted wood soffit and fascia, with protruding cornice, boxes the eaves. A white-painted, corbelled brick chimney protrudes near the northwest corner of the house and another emerges at the junction of the roof ridges.

22. Architectural style: Late Victorian/Edwardian

Other architectural styles:

Building type:

23. Landscape or special setting features:

This property is located on terrain sloping downward from north to south, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest, one- and two-story houses and commercial buildings. Setbacks from West 13th Street, the busy, principal east-west thoroughfare through this area, are generally the same on this block. This property is situated on the south side of West 13th Street, between 716 West 13th Street to the east and 724 West 13th Street to the west. Gravel covers the strip separating the sidewalk from the street. A planted-grass yard, with mature landscaping, covers the lot. Dominating the back yard is a gravel parking area and driveway to the attached garage. A wood privacy fence delimits the eastern edge and the eastern half of the southern edge of the property.

24. Associated buildings, features or objects: No associated buildings identified.

IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: 1900 Actual:

Source of Information: Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk &

Co, consulted 1886 through 2003.

26. Architect: unknown

Source of information:

27. Builder: unknown

Source of information:

28. Original Owner: John Cleghorn

Source of information: Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk &

Co, consulted 1886 through 2003.

29. Construction history:

According to Pueblo County Tax Assessor records, this building was constructed in 1900. Sanborn maps and city directories corroborate this date. It was one of four nearly identical and neighboring houses: 722 (5PE.5662), 724 (5PE.5663), 726 (5PE.517.39), and 738 (5PE.517.4) West 13th Street. The attached garage was not an original feature but, based on Sanborn maps, was constructed before 1952. The enclosed front and rear porches, replaced windows, and the paint applied over the original brick exterior wall cladding appear to date to sometime after 1990, based on the building materials.

30. Location: **original** Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Single Dwelling
32. Intermediate use(s): Single Dwelling
33. Current use(s): Single Dwelling
34. Site type(s): Residence

(Resource number)

Architectural Inventory Form

Page 4

35. Historical background:

The first owner and resident of this house, constructed around 1900, was John Cleghorn, founder and president of John Cleghorn & Company, a grocer and seed distributor. He was born in Canada in May 1852. He married his wife, Anna M., around 1882. She was born in Illinois in January 1863. They had at least three children: Willard V., Miriam A., and Madeline G. They resided here with a domestic servant, who in 1900 was Mesia Jones, and remained at this address until prior to 1909.

The owner and resident from around 1909 through 1919 was James Wimmer, vice president of the S.C. Gallup Saddlery Company. From around 1925 through 1935, the resident and owner was Aldred B. Shurtz. The residents in 1940 were Cecil W. Calhoun, Thomas V. Latta, and George Drake.

Melvin L. Shafer purchased the property around 1945 and resided here through 1950. He served in the U.S. Army in France during World War I and came to Pueblo in 1931. Shafer's wife was Florence B. Shafer, and he had two children, Carol Morse and Frederick Baker. Melvin Shafer died on October 10, 1986.

In 1955, the resident was Francis Forsythe, followed by Lela A. Jones and Fannie Dawson in 1960. Myrtyl M. Jackson purchased the property prior to 1981, when she transferred it to John M. Jackson. Elden W. Burchard acquired the house and lot in 1991, selling it to Todd S. Levine in 1996. In 1999, Levine sold the property to Thomas Moriarty. J.P. Morgan Chase Bank, the current owner, obtained the house and lot in 2004.

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

U.S. Census of 1900. Precinct 3, Pueblo, Pueblo County, Colorado. Series T623, roll 128, p. 12.

"Melvin L. Shafer" [obituary]. Pueblo Chieftain, 10 October 1987, p. 7D.

5PE.5662

722 W 13th Street

(Resource number)

Architectural Inventory Form

Page 5

VI.	SIGNIFIC	ANCE												
37	. Local la	andmark designatio	on: Yes		No	2								
	Design	ation authority:												
	Date of	f designation:												
38	. Applica	able National Regis	ter criteria:											
		B. Associated with the lives of persons significant in our past.												
		components may lack individual distinction.												
D. Has yielded, or may be likely to yield, information important in history or prehistory.Qualifies under Criteria Considerations A through G (see manual).														
		Does not meet any			_	•	•							
		o Standards for D			J									
	2	1a. History Have direct assoc	ciation with the I	nistorica	al develo	pment o	of the city, s	state, or nation	; or					
		1b. History Be the site of a si	gnificant histori	c event	; or									
	_	1c. History												
		Have direct and s	ubstantial asso	ciation	with a pe	erson or	group of pe	ersons who had	d influence o	n society.				
	_	2a. Architecture	-1-:	:-4:4		:44								
		_												
		2b. Architecture Be a significant e	Be a significant example of the work of a recognized architect or master builder, or											
		2c. Architecture												
		Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a significant or influential innovation;												
	_	2d. Architecture												
		Portray the environment of the characterized by	•			ohysical	developme	ent of an area	of the city in a	an era of history				
	_	3a. Geography												
		•	ire of the cor	ntemporary city, or										
		3b. Geography Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteris or rarity; or												
	0	3c. Geography Make a special co	ontribution to Pu	ıeblo's	distinctiv	e chara	cter.							
		Not Applicable												
		Does not meet ar	ny of the above	Pueblo	landmar	k criteria	a.							
39	9. Area(s) o	of Significance:	Architecture)										
40	D. Period of	f Significance:	ca. 1900											
41	1. Level of	significance:	National:	St	ate	Loca								

(Resource number)

Architectural Inventory Form

Page 6

42. Statement of significance:

This property is historically significant under Pueblo Local Landmark criterion 1A for its association with the development of Pueblo's North Side Neighborhood, when more architecturally sophisticated buildings joined the smaller, plainer dwellings originally constructed here. It is also associated with Pueblo's professional, entrepreneurial middle class, which largely settled in the neighborhood. As well, the house is architecturally significant under National Register criterion C (local landmark criterion 2A) as an example of the Edwardian style. However, the levels of architectural and historical significance, combined with physical integrity, are not to the extent that this property would qualify for individual listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a City of Pueblo Landmark. It is, nonetheless, a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed around 1900, this house exhibits a moderate level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. Enclosed porches, replaced window, and a newer exterior wall cladding have all removed some character-defining features. Nonetheless, this house still retains its basic form and other architectural features typical to the style.

'II. I	NATIONA	L REGISTER ELIGIBILITY A	SSESSMEN	IT										
44.	National Re	egister eligibility field assessment:	☐ Ind	No.	ot eli	gible		■ Need data						
	Local landr	mark eligibility field assessment:	☐ Ind		 7. N	ot eli	gible	Need data			ıta			
45.	Is there Na	tional Register district potential?	Yes 🚁	No										
	Discuss:	Pueblo's North Side Neighborho classes. Its diversity of architect cultural climates. As well, the net the area's dominant industry, st	tural styles an eighborhood is	d forms s distinc	directly rep	present	ts the	city	's ch	angin	g eco	nomic	and	of
	If there is N	National Register district potential, is t	his building cor	ntributing	:	Yes		No		N/A				
46.	If the buildi	ng is in existing National Register dis	trict, is it contri	buting:		Yes		No		N/A	7			

VIII. RECORDING INFORMATION

47. Photograph numbers): CD-ROM Photo Disc: North Side Photos

File Name(s): 13thstw722

Negatives filed at: Special Collections

Robert Hoag Rawlings Public Library

100 East Abriendo Avenue Pueblo, CO 81004-4290

48. Report title: Pueblo North Side Neighborhood Survey

49. Date(s): **06/28/05**

50. Recorder(s): Adam Thomas

51. Organization: Historitecture, L.L.C.

52. Address: **PO Box 419**


Estes Park, CO 80517-0419

53. Phone number(s): (970) 586-1165

722 W 13th Street 5PE.5662 (Resource number)

Architectural Inventory Form

Page 7




(Resource number)

Architectural Inventory Form

Page 8

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)