COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

Date Initials
Determined Eligible-National Register
Determined Not Eligible - National Register
Determined Eligible - State Register
Determined Not Eligible - State Register
Need Data
Contributing to eligible National Register District
Noncontributing to eligible National Register District



I. IDENTIFICATION

1. Resource number: 5PE.5699

2. Temporary resource number:

3. County: Pueblo4. City: Pueblo

Historic building name: Parkview Medical Center
 Current building name: Medical Office Building
 Building address: 405 W 15th Street

8. Owner name: Parkview Medical Center, Inc.

Owner organization:

Owner address: 400 W 16th St

44. National Register eligibility field assessment: Local landmark eligibility field assessment:

Pueblo, CO 81003

☐ Individually eligible	Not eligible	□ Need data
Individually eligible	Not eligible	Need data

Parcel number(s):

525142008

(Resource number)

Architectural Inventory Form

Page 2

II. GEOGRAPHIC INFORMATION																
	9.	P.M.:	6	ith			Town	ship:	2	.0S			R	Range:	65V	v
			sw	1/4	of	sw	1/4	of :	SE	1/4	of	NE	1/4	of S	ection	25
	10.	UTM r	efere	ence zo	one:	1	3									
		Eastin	ıg:			5	33947						North	ing:		4236860
	11.	USGS	qua	d name	e:	N	lorthe	ast Pu	eblo				Scale) :		7.5
		Year:					961 (P 974)	hotor	evise	ed 197	0 and	t				
	12.	Lot(s)	:			N		Additio	n. Al							k 1 of Bartlett & of Henry C.
		Additio	on:			В	Bartlett	& Mil	ller A	dditio	n		Year	of additi	ion:	1871
1	3.	Bound	dary o	descrip	tion an	nd jus	tification	on:								
		The b	ound	dary, a	s desc	cribe	d abov	e, cor	ntains	s but o	does	not e	ceed th	he land	histori	cally associated with this property.
		Mete	s and	d bound	ds exis	t:										
III.	AF	RCHIT	ГЕС	TURA	AL DE	SC	RIPT	ON								
1	4.	Buildir	ng pla	an (foo	tprint,	shap	e):		Rec	tangu	ılar P	lan				
		Other	build	ling pla	ın desc	criptio	ns:									
1	5.	Dimer	nsion	s in fee	et (leng	gth x v	width):		8,83	36 squ	iare f	eet				
1	6.	Numb	er of	stories	s:				2							
1	7.	Primary external wall material(s):				Brio	ck					Other wall materials:				
1	8.	Roof o	config	guration	n:				Flat	Roof						
		Other	roof	configu	urations	s:										
1	9.	Prima	ry ex	ternal r	roof ma	ateria	ıl:		Asp	halt R	Roof					
		Other	roof	materia	als:											
2	20.	Specia	al fea	atures:					Fen	се						
2	21.	Gener	ral ar	chitect	ural de	scrip	tion:									
	Oriented to the east, this office building rests on a concrete foundation. A tan-brick veneer clads the exterior walls. Panels of brick on all but the north elevation and the parapet are painted brown. However, blue, glazed bricks are showing though the paint. Windows are 1-beside-1-light, sliding-sash, with aluminum frames and brick sills. Those on the lower level open behind heavy steel grilles. Fixed-frame, single-light windows appear in the south end of the west elevation, and in the second story of the northeastern bay. Most windows open beneath round, blue canvas awnings. Two doorways open in bays protruding from either end of the symmetrical facade. Both host aluminum-frame, plate-glass doors. The rear (west) elevation is similar to the façade, but, because of the slope of the terrain, the doorways enter the second story. Asphalt and gravel covers the flat roof, which is surrounded by a parapet.															
2	22.	Archite	ectur	al style	: :				Мо	dern	Move	ement	s			
		Other	arch	itectura	al style	s:										
		Buildir	ng ty	pe:												
2	23.	Lands	cape	or spe	ecial se	etting	feature	es:								

(Resource number)

Architectural Inventory Form

Page 3

This property is located on terrain sloping downward from northwest to southeast, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest, one- and two-story houses. Setbacks from West 14th Street are generally the same on this block. This property is situated on the northwest corner of West 15th Street and North Grand Avenue. Grass covers the strips separating the sidewalks from the streets. A planted-grass yard, with mature landscaping, is located along the south side of the building. Brick planters fill the recesses of the building. Surrounding a sunken garden along the south side of the building is a brick wall capped by a metal mesh railing. To the east and west are macadam parking lots.

24. Associated buildings, features or objects: No associated buildings identified.

IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: Actual: 1963-64

Source of Information: Pueblo County Office of Tax Assessor. Property information card [internet].

26. Architect: unknown

Source of information:

27. Builder: unknown

Source of information:

28. Original Owner: Parkview Episcopal Hospital & Howard Whitlock Jr.

Source of information: Pueblo County Office of Tax Assessor. Property information card [internet].

29. Construction history:

According to Pueblo County Tax Assessor records, this building was constructed in 1967. However, a newspaper article from November 1963 reports that the building would be completed in December of that year. An analysis of the style, materials, and historical records corroborates the 1964-64 date. The only notable alteration since that time has been the painting of the bluebrick panels and parapets.?ÿ

30. Location: original Date of move(s):

V. HISTORICAL ASSOCIATIONS

Original use(s): Medical Business/Medical Office
 Intermediate use(s): Medical Business/Medical Office
 Current use(s): Medical Business/Medical Office

34. Site type(s): Medical Office Building

35. Historical background:

This medical office building was constructed in late 1963 or early 1964 as part of the adjacent Parkview Episcopal Hospital/Parkview Medical Center complex. The \$275,000-building was designed with office space for 14 physicians and dentists. The first 2 physicians to open offices in the building were Dr. Clifford F. Bramer and Dr. Herbert H. Schneider. Dr. Bramer graduated from the University of Buffalo and began practicing in Pueblo in 1948. Dr. Schneider was a graduate of the University of Bern, Switzerland. He trained as physician in hospitals in Washington, D.C., and Albuquerque, N.M., before coming to Pueblo. This building continues to house a variety of specialty medical professionals.

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

"Two Doctors Open Offices in Parkview Medical Center." Pueblo Chieftain, 5 November 1963, p. 3A.

(Resource number)

Architectural Inventory Form

Page 4

ı. Sı	GNIFI	CANCE										
37.	Local landmark designation: Yes No Designation authority: Date of designation:											
38.	8. Applicable National Register criteria:											
		 A. Associated with events that have made a significant contribution to the broad pattern of our history. B. Associated with the lives of persons significant in our past. C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose components may lack individual distinction. D. Has yielded, or may be likely to yield, information important in history or prehistory. Qualifies under Criteria Considerations A through G (see manual). Does not meet any of the above National Register criteria. 										
	Puel	olo Standards for Designation:										
	2	1a. History Have direct association with the historical development of the city, state, or nation; or 1b. History Be the site of a significant historic event; or										
	u	1c. History										
		Have direct and substantial association with a person or group of persons who had influence on society.										
		2a. Architecture Embody distinguishing characteristics of an architectural style or type; or										
		2b. Architecture Be a significant example of the work of a recognized architect or master builder, or										
		2c. Architecture Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a significant or influential innovation;										
		2d. ArchitecturePortray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style.										
		3a. Geography Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or										
	0	3b. Geography Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or										
	0	3c. Geography Make a special contribution to Pueblo's distinctive character.										
		Not Applicable Does not meet any of the above Pueblo landmark criteria.										
39.	Area(s)	of Significance: Not Applicable										
40.	Period	of Significance: n/a										
41.	Level o	significance: National: State Local										

(Resource number)

Architectural Inventory Form

Page 5

42. Statement of significance:

Because this property is less than 50 years old and does not meet any of criteria considerations A through G, it is ineligible for listing in the National Register of Historic Places. Moreover, the architectural and historical significance are not to the extent that the property would qualify for individual listing in the Colorado State Register of Historic Properties or as a City of Pueblo landmark. Given its age, the property should not be considered a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed in 1967, this office building exhibits a high level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. The only notable alteration has been the painting of the blue-brick panels and parapet.

VII.	/II. NATIONAL REGISTER ELIGIBILITY ASSESSMENT												
44.	National Re	egister eligibility field assessment:	■ Ind	(Not eligible					Need da	ata		
	Local landr	mark eligibility field assessment:	☐ Inc	(Not eligible					Need data			
45.	Is there Na	tional Register district potential?	Yes 🚁	No									
	Discuss: Pueblo's North Side Neighborhood represents the evolution of the city's professional middle and upper classes. Its diversity of architectural styles and forms directly represents the city's changing economic and cultural climates. As well, the neighborhood is distinctive because it appears to have evolved independently of the area's dominant industry, steel manufacturing.										of		
	If there is N	lational Register district potential, is t	his building cor	ntributing	:	Yes		No		N/A			
46.	If the buildi	ng is in existing National Register dis	trict, is it contril	buting:		Yes		No		N/A			

VIII. RECORDING INFORMATION

47. Photograph numbers): CD-ROM Photo Disc: North Side Photos

File Name(s): 15thstw405

Negatives filed at: Special Collections

Robert Hoag Rawlings Public Library

100 East Abriendo Avenue Pueblo, CO 81004-4290

48. Report title: Pueblo North Side Neighborhood Survey

49. Date(s): **07/18/05**

50. Recorder(s): Adam Thomas

51. Organization: Historitecture, L.L.C.

52. Address: **PO Box 419**


Estes Park, CO 80517-0419

53. Phone number(s): (970) 586-1165

(Resource number)

Architectural Inventory Form

Page 6




(Resource number)

Architectural Inventory Form

Page 7

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)