
COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

Official Eligibi (OAHP use onl	OAHF Rev. 9	
Date	Initials	
Determined	Eligible-National Register	
Determined	Not Eligible - National Register	
Determined	Eligible - State Register	
Determined	Not Eligible - State Register	
Need Data		
Contributing	to eligible National Register District	

525136004



I. IDENTIFICATION

Resource number: 5PE.5753 Parcel number(s):

2. Temporary resource number:

County: Pueblo
 City: Pueblo

5. Historic building name: MacIntyre, Remer Young and Mary Eva, House;

Playhouse Preschool

6. Current building name: Perez, Wilmer and Mirza, House

7. Building address: 700 W 17th Street

8. Owner name: Wilmer and Mirza Perez

Owner organization:

Owner address: 700 W 17th St

Pueblo, CO 81003

44.	National Register eligibility field assessment:	☐ Individually eligible	Not eligible	□ Need data
	Local landmark eligibility field assessment:	Individually eligible	Not eligible	■ Need data

Architectural Inventory Form

Page 2

II CEC	\mathcal{L}		INFOR	MATI	\cap NI
II. GEL	JURF	л піс	INCOR	יו ו איועו	UIN

P.M.: 6th Township: **20S** Range: 65W SW 1/4 SW NE 1/4 of Section 25 10. UTM reference zone: 13 533584 4237009 Northing: Easting: 11. USGS quad name: **Northeast Pueblo** Scale: 7.5 Year: 1961 (Photorevised 1970 and 1974) 12. Lot(s): Lots 1 and 2; Block 5 of Bartlett & Miller Addition. Also Lots 1 and 2; Block 18 of Craigs Addition Addition: **Bartlett & Miller Addition** Year of addition: 1871 Boundary description and justification: The boundary, as described above, contains but does not exceed the land historically associated with this property. Metes and bounds exist: П III. ARCHITECTURAL DESCRIPTION 14. Building plan (footprint, shape): Rectangular Plan Other building plan descriptions:

6. Number of stories: 1 1/2

Dimensions in feet (length x width):

io. Number of stories.

17. Primary external wall material(s): Brick Other wall materials:

1,320 square feet

Wood/Horizontal Siding

18. Roof configuration: Gabled Roof/Side Gabled Roof

Other roof configurations:

19. Primary external roof material: Wood Roof/Shingle Roof

Other roof materials:

15.

20. Special features: Chimney

Fence

Garage/Attached Garage

Porch

Roof Treatment/Dormer

21. General architectural description:

Oriented to the north, this house rests on a concrete foundation. Because this building is situated on a steep slope, the basement is fully exposed across the rear (south) elevation. On the east end of this elevation opens a 12-light, white-painted door, providing access to a brick patio. At the opposite end is an attached garage. It has a 6-panel, 12-light, wood garage door, painted black. A red, raked-brick veneer, made to resemble a 6-over-1 common bond, clads the exterior walls. White-painted, horizontal wood siding covers the north-facing dormers, and cream-painted, square-cut wood shingles cover the south-facing dormer. Windows are 6-over-6-light, double-hung sash, with white-painted wood frames. Those in the front (north) façade have flanking, black-painted, wood louvered shutters. The windows across the south-facing dormer are 1-over-1-light, double-hung sash. The principal doorway opens in the center of the symmetrical facade. It hosts a black-painted, 6-panel wood door. The doorway features sidelight and classical surround. Engaged chimneys and hearths protrude from the center of the side elevations. French doors (paired, 4-light) open in the north end of the west elevation. They provide access to a concrete patio, which is actually the roof of the attached garage. The patio is enclosed beneath a green, translucent fiberglass roof and behind

Architectural Inventory Form

Page 3

a fine plastic mesh. Black-stained wood shingles cover the side-gabled roof. Three front-gabled dormers protrude from the north-facing slope and a single shed-roof dormer dominates the south slope.

22. Architectural style:

Late 19th And 20th Century Revivals/Colonial Revival

Other architectural styles:

Building type:

23. Landscape or special setting features:

This property is located on terrain sloping steeply downward from northeast to southwest, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest, one- and two-story houses. Setbacks from West 17th Street are generally the same on this block. This property is situated on the southwest corner of West 17th and West streets. Separating the streets from the sidewalks is a grass-covered strip. A planted-grass yard, with lush, mature landscaping, covers the lot. Surrounding the back yard are chain-link and wood privacy fences. A macadam driveway connects the attached garage to the alley behind (south of) the house.

24. Associated buildings, features or objects:

No associated buildings identified.

IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: Actual: 1942

Source of Information: Pueblo County Office of Tax Assessor. Property information card [internet].

26. Architect: unknown

Source of information:

Builder: unknown

Source of information:

28. Original Owner: Remer Y. MacIntyre

Source of information: Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk &

Co, consulted 1886 through 2003.

29. Construction history:

According to Pueblo County Tax Assessor records, this building was constructed in 1942. An analysis of the style, materials, and historical records corroborates this date. The only notable alteration has been the construction of the rear (south-facing) dormer, which appears to date to after 1980.

30. Location: **original** Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Single Dwelling
32. Intermediate use(s): Single Dwelling
33. Current use(s): Single Dwelling
34. Site type(s): Residence

35. Historical background:

The first owner and resident of this house, constructed in 1942, was prominent Pueblo real estate broker Remer Young MacIntyre. He was born in Thomasville, Georgia, around 1889, and attended Auburn College. His wife, Mary Eva MacIntyre, was also born in Thomasville, Georgia, in 1893. They were married around 1917 and had a son, Archbold Thompson MacIntrye, IV. The MacIntyres arrived in Pueblo in 1919, when Remer opened the MacIntyre Manufacturing Company. He also appears to have sold automobiles before entering the real estate business around 1943. Mary MacIntyre operated the Playhouse Preschool out of this house for 32 years, retiring in 1962. Remer died on August 3, 1958; Mary remained here until her own death, on November 21, 1964.

Patricia D. Kelly purchased this property in 1970, selling it to Michael D. and Drucilla N. Pugh in 1984. In 1995, Steve and

Architectural Inventory Form

Page 4

Christine Arveschoug acquired the house and lot, selling them to Wilmer and Mirza Perez, the current owners and residents, in 2002.

Until after 1960, this house appears to have been addressed as 702 West 17th Street.

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

U.S. Census of 1930. Precinct 0, Pueblo, Pueblo County, Colorado. Sheet 8B.

"R.Y. MacIntyre Dies At Home." Pueblo Chieftain, 4 August 1958, p. 6.

"MacIntyre, Mary Eva" [obituary]. Pueblo Chieftain, 22 November 1964, p. 8B.

700 W 17th Street 5PE.5753

(Resource number)

Architectural Inventory Form

Page 5

VI.	SIGNIFIC	CANCE									
37	. Local	landmark designation	on: Yes		No						
	Desigr	nation authority:		_	,						
	Date o	of designation:									
38	. Applic	able National Regis	ter criteria:								
		A. Associated with B. Associated with			•			the broad patte	ern of our hist	tory.	
		C. Embodies the d of a master, or that components may la	t possess high a	artistic v	alues, d	pe, perio or represe	d, or method ents a signifi	d of construction icant and distin	on, or represe eguished entit	ents the work ty whose	
	9	D. Has yielded, or		•				ry or prehistory	' .		
	8	Qualifies under Cri Does not meet any			_		nanual).				
		Does not meet any	or the above iv	ational	rtogioto	i ontona.					
	Pueb	lo Standards for D	esignation:								
	2	1a. History Have direct asso	ciation with the	historica	al devel	opment o	f the city, st	ate, or nation;	or		
		1b. History									
		Be the site of a si	ignificant histori	c event	; or						
		1c. History									
		Have direct and s	ubstantial asso	ciation	with a p	erson or	group of per	rsons who had	influence on	society.	
	_	2a. Architecture	alita mala ana atao			L 11 1 1	-646				
		Embody distingui	shing character	istics of	r an arc	nitecturai	style or type	e; or			
		2b. Architecture Be a significant e	xample of the v	vork of a	a recogr	nized arch	nitect or mas	ster builder, or			
	_	2c. Architecture									
		Contain elements significant or influ			n, engin	eering, m	aterials, cra	ftsmanship, or	artistic merit	which represent a	a
	_	2d. Architecture									
		Portray the environments of the characterized by					developmer	nt of an area of	the city in ar	n era of history	
	_	3a. Geography									
		Have a prominen	t location or be	an esta	blished	, familiar,	and orienting	ng visual featur	e of the conte	emporary city, or	
		3b. Geography Promote understa or rarity; or	anding and app	reciatio	n of Pue	eblo's env	ironment by	means of dist	inctive physic	cal characteristics	
		3c. Geography									
		Make a special co	ontribution to P	ueblo's	distincti	ve charac	eter.				
	_	Not Applicable									
		Does not meet ar	ny of the above	Pueblo	landma	ırk criteria	l.				
39	9. Area(s)	of Significance:	Architecture	е							
40). Period o	of Significance:	1942								
41	I. Level of	significance:	National:	St	ate	Local					

(Resource number)

Architectural Inventory Form

Page 6

42. Statement of significance:

This property is historically significant under Pueblo Local Landmark criterion 1A for its association with the 20th century development of Pueblo's North Side Neighborhood, when the city's professional and entrepreneurial class moved northward to construct large homes, like this one, in the latest contemporary suburban styles. As well, the house is architecturally significant under National Register criterion C (Pueblo Local Landmark criterion 2A) as an example of the Colonial Revival. However, the levels of architectural and historical significance, combined with physical integrity, are not to the extent that this property would qualify for individual listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a City of Pueblo Landmark. It is, nonetheless, a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed in 1942, this house exhibits a moderately high level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. The only notable modification has been the construction of the rear dormer. This property retains sufficient physical integrity to convey its architectural and historical significance.

/II.	NATIONA	L REGISTER ELIGIBILITY A	SSESS	MEN	I											
44.	National Register eligibility field assessment:			Individually eligible					Not eligible					■ Need data		
	Local landmark eligibility field assessment:		☐ Individually eligible				Not eligible				Need data			a		
45.	Is there Na	tional Register district potential?	Yes		No											
	Discuss:	Pueblo's North Side Neighborho classes. Its diversity of architec cultural climates. As well, the no the area's dominant industry, st	tural sty eighborh	les and nood is	d forms disting	directly re	epresen	ts the	city	's ch	nangir	ng ec	onor	nic a		of
	If there is National Register district potential, is this			ing cor	ntributing	g:	Yes		No		N/A					
46.	6. If the building is in existing National Register district, is			contrib	outing:		Yes		No		N/A					

VIII. RECORDING INFORMATION

47. Photograph numbers): CD-ROM Photo Disc: North Side Photos

File Name(s): 17thstw700

Negatives filed at: Special Collections

Robert Hoag Rawlings Public Library

100 East Abriendo Avenue Pueblo, CO 81004-4290

48. Report title: Pueblo North Side Neighborhood Survey

49. Date(s): **07/26/05**

50. Recorder(s): Adam Thomas

51. Organization: Historitecture, L.L.C.

52. Address: **PO Box 419**


Estes Park, CO 80517-0419

53. Phone number(s): (970) 586-1165

Architectural Inventory Form

Page 7


SITE SKETCH MAP



Architectural Inventory Form

Page 8

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)