Official Eligibility Determination (OAHP use only)

OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

Date _	Initials
D	etermined Eligible-National Register
D	etermined Not Eligible - National Register
D	etermined Eligible - State Register
D	etermined Not Eligible - State Register
N	eed Data
C	ontributing to eligible National Register District
N	oncontributing to eligible National Register Distri



I. IDENTIFICATION

I. Resource number: 5PE.5756

2. Temporary resource number:

3. County: Pueblo4. City: Pueblo

5. Historic building name: Butz, William K., House
6. Current building name: Montoya, Frances L., House

Building address: 720 W 17th Street
 Owner name: Frances L. Montoya

Owner organization:

Owner address: 2 Trent Ct

Pueblo, CO 81005

44.	National Register eligibility field assessment:	☐ Individually eligible	Not eligible	□ Need data
	Local landmark eligibility field assessment:	Individually eligible	Not eligible	Need data

Parcel number(s):

525216003

(Resource number)

Architectural Inventory Form

Page 2

II.	GE	OGR	RAP	HIC IN	NFOF	RMA	TION													
ç	9.	P.M.:		6th			Tow	nship:	: :	20S			ı	Range:	65V	v				
			SE	1/4	of	NE	1/4	of	SE	1/4	of	NW	1/4	of	Section	25				
	10.	UTM	refer	ence z	one:		13													
		Easti	ng:				533512	2					Nortl	hing:		4237013				
•	11.	USG	S qua	ad nam	e:		Northe	ast P	ueblo)			Scal	e:		7.5				
		Year:					1961 (I 1974)	Photo	revis	ed 197	70 and	d								
•	12.	. Lot(s): West 27.92 fe								et of Lot 4 and the east 30.04 feet of Lot 5; Block						; Block 18				
		Addit	ion:				Craig's	s Add	ition				Year	of add	ition:	1871				
1	3.	Boun	dary	descrip	tion a	ınd ju	stificati	ion:												
		The b	ooun	dary, a	s des	cribe	ed abo	ve, co	ntain	s but	does	not e	xceed t	he land	d histori	cally associate	ed with t	his prop	erty.	
		Mete	es an	d boun	ds exi	st:														
III.	ΑF	RCHI	TEC	TUR	AL D	ESC	RIPT	ION												
1	4.	Buildi	ing p	lan (foc	tprint,	, shap	oe):		Re	ctangı	ular P	Plan								
		Other	r buil	ding pla	an des	cripti	ons:													
1:	5.	Dime	nsior	ns in fe	et (len	igth x	width)	-	896	squa	re fe	et								
1	6.	Numb	oer o	f stories	3:				1											
1	7.	Prima	ary e	xternal	wall m	nateri	al(s):		Stu	ICCO						Other wall r	materials	3:		
1	8.	Roof	confi	guratio	n:				Ga	bled F	Roof/S	Side G	abled	Roof						
		Other	r roof	config	uratio	ns:														
1	9.	Prima	ary e	xternal	roof m	nateri	al:		Ası	ohalt l	Roof/	Comp	osition	Roof						
		Other	r roof	materi	als:															
2	0.	Spec	ial fe	atures:					Fer	псе										
									Ch	imney	,									
									Po	rch										
2	1.	Gene	ral a	rchitect	ural d	escri	otion:													
		red-b wood princ roofe hosts porch	orowing sure in the sure in th	n-paint rounds doorwa ood, on -panel, ans the	ed, ve s. The ay. It I wood 1-ligl eentir	ertica stud hosts d kne ht, gl	Il wood co-cov a a whi ee brac ass-in- ir eleva	d sidii vered ite, 2- kets, wood ation.	ng. W sills a panel shelte I-fram It has	indoware property, 2-light ers the documents of the documents of the documents are consisted in the documents of the document	vs are ojecti ht, mo e doo or, pai ncrete	e 6-ove ing. O etal de or. And inted l e floor	er-6-lig pening por, op other de brown, r and si	ht, dou in the ening k oorway openir imple, s	ble-hung center of behind a gopens ng behing square,	ads the exterion g sash, with respect the symmetrical brown, aluming in the east ended an aluminum wood supports des from the control of the	ed-painte ical fron num-frar I of the r n-frame s. Browr	ed wood at (north) me storn ear (sou storm de a asphal	I frames and fragade is the door. And the levate oor. And the shingles to be a front oor. And the levate oor. And the levate oor. And the levate oor.	and thin s the shed- tion. It ed-roof s cover
2	2.	Archi	tectu	ral style	e:				No	Style	•									
		Other	r arch	nitectura	al styl	es:														
		Buildi	ing ty	vpe:					Ra	nch T	уре									
2	3.	Lands	scap	e or spe	ecial s	etting	g featui	res:												

(Resource number)

Architectural Inventory Form

Page 3

This property is located on terrain sloping downward from northeast to southwest, with an elevation of around 4,700 feet above mean sea level. The neighborhood features one- and two-story houses. Setbacks from West 17th Street are generally the same on this block. This property is situated on the south side of West 17th Street, between 719 West 17th Street to the east and 726 West 17th Street to the west. Separating the street from the sidewalk is a concrete strip. A planted-grass yard, with mature landscaping, covers the lot. Surrounding the backyard is a combination of wood privacy and chain-link fences.

24. Associated buildings, features or objects:

1: Type: Shed

Describe: A shed is located on the west side of the property, midway between the house and the alley.

Oriented to the east, the structure appears to lack a formal foundation. Unpainted plywood walls, with cornerboards, clad the exterior walls. Opening in the south side of the front (east) elevation is a plywood door. In the north side of the same elevation is a 1-beside-1-light, sliding sash window, with an aluminum frame. Brown asphalt shingles cover the front-gable roof, which projects outward slightly above the front elevation, creating a pseudo hay hood.

IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: Actual: 1947

Source of Information: Pueblo County Office of Tax Assessor. Property information card [internet].

26. Architect: Unknown

Source of information:

27. Builder: Unknown

Source of information:

28. Original Owner: William K. Butz

Source of information: Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk &

Co, consulted 1886 through 2003.

29. Construction history:

According to Pueblo County Tax Assessor records, this building was constructed in 1947. An analysis of the style, materials, and historical records corroborates this date. The only notable alterations have been the application of stucco over the original brick veneer and the construction of the rear porch. These modifications appears to date to after 1980.

30. Location: **original** Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Single Dwelling
32. Intermediate use(s): Single Dwelling
33. Current use(s): Single Dwelling
34. Site type(s): Residence

35. Historical background:

The first owner and resident of this house, constructed in 1947, was William K. Butz. He served in the U.S. Army during World War II and was an employee of Fisher's Grocery, from which he retired in 1971. With his wife, Ursula B. Butz, William had a son, Charles Butz. William Butz died on March 3, 1974.

Richard A. and Twila A. Cruz purchased this property in 1979. Bank Western Federal Savings Bank acquired the house and lot from Twila Cruz in 1985, selling them in 1986 to Robert J. Giebel. In 1988, Sandra S. and Patrick F. McKone acquired the property, selling it to Jerry and Laura Ann Griego in 1995. Mark I. and Angelica L. Chavez purchased the house and lot in 1995. Frances L. Montoya, the current owner and resident, acquired the property from the Chavezes in 1998.

36. Sources of information:

720 W 17th Street 5PE.5756 (Resource number)

Architectural Inventory Form

Page 4

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

"William K. Butz" [obituary]. Pueblo Chieftain, 5 March 1974, p. 10B.

(Resource number)

Architectural Inventory Form

Page 5

VI. S	IGNIFICANCE
37.	Local landmark designation: Yes ☐ No
	Designation authority:
	Date of designation:
38.	Applicable National Register criteria:
00.	A. Associated with events that have made a significant contribution to the broad pattern of our history. B. Associated with the lives of persons significant in our past.
	C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose components may lack individual distinction.
	D. Has yielded, or may be likely to yield, information important in history or prehistory.
	Qualifies under Criteria Considerations A through G (see manual).
	Does not meet any of the above National Register criteria.
	Pueblo Standards for Designation:
	1a. History
	Have direct association with the historical development of the city, state, or nation; or
	1b. History
	Be the site of a significant historic event; or
	1c. History
	Have direct and substantial association with a person or group of persons who had influence on society.
	2a. Architecture
	Embody distinguishing characteristics of an architectural style or type; or
	2b. Architecture
	Be a significant example of the work of a recognized architect or master builder, or
	 2c. Architecture Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a significant or influential innovation;
	2d. Architecture
	Portray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style.
	3a. Geography Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or
	3b. Geography
	Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or
	3c. Geography
	Make a special contribution to Pueblo's distinctive character.
	Not Applicable
	Does not meet any of the above Pueblo landmark criteria.
39.	Area(s) of Significance: Not Applicable
40.	Period of Significance: n/a
41.	Level of significance: National:

(Resource number)

Architectural Inventory Form

Page 6

42. Statement of significance:

This property is historically significant under Pueblo Local Landmark criterion 1a for its association with the post-World War II development of Pueblo's North Side Neighborhood. However, the levels of architectural and historical significance, combined with physical integrity, are not to the extent that this property would qualify for individual listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a City of Pueblo Landmark. Nonetheless, it is a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed in 1947, this house exhibits a moderately high level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. The only notable modifications have been the installation of stucco and the construction of the rear porch. This property retains sufficient physical integrity to convey its architectural and historical significance.

VII.	NATIONA	L REGISTER ELIGIBILITY A	SSESSMENT						
44.	National Ro	egister eligibility field assessment:	Individually eligible	2	Not eligible	,	■ Need data		
	Local landr	mark eligibility field assessment:	☐ Individually eligible		Not eligible	э	■ Need data		
45.	Is there Na	ational Register district potential?	Yes 🐼 No 🗖						
	Discuss: Pueblo's North Side Neighborhood represents the evolution of the city's professional middle and upper classes. Its diversity of architectural styles and forms directly represents the city's changing economic and cultural climates. As well, the neighborhood is distinctive because it appears to have evolved independent the area's dominant industry, steel manufacturing.								
	If there is N	National Register district potential, is t	this building contributing:	Yes	No 🗖	N/A			
46.	If the buildi	ing is in existing National Register dis	strict, is it contributing:	Yes	No 🗖	N/A			

VIII. RECORDING INFORMATION

47. Photograph numbers): CD-ROM Photo Disc: North Side Photos

File Name(s): 17thstw720

Negatives filed at: Special Collections

Robert Hoag Rawlings Public Library

100 East Abriendo Avenue Pueblo, CO 81004-4290

48. Report title: Pueblo North Side Neighborhood Survey

49. Date(s): **07/26/05**

50. Recorder(s): Adam Thomas

51. Organization: Historitecture, L.L.C.

52. Address: **PO Box 419**

Estes Park, CO 80517-0419


53. Phone number(s): (970) 586-1165

720 W 17th Street 5PE.5756
(Resource number)

Architectural Inventory Form

Page 7

SITE SKETCH MAP




(Resource number)

Architectural Inventory Form

Page 8

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)