5PE.516.19

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

Official Eligibility Determination	
OAHP use only)	

OAHP1403 Rev. 9/98

(OAIII C	3C Offig)
Date	Initials
Dete	mined Eligible-National Register
Dete	mined Not Eligible - National Register
Dete	mined Eligible - State Register
Dete	mined Not Eligible - State Register
Need	Data
Cont	ibuting to eligible National Register District
Nonc	ontributing to eligible National Register Distric

Parcel number(s):

525150006



I. IDENTIFICATION

I. Resource number: 5PE.516.19

2. Temporary resource number:

3. County: Pueblo4. City: Pueblo

5. Historic building name: Lucas, Dr. Wilbur, House; Johnston, J. Will, House;

Clevenger, Mac V., House

6. Current building name: Horton-Rogers House7. Building address: 409 W 18th Street

8. Owner name: Keith Horton and Jennifer Rogers

Owner organization:

Owner address: 409 W 18th St

Pueblo, CO 81008

(Resource number)

Architectural Inventory Form

Page 2

II. GI	EOGF	RAPH	IIC IN	IFOF	RMA	ATION	l								
9.	P.M.:	: 6	ith			Tow	nship): 2	20S			R	ange:	65W	ı
		NE	1/4	of	NE	1/4	of	SW	1/4	of	NE	1/4	of Se	ction	25
10.	UTM	refere	ence zo	one:		13									
	Easti	ng:				533952	2					Northi	ng:		4237161
11. USGS quad name: Northeast I				ast F	Pueblo	ueblo Scale:						7.5			
	Year: 1961 (Photo 1974)						Photo	orevis	ed 197	0 and	d				
12.	Lot(s):				East 9	feet	3 inch	es of I	Lot 1	3 and	all of Lo	ts 14 an	Block 16	
	Addit	ion:				Bartlet	t & N	/liller /	dditio	n		Year o	of additio	n:	1871
13.	Boun	dary o	descrip	tion a	nd ju	ıstificati	ion:								
	The I	bound	lary, a	s des	crib	ed abo	ve, c	ontain	s but	does	not e	xceed th	e land h	istorio	cally associated with this property.
	Mete	es and	d bound	ds exi	st:										
III. A	RCHI	TEC	TUR	AL D	ESC	CRIPT	ION	l							
14.	Build	ing pla	an (foo	tprint,	sha	pe):		Re	ctangu	ılar P	Plan				
	Othe	r build	ing pla	an des	cript	ions:									
15.	Dime	ension	s in fee	et (len	gth x	width):		2,435 square feet							
16.	Numl	ber of	stories	3:				2							
17.	Prima	ary ex	ternal	wall m	nateri	al(s):		Stu	ссо						Other wall materials:
18.	Roof	config	guratio	n:				Hip	ped R	oof					
	Othe	r roof	configu	uration	ns:										
19.	Prima	ary ex	ternal	roof m	nater	ial:		Ter	ra Cot	ta Ro	oof				
	Othe	r roof	materi	als:											
20.	Spec	ial fea	tures:												
								Ch	mney						
								Poi	ch						

21. General architectural description:

Oriented to the south, this house rests on a concrete foundation. White stucco clads the exterior walls. Windows are generally 1-over-1-light, double-hung sash, with green-painted wood frames and projecting, stucco-covered sills. Those opening in the first story of front (south) façade and the southern portion of the west elevation's first story have round-arch upper sashes. Other windows are single-light casement. The windows spanning a single-story room, protruding from the west elevation, feature divided-light casements, sidelights, and transoms, all beneath round arches. A porch spans the façade from the center to the eastern end. It has a red, terra-cotta tile floor and a green-painted, elaborately turned balustrade. The eastern portion of the porch features an arcade. Five brick steps approach the porch on the west end of its south elevation. Flanking it are black, wrought-iron railings. The principal doorway opens in the center of the façade. It hosts a 1-panel, 1-light oak door, with beveled glass. It opens behind an oak-frame screen door. Another doorway opens directly above this one, in the second story. It hosts a single-light, white-painted slab door. It provides access to a central balcony, with a scroll-cut wood balustrade mimicking to the front porch railing. The balcony continues to the east and west, behind the curvilinear parapets, which are highlighted with coping. Another doorway opens beneath a round arch in the south elevation of a single-story room protruding from the north half of the west elevation. It is a green-painted, vertical plank door, with 4 lights. It opens behind a wood-frame screen door. Approaching it are 6 brick steps. Opening in the rear (north) elevation is another doorway. Above it is an enclosed, sleeping porch. Green terra cotta tiles cover the centrally hipped main roof and all other roof surfaces. The shaped rafter ends are

(Resource number)

Architectural Inventory Form

Page 3

exposed beneath the broadly overhanging eaves. Stucco-clad chimneys protrude from the southeast and southwest corners and from the roof's east-facing slope.

22. Architectural style:

Late 19th And 20th Century Revivals/Mission

Other architectural styles:

Building type:

23. Landscape or special setting features:

This property is located on terrain sloping downward from west to east, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest and large, one- and two-story houses. Setbacks from West 18th Street are generally the same on this block. This property is situated on the north side of West 18th Street, between 401 West 18th Street to the east and 419 West 18th Street to the west. Separating the street from the sidewalk is a grass strip. A planted-grass yard, with mature landscaping, covers the lot. Surrounding the backyard is a stucco-clad wall. A concrete driveway runs along the west side of the house, connecting the garage to West 18th Street.

24. Associated buildings, features or objects:

1: Type: Garage

Describe: A 2-car garage is located on the northwest corner of this property. Oriented to the south, the

building rests on a concrete foundation. White stucco clads the exterior walls. Dominating the front (south) elevation is a 2-car, wood, overhead pivot type garage door, painted green. At the eastern end of this door is an integral, pedestrian door. Sheltering this doorway is a small, hipped roof, covered in green terra cotta tiles and supported on exposed rafters. Capping the front elevation is a shaped parapet with a niche at its apex. The rear (south) elevation has a

pair of window openings. Gray sheets of asphalt cover the shed roof.

2: Type: Pergola

Describe: A pergola is located directly north of the house, along the northern edge of the property. It

consists of a green-painted wood frame and flat roof. The north elevation has a stucco-covered

wall.

IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: Actual: 1914

Source of Information: Pueblo County Office of Tax Assessor. Property information card [internet].

26. Architect: George W. Roe

Source of information: Munch, J. Colorado Cultural Resource Survey, Architectural/Historical Component Form (no.

618), August 1981.

27. Builder: Frank C. Tribebes

Source of information: Munch, J. Colorado Cultural Resource Survey, Architectural/Historical Component Form (no.

618), August 1981.

28. Original Owner: Dr. Wilbur Lucas

Source of information: Pueblo City Directory, Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk &

Co, consulted 1886 through 2003.

29. Construction history:

According to Pueblo County Tax Assessor records, this building was constructed in 1914 from a design by prominent Pueblo architect George W. Roe. An analysis of the style, materials, and historical records corroborates this date. This house has not been significantly altered since its construction by Frank C. Tribebes

30. Location: original Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Single Dwelling

(Resource number)

Architectural Inventory Form

Page 4

31.	Original use(s):	Single Dwelling
32.	Intermediate use(s):	Single Dwelling
33.	Current use(s):	Single Dwelling
34.	Site type(s):	Residence

35. Historical background:

The first owner and resident of this house, constructed in 1914, was Pueblo physician Dr. Wilbur Lucas, a surgeon for the Colorado Fuel & Iron Company, later the CF&I Steel Corporation. He also served in the medical corps during World War I. Dr. Lucas was born on June 22, 1873, in Indiana. His wife, Edith J. Lucas, was born in Kansas around 1888. They had at least two children, Edith M. and Mary M. Lucas. The family remained here through 1925.

Around 1930, industrial investment broker J. Will Johnston purchased this property and resided here until his death a few years later. He was born around 1862 in Ohio. His wife, Clara M. Johnston, was also born in Ohio, around 1866. They resided here with a live-in domestic servant, Edith Owens. J. Will Johnston died in 1934. His widow, Clara, continued to reside here through at least 1935. She died on December 14, 1965.

Mac V. Clevenger purchased this property around 1940 and resided here until his death more than 4 decades later. He was born on April 6, 1888, in Utica, Kansas, moving to Pueblo in 1914. Clevenger initially worked as a cowboy on a ranch near Arlington, Colorado. Then, in 1917, he started selling used automobiles, opening a Dort dealership in 1919. From 1920 until 1928, he was the Pueblo dealer for Durant and Star automobiles. Clevenger operated a Plymouth and DeSoto dealership from 1928 to 1935. From that time until his retirement in July 1959, he owned the Chrysler-Plymouth dealership at the corner of 7th Street and Santa Fe Avenue. After his retirement, he spent his time operating ranches in Siloam, Westcliffe, and Kansas. He was an organizing member of the Turkey Creek Soil Conservation District, of which he was a president.

On July 11, 1940, Mac Clevenger married Maurine A. Baker in New Mexico. Mac had a daughter, Marilyn Wilgus, and a step-son, Gene Good. Mac Clevenger died on March 9, 1982. Maurine Clevenger remained the owner of this property until her death on August 7, 2000. In 2001, her estate sold the house and lot to Keith Horton and Jennifer Rogers, the current owners and residents.

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

"Johnston (Clara M.)" [obituary]. Pueblo Chieftain, 16 December 1965, p. 7C.

"Mac V. Clevenger" [obituary]. Pueblo Chieftain, 11 March 1982, p. 10B.

U.S. Census of 1920. Precinct 2, Pueblo, Pueblo County, Colorado. Sheet 6A.

U.S. Census of 1930. Precinct 37, Pueblo, Pueblo County, Colorado. Sheet 4B.

World War I Draft Registration Card for Wilbur Lucas, Serial No. 1510, Order No. 1255.

Architectural Inventory Form

Page 5

VI.	SIGNIFI	CANCE								
37	. Loca	I landmark designati	on: Yes	☐ No	a					
	Desi	gnation authority:	•	<u> </u>	_					
	Date	of designation:								
38	. Appli	cable National Regis	ster criteria:							
		B. Associated with C. Embodies the c of a master, or tha components may b D. Has yielded, or Qualifies under Cr	events that have made a significant contribution to the broad pattern of our history. the lives of persons significant in our past. istinctive characteristics of a type, period, or method of construction, or represents the work to possess high artistic values, or represents a significant and distinguished entity whose ack individual distinction. may be likely to yield, information important in history or prehistory. teria Considerations A through G (see manual).							
	Pue	blo Standards for I	Designation:							
		1a. History Have direct associated for the site of a second for the site of a second for the site of a second f	ciation with the his significant historic substantial associ ishing characteris example of the wo	event; or ation with a p ics of an arc	person or gro hitectural st	oup of persons of the sect or master but	who had influence o	on society. rit which represent a		
	0	characterized by	onment of a group a distinctive archi			evelopment of a	n area of the city in	an era of history		
		3a. Geography Have a prominer	nt location or he ar	established	familiar a	nd orienting view	ual feature of the co	ntemporary city, or		
	0	3b. Geography				-		sical characteristics		
		3c. Geography Make a special o	ontribution to Pue	blo's distincti	ve characte	ır.				
	0	Not Applicable Does not meet a	ny of the above P	ueblo landma	ark criteria.					
3	_) of Significance:	Social History Architecture	′						
4	0. Period	of Significance:	Social History	1914-1955:	Architectu	re, 1914				
		of significance:	National:	Q	Local					

Architectural Inventory Form

Page 6

42. Statement of significance:

This property is significant under National Register Criterion A (Pueblo Local Landmark Criterion 1A--history) for its association with the 20th-century development of Pueblo's North Side Neighborhood, when the city's professional and entrepreneurial class moved northward to construct large homes, like this one, in the latest contemporary suburban styles. This house was home to three notable Pueblo professionals, surgeon Dr. Wilbur Lucas, investment broker J. Will Johnston, and automobile dealer Mac V. Clevenger. The property is also significant under Local Landmark Criterion 2A (important individuals) for its association Lucas, Johnston, and Clevenger, who were all civic leaders. As well, the house is significant under National Register Criterion C (Local Landmark Criteria 2A and 2B--architecture) as an outstanding example of the Mission style. Character-defining features include the curvilinear-shaped parapet with coping; round-arch windows; a heavy tile roof; an arcaded porch; and a stucco finish. As well, it is one of the few houses in the North Side known to have been designed by architect George W. Roe, whose other commissions include the library at the University of Colorado, at Boulder, and buildings at the Colorado School of Mines, at Golden. The levels of architectural and historical significance, combined with physical integrity, are to the extent that this property could qualify for individual listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a City of Pueblo Landmark. It is most likely a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed in 1914, this house exhibits a high level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. It has not been notably altered since its construction. This property retains sufficient physical integrity to convey its architectural and historical significance.

VII.	II. NATIONAL REGISTER ELIGIBILITY ASSESSMENT												
44.	National Re	gister eligibility field assessment:	Individually eligible		Not eligible	le Need data							
	Local landm	ark eligibility field assessment:	Individually eligible		Not eligibl	le Need data	Need data						
45.	Is there Nati	ional Register district potential?	Yes 🔊 No 🗖										
	Discuss:	Pueblo's North Side Neighborho classes. Its diversity of architec cultural climates. As well, the no the area's dominant industry, st	tural styles and forms directly r eighborhood is distinctive beca	epresents th	ne city's c	changing economic and							
	If there is Na	ational Register district potential, is	this building contributing:	Yes 🕝	No 🗖	N/A							
46.	If the buildin	g is in existing National Register dis	strict, is it contributing:	Yes	No 🗖	N/A							

VIII. RECORDING INFORMATION

47. Photograph numbers): CD-ROM Photo Disc: North Side Photos

File Name(s): 18thstw409

Negatives filed at: Special Collections

Robert Hoag Rawlings Public Library

100 East Abriendo Avenue Pueblo, CO 81004-4290

48. Report title: Pueblo North Side Neighborhood Survey

49. Date(s): **07/26/05**

50. Recorder(s): Adam Thomas

51. Organization: Historitecture, L.L.C.

52. Address: PO Box 419

Estes Park, CO 80517-0419


53. Phone number(s): (970) 586-1165

(Resource number)

Architectural Inventory Form

Page 7

SITE SKETCH MAP




(Resource number)

Architectural Inventory Form

Page 8

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)