COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

This survey form represents an UNOFFICIAL COPY and is provided for informational purposes only. All information, particularly determinations of eligibility for the National Register, the State Register, or as a local landmark, can and will change. Please contact the Colorado Historical Society Office of Archaeology and Historic Preservation for an official copy of this document.



I. IDENTIFICATION

1.	Resource number:	5PE.6605			P	arcel number:	525118017
2.	Temporary resource number:						
3.	County:	Pueblo					
4.	City:	Pueblo					
5.	Historic building name:	Earl V. Voris House					
6.	Current building name: Mark W. and Carolyn A. Lowrey House						
7.	Building address:	203 West 19	9th Street				
8.	Owner name:	Mark W. and	d Carolyn A. Lowrey Ho				
	Owner organization:						
	Owner address:	203 W 19th	St				
		81003					
44.	National Register eligibility field assessment: State Register eligibility field assessment: Local landmark eligibility field assessment:		☐ Individually eligible	☑ Not eligible	☐ Need data	☐ Previously I	isted
			☐ Individually eligible	_		_	
			☐ Individually eligible				
	3		, ,				

Architectural Inventory Form

5PE.6605 UNOFFICIAL COPY

Page 2

II. GEOGRAPHIC INFORMATION

9. P.M.: **6th** Township: **20S** Range: **65W**

NE 1/4 SE 1/4 NE 1/4 NE 1/4 of section 25

10. UTM Reference Zone: 13

Easting: 534230 Northing: 4237294

11. USGS quad name: Northeast Pueblo Scale: 7.5

Year: 1961 (Photorevised 1970 and 1974)

12. Lot(s): East 63 feet Lots 17 through 20; Block 21

Addition: Barndollar & Company Second Addition Year of addition: 1871

13. Boundary description and justification: The boundary, as described above, contains but does not exceed the land historically associated with this property.

■ Metes and bounds exist

III. ARCHITECTURAL DESCRIPTION

14. Building Plan (footprint, shape): Irregular Plan

Other building plan descriptions:

15. Dimensions in feet: 1,782 square feet

16: Number of stories: 1 1/2

17: Primary external wall material(s): Stucco

Other wall materials:

18: Roof configuration: Flat Roof

Other roof configuration:

19: Primary external roof material: Synthetic Roof/Rubber Roof

Other roof materials:

20: Special features: Chimney

Fence

Garage/Attached Garage

21: General architectural description:

Oriented to the south, this house rests on a concrete foundation. Light-blue stucco clads the exterior walls. The corners of the wing protruding from the west end of the asymmetrical front (south) facade are rounded. Spanning eastward from this wing and wrapping around a southeast-facing corner is a pent roof, covered in wood shingles. Windows are generally 1-over-1-light, double-hung sash, with white vinyl frames and blue-painted wood surrounds. The protruding wing hosts a single-light picture widow. Opening in either face of the southeast-facing corner, west of the main entrance, are casement windows with steel frames. The principal doorway opens within a deep recess near the east end of the facade. It hosts a blue-painted wood slab door, with a frosted-glass sidelight to the east. Approaching the recess from the east are wide, concrete steps. A secondary doorway opens in the east elevation of a single-story structure connecting the house to the two-story garage to the north. It provides access to a concrete stoop and is sheltered beneath a pent roof with wood shingles. The east elevation hosts a pair of single-car, 16-panel, overhead-pivot type garage doors, painted light blue and constructed of wood. A stucco-covered hearth and chimney are engaged to the east end of the facade. Another hearth and chimney, constructed of red bricks, is engaged to the south elevation of the two-story garage. A rubber membrane covers the flat roof.

22. Architectural style: No Style

Other architectural style:

Building type:

23. Landscape or special setting features:

This property is located on terrain sloping downward from west to east, with an elevation of around 4,700 feet above mean sea level. This residential neighborhood features modest and large, 1- and 2-story houses. Mineral Palace Park is located directly across West 19th Street. Setbacks from West 19th Street are generally the same on this block. This property is situated on the northwest corner of West 19th and North Main streets. The sidewalk parallel to West 19th Street consists of red bricks, set in a herringbone pattern; the sidewalk along Main Street is concrete. Separating the streets from the sidewalks are grass-covered strips, with large junipers planted in the West 19th Street strip. A planted-grass yard, with lush, mature landscaping, covers the lot. Concealing the southeast corner of the house and the area

Architectural Inventory Form

5PE.6605 UNOFFICIAL COPY

Page 3

between the house and garage are wood privacy fences.

24. Associated building, features or objects:

There are no other buildings associated with this property.

IV. ARCHITECTURAL HISTORY

25. Date of Construction: 1943 ☒ Actual ☐ Estimate

Source of information: Pueblo County Assessor Property Profile.

26. Architect: Unknown

Source of information:

27. Builder: Unknown

Source of information:

28. Original Owner: Earl V. Voris

Source of information: Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co.,

consulted 1886 through 2003.

29. Construction history:

According to Pueblo County tax assessor records, this house was constructed in 1943. An analysis of the style, materials, and historical records corroborates this date. This appears to have originally been Art Moderne in style, suggested by the rounded corners and flat roof, and lacked the two-story garage. According to Sanborn maps and structural evidence, a single-car garage was attached to the east elevation. It is now enclosed. Sometime after 1970, the house gained the two-story garage, pent roofs, and other modifications.

30. Location: Original Location Date of move(s):

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Domestic/Single Dwelling
32. Intermediate use(s): Domestic/Single Dwelling
33. Current use(s): Domestic/Single Dwelling

34. Site type(s): **Residence**

35. Historical background:

The first owner and resident of this house, built in 1943, was Earl V. Voris, with his wife, Mildred A. Voris. Both Earl and Mildred were natives of Colorado; he was born around 1903 while she was born circa 1910. They were married around 1930 and had a son, Theodore Voris. Earl Voris had been a teacher in Ault, Weld County, Colorado in the 1930s, before moving to Pueblo and teaching in the city's public schools. The family moved from here prior to 1950.

Dr. John T.F. and Elizabeth C. Barwick were the residents of this house in 1950. During this time, Dr. Barwick served as a physician at St. Mary-Corwin Hospital.

In 1960, Thomas A. and Margaret Brown lived here. Thomas worked as the area manager for the Sarah Coventry Company, a shop-at-home mail order company.

Edwin D. and N. Lynn Strachan lived here from about 1965 until 1978, when current owners and residents Mark W. and Carolyn A. Lowrey purchased the property.

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card. [internet]

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co., consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

U.S. Census of 1930. Precinct 35, Ault, Weld County, Colorado. Sheet 2A.

Architectural Inventory Form Page 4

5PE.6605 **UNOFFICIAL COPY**

VI. SIGNIFICANC	E
-----------------	---

37.	Local landmark designation: Yes 🛮 No							
	Designation authority:							
	Date of designation:							
38.	Applicable National Register criteria: A. Associated with events that have made a significant contribution to the broad patterns of our history.							
	☐ B. Associated with the lives of persons significant in our past.							
	☐ C. Embodies the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or							
	that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual							
	distinction.							
	☐ D. Has yielded, or may be likely to yield, information important in prehistory or history.							
	☐ Qualifies under Criteria Considerations A through G (see manual).							
	☐ Does not meet any of the above National Register criteria.							
	Applicable Colorado State Register criteria:							
	A. Associated with events that have made a significant contribution to history.							
	☐ B. Connected with persons significant in history.							
	☐ C. Has distinctive characteristics of a type, period, method of construction or artisan.							
	D. Is of geographic importance.							
	☐ E. Contains the possibility of important discoveries related to prehistory or history.							
	Does not meet any of the above Colorado State Register criteria.							
	Applicable City of Pueblo landmark criteria:							
	■ 1a. History: Have direct association with the historical development of the city, state, or nation; or							
	1b. History: Be the site of a significant historic event; or							
	1c. History: Have direct and substantial association with a person or group of persons who had influence on society.							
	2a. Architecture: Embody distinguishing characteristics of an architectural style or type; or							
	2b. Architecture: Be a significant example of the work of a recognized architect or master builder, or							
	2c. Architecture: Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which							
	represent a significant or influential innovation;							
	2d. Architecture: Portray the environment of a group of people or physical development of an area of the city in an era of history							
	characterized by a distinctive architectural style.							
	3a. Geography: Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or							
	3b. Geography: Promote understanding and appreciation of Pueblo's environment by means of distinctive physical							
	characteristics or rarity; or							
	☐ 3c. Geography: Make a special contribution to Pueblo's distinctive character. ☐ Does not meet any of the above City of Pueblo landmark criteria.							
	LI DUES HUL HIEEL AHV ULLIE ADUVE CILV UL PUEDIU IAHUHIALK CHIEHA.							

39. Areas of significance: Social History 40. Period(s) of Significance: 1943-1958


Architectural Inventory Form Page 5

5PE.6605 **UNOFFICIAL COPY**

41.	Level of Significance:	National 🔲 Sta	te 🛚 Local							
42.	Statement of Significance:									
43	This property is historically so North Side Neighborhood, wholarge homes in the latest conhouse is unable to convey its listing in the National Register Pueblo Landmark. It should in Assessment of historic physical	en the city's p temporary sub historical and er of Historic F not be consider	rofessional and ei urban styles. Hov architectural sig Places, the Colora ed a contributing	ntrepreneu vever, beca nificance. T do State Re	rial class use of its This prope egister of	continu low leve erty wou Historic	ed to coel of phy ald not o	Instruct manual resical intequality for ties, or as	nodest and grity, this individual	
	Constructed in 1943, this ho	0 0	· ·	l integrity	relative to	the se	ven aspe	ects of int	egrity as	
	defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. Alterations dating to after 1970 have significantly altered the form and style o this house. This building does not retain sufficient physical integrity to convey its historical and architectural significance.								ials, n and style of	
VII. NA	ATIONAL REGISTER ELIGIB	ILITY ASSES	SMENT							
44.	National Register eligibility field State Register eligibility field ass Local landmark eligibility field as	sessment:	☐ Individually elig☐ Individually elig☐ Individually elig☐ Individually elig	ible 🛮 Not	eligible [Need	data 🔲	Previously	y listed	
45.	Is there National Register distric	t potential:	☑ Yes ☐ No							
	Discuss: Pueblo's North Side Neighborhood represents the evolution of the city's professional middle and upper classes. Its diversity of architectural styles and forms directly represents the city's changing economic and cultural climates. As well, the neighborhood is distinctive because it appears to have evolved independently of the area's dominant industry, steel manufacturing.									
	If there is National Register distr	ict potential, is t	his building contrib	outing:	☐ Yes	⊠ No	□ N/A			
46.	. If the building is in existing National Register district, is it contributing:			ng:	☐ Yes	□No	⊠ N/A			
∕III. R	ECORDING INFORMATION									
47.	Digital photograph file name(s):	19thstw203 -	1 to - 4							
	Digital photographs filed at:	ographs filed at: Robert Hoag Rawlings Public Library 100 E Abriendo Ave Pueblo, CO 81004-4290								
48.	Report title:	Pueblo North	Side Neighborhoo	od Survey, 1	Phase 2					
49.	Date(s):	1/31/2008								
50:	Recorder(s):	Adam Thoma	s and Jeffrey DeH	Ierrera						
51:	Organization:	Historitectur	e, LLC							
52:	Address:	PO Box 419								
53:	Phone number(s):	Estes Park, C (970) 586-116	0 80517-0419 35							


Page 6

SKETCH MAP



Page 7

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo - 1961 (Photorevised 1970 and 1974)