5PE.5798

# COLORADO CULTURAL RESOURCE SURVEY


# **Architectural Inventory Form**

Page 1

(OAHP use	Rev. 9/98	
Date		
Determine	ed Eligible-National Register	
Determine	ed Not Eligible - National Register	
Determine		
Determine	ed Not Eligible - State Register	
Need Dat	a	
Contributi	ng to eligible National Register District	

Parcel number(s):

525413006



### I. IDENTIFICATION

I. Resource number: 5PE.5798

2. Temporary resource number:

3. County: Pueblo4. City: Pueblo

Historic building name: Sands, Harry C, House
 Current building name: Gartner Law Office
 Building address: 1318 Court Street

8. Owner name: Michael D. and Priscilla J. Gartner

Owner organization:

Owner address: 1318 Court St

Pueblo, CO 81003

44.	National Register eligibility field assessment:	☐ Individually eligible	Not eligible	☐ Need data
	Local landmark eligibility field assessment:	☐ Individually eligible	Not eligible	■ Need data

# **Architectural Inventory Form**

Page 2

II. GEOGRAPHIC INFORMATION	II.	GEOGR/	APHIC	INFORM	//ATION
----------------------------	-----	--------	-------	--------	---------

9. F	P.M.: <b>6th</b>	Township:	20S		R	ange:	65W		
	<b>NE</b> 1/4 of <b>NV</b>	<b>V</b> 1/4 of	<b>NE</b> 1/4	of SE	1/4	of Sec	etion <b>25</b>		
10. l	UTM reference zone:	13							
ſ	Easting:	534155			North	ing:	4236729		
11. l	USGS quad name:	Northeast Pu	ieblo		Scale	:	7.5		
`	Year: 1961 (Photorevised 1970 and 1974)								
12. L	Lot(s):	North 70 feet Block 10	of the wes	t 40 feet	of Lot 7 a	nd the no	orth 70 feet of Lot 8;		
A	Addition:	County Addi	tion		Year	of addition	n: <b>1869</b>		
13. E	Boundary description and ju	ustification:							
7	The boundary, as describ	ed above, co	ntains but o	does not	exceed th	e land hi	storically associated w	vith this property.	
	Metes and bounds exist:								
II. AR	I. ARCHITECTURAL DESCRIPTION								
14. E	Building plan (footprint, sha	ipe):	L-Shaped	l Plan					
(	Other building plan descrip	tions:							
15. [	Dimensions in feet (length	x width):	1,608 squ	are feet					
16. N	Number of stories:		1						
17. F	Primary external wall material(s): Brick Stucco						Other wall mate	erials:	
18. F	Roof configuration:		Gabled R	oof/Cros	s Gabled	Roof			
(	Other roof configurations:								
19. F	Primary external roof mater	rial:	Asphalt R	Roof/Com	position	Roof			
(	Other roof materials:								
20.	Special features:		Car Port						
			Chimney						

21. General architectural description:

Oriented to the west, this building rests on a concrete foundation. A brown-orange brick veneer clads lower half of the exterior walls. Buff-colored stucco covers the remainder of the wall surface. Windows are single-light fixed frame, with gray wood surrounds. The rear (east) elevation hosts tripartite, aluminum-frame windows, with the end lights opening as sashes. A front-gabled porch spans the façade. It has a concrete floor and gray-painted, wrought-iron supports. A single, concrete step approaches the porch on the north end of its west elevation. The principal doorway opens in the north end of the façade. It hosts a 9-panel, 3-light wood door, with leaded, beveled-glass glazing, opening behind a brown, aluminum-frame storm door. Flanking it are frosted-glass sidelights. A side-gabled, 2-car carport extends southward from the south elevation. It has wrought-iron supports. A doorway opens in the center of the south elevation, into the carport. A small, stucco-covered roof, separate from the main building but contained beneath the carport roof, is located at the southeast corner. Its west elevation hosts a single-light wood slab door. An orange-brown engaged chimney, with integral planter, protrudes from the west end of the north elevation. Gray, interlocking asphalt shingles cover the cross-gabled roof, and gray-painted wood fascia and soffit box the eaves.

22. Architectural style: Modern Movements

(Resource number)

### **Architectural Inventory Form**

Page 3

Other architectural styles:

Building type: Ranch Type

23. Landscape or special setting features:

This property is located on terrain sloping downward from west to east, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest and large houses and high-rise hospital and apartment buildings. Setbacks from Court Street are generally the same on this block. This property is situated on the southeast corner of Court and West 14th streets. Separating the street from the sidewalk is a grass-covered strip. A planted-grass yard, with mature landscaping, covers the lot. Encircling the southeast corner of the yard is a wood privacy fence. A concrete driveway runs along the south side of the house, connecting Court Street to the car port.

24. Associated buildings, features or objects: No associated buildings identified.

#### IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: Actual: 1964 (original)

Source of Information: Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk &

Co, consulted 1886 through 2003.

26. Architect: unknown

Source of information:

27. Builder: unknown

Source of information:

28. Original Owner: Harry C. Sands

Source of information: Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk &

Co, consulted 1886 through 2003.

29. Construction history:

According to Pueblo County Tax Assessor records, this building was constructed in 1984. However city directory listings for this address date to 1964. This building was extensively remodeled during its conversion into an office building, in 2003. The most notable alteration has been the replacement of most windows and installation of entirely new windows.

30. Location: original Date of move(s):

#### V. HISTORICAL ASSOCIATIONS

31. Original use(s): Single Dwelling
32. Intermediate use(s): Single Dwelling
33. Current use(s): Professional
34. Site type(s): Law Offices

35. Historical background:

The first owner and resident of this house, constructed in 1964, was Harry C. Sands. He died in 1969, but his widow, Nina I. Sands, continued to live here through at least 1984. The R.R. West Family Trust acquired the property in 1987, selling it to Michael D. and Priscilla J. Gartner, the current owners, in 2003. The former dwelling now houses their Gartner Law Office.

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

# **Architectural Inventory Form**

Page 4

ı. Sı	IGNIFICANCE											
37.	Local landmark designation: Yes No											
	Designation authority:											
	Date of designation:											
38.	Applicable National Register criteria:											
	A. Associated with events that have made a significant contribution to the broad pattern of our history.  B. Associated with the lives of persons significant in our past.	·										
	C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguished entity whose components may lack individual distinction.											
	D. Has yielded, or may be likely to yield, information important in history or prehistory.											
	Qualifies under Criteria Considerations A through G (see manual).											
	Does not meet any of the above National Register criteria.											
	Pueblo Standards for Designation:											
	1a. History											
	Have direct association with the historical development of the city, state, or nation; or											
	1b. History  Be the site of a significant historic event; or											
	1c. History											
	Have direct and substantial association with a person or group of persons who had influence on society.											
	2a. Architecture											
	Embody distinguishing characteristics of an architectural style or type; or	Embody distinguishing characteristics of an architectural style or type; or										
	<u>2b. Architecture</u>											
	Be a significant example of the work of a recognized architect or master builder, or	Be a significant example of the work of a recognized architect or master builder, or										
	<ul> <li>2c. Architecture</li> <li>Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a significant or influential innovation;</li> </ul>	Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a										
	<ul> <li>2d. Architecture</li> <li>Portray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style.</li> </ul>											
	3a. Geography  Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or											
	3b. Geography											
	Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or											
	3c. Geography	3c. Geography										
	Make a special contribution to Pueblo's distinctive character.											
	Not Applicable	Not Applicable										
	Does not meet any of the above Pueblo landmark criteria.											
39.	Area(s) of Significance: Not Applicable											
40.	Period of Significance: n/a											
41.	Level of significance: National: State Local											

(Resource number)

# **Architectural Inventory Form**

Page 5

42. Statement of significance:

Because this property is less than 50 years old and does not meet any of criteria considerations A through G, it is ineligible for listing in the National Register of Historic Places. Moreover, the architectural and historical significance are not to the extent that the property would qualify for individual listing in the Colorado State Register of Historic Properties or as a City of Pueblo landmark. Given its age, the property should not be considered a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed in 1964, this former dwelling exhibits a moderate level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. This house was remodeled into an office building in 2003. Most of the original windows were replaced and entirely new windows installed.

	windows were replaced and entirely new windows installed.														
/II.	NATIONAI	L REGISTER ELIGIBILITY A	SSESS	MEN	Т										
44.	National Re	☐ Individually eligible			1	Not eligible Not eligible					Need data		ì		
	Local landmark eligibility field assessment:			Individually eligible								■ Need d			
45.	Is there Na	tional Register district potential?	Yes		No										
	Discuss: Pueblo's North Side Neighborhood classes. Its diversity of architectura cultural climates. As well, the neigh the area's dominant industry, steel				l form distin	s directly r	epresen	ts the	city	's ch	angir	ng eco	nomic a	and	of
	If there is National Register district potential, is this building contributing:				ng:	Yes		No		N/A					
46.	6. If the building is in existing National Register district, is it contributing:					Yes		No		N/A	<b>4</b>				

#### **VIII. RECORDING INFORMATION**

47. Photograph numbers): CD-ROM Photo Disc: North Side Photos

File Name(s): courtst1318

Negatives filed at: Special Collections

**Robert Hoag Rawlings Public Library** 

100 East Abriendo Avenue Pueblo, CO 81004-4290

48. Report title: Pueblo North Side Neighborhood Survey

49. Date(s): **08/08/05** 

50. Recorder(s): Adam Thomas

51. Organization: Historitecture, L.L.C.

52. Address: **PO Box 419** 

Estes Park, CO 80517-0419


53. Phone number(s): (970) 586-1165

1318 Court Street 5PE.5798

(Resource number)

# **Architectural Inventory Form**

Page 6




1318 Court Street 5PE.5798

(Resource number)

# **Architectural Inventory Form**

Page 7

# **LOCATION MAP**



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)