
COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

This survey form represents an UNOFFICIAL COPY and is provided for informational purposes only. All information, particularly determinations of eligibility for the National Register, the State Register, or as a local landmark, can and will change. Please contact the Colorado Historical Society Office of Archaeology and Historic Preservation for an official copy of this document.



I. IDENTIFICATION

1.	Resource number:	5BL.10482			Parce	el number:	158320037004
2.	Temporary resource number:						
3.	County:	Boulder					
4.	City:	Eldora					
5.	Historic building name:	Ralph W. an	nd Gladys O. Harlow Ca	bin			
6.	Current building name:	rrent building name: Calvin C. and Lee S.S. Miller Cabin					
7.	7. Building address: 824 Eldorado Avenue						
8.	Owner name:	The Calvin C. and Lee S.S. Miller Revocable Trust					
	Owner organization:						
	Owner address:	523 Colorad	lo Blvd				
		Denver, CO	80206				
44.	National Register eligibility field	l assessment:	☐ Individually eligible		☐ Need data	☐ Previou	ısly listed
	State Register eligibility field assessment:		☐ Individually eligible	■ Not eligible	■ Need data	☐ Previou	usly listed
	Local landmark eligibility field a	☐ Individually eligible	☑ Not eligible	■ Need data	☐ Previou	ısly listed	

Architectural Inventory Form

5BL, 10482 **UNOFFICIAL COPY**

Page 2

ш	CEO	\sim D \wedge	DLIC	INIEODI	JATION
H.	CIEC	ハコベル	NPHIL	HALOKI	MALICIN

9.	P.M.: 6th Township: 1S Range: 73W						
	SW 1/4 NE 1/4 SE 1/4 NE 1/4 of section 20 Grid aligned on northwest corner of section.						
10.	UTM Reference Zone: 13						
	Easting: 450956 Northing: 4422077						
11.	USGS quad name: Nederland Scale: 7.5						
	Year: 1972						
12.	Lot(s): Lot 4						
	Addition: Eldora Subdivision Exemption Plat No. 1 Year of addition: 2000						
13.	Boundary description and justification: The boundary, as described above, contains but does not exceed the land						
	historically associated with this property.						
	☐ Metes and bounds exist						
. ARC	ARCHITECTURAL DESCRIPTION						
14.	Building Plan (footprint, shape): Rectangular Plan						

Ш

Other building plan descriptions:

15. Dimensions in feet: 310 square feet

16: Number of stories:

17: Primary external wall material(s): **Wood/Simulated Log Siding**

Other wall materials:

18: Roof configuration: Gabled Roof/Side Gabled Roof

Other roof configuration:

19: Primary external roof material: **Asphalt Roof/Composition Roof**

Other roof materials:

20: Special features: None Applicable

21: General architectural description:

Oriented to the north, this cabin appears to rest on a concrete foundation. Horizontal, simulated log siding, painted brown, clads the exterior walls. Windows are generally 4-light casement, with green-painted wood frames and surrounds. An 8-over-8-light, double-hung sash window opens in the east end of the front (north) elevation. The principal doorway opens in the north end of the east elevation. Brown asphalt shingles cover the side-gabled roof, and sheets of asphalt cover a shed-roofed addition across the north elevation.

Because of lack of access to this property and poor visibility from the public right-of-way, this cabin could not be fully surveyed.

22. Architectural style: Late 19th And Early 20th Century American Movements/Rustic

Other architectural style:

Building type:

23. Landscape or special setting features:

This property is located within a canyon, just north of Middle Boulder Creek. It is situated on the south side of Eldorado Avenue, the principal east-west thoroughfare through the village of Eldora. Setbacks vary greatly on this road, with this cabin having an unusually deep setback; the cabin is accessed from Eldorado Avenue via a wood foot bridge across a low, marshy area. A stand of aspens nearly conceal the principal building.

24. Associated building, features or objects:

There are no other buildings associated with this property.

IV. ARCHITECTURAL HISTORY

25. Date of Construction: 1935 □ Actual □ Estimate

Source of information: Boulder County Assessor Records. Current records available on-line.

Eldora Survey

Architectural Inventory Form Page 3

5BL.10482 **UNOFFICIAL COPY**

	26.	Architect:	Unknown				
		Source of information:					
	27.	Builder:	Unknown				
		Source of information:					
	28.	Original Owner:	Ralph William and Gladys O. Harlow				
		Source of information:	Warranty Deed 90312973. From W.T. Harpel to Ralph W. and Gladys O. Harlow, 9 January 1935. Boulder County Clerk and Recorder, book 622, p. 137.				
	29.	Construction history:					
	According to Boulder County Assessor records, this cabin was constructed in 1935. An analysis of the style, materia and historical records corroborates this date. Due to a lack of access to this property and poor visibility from the puright-of-way, determining modifications was difficult. However, structural evidence and assessor records suggest that the gabled wing to the east elevation dates to 1985. 30. Location: Original Location Date of move(s):						
V. H	IST	ORICAL ASSOCIAT	TIONS				
		Original use(s):	Domestic/Cabin				
		Intermediate use(s):	Domestic/Cabin				
		Current use(s):	Domestic/Cabin				
	34.	Site type(s):	Vacation Residence				
		Historical background:					
	The first owners of this cabin, constructed in 1935, were Ralph William and Gladys O. Harlow. They purchased the property from W.T. Harpel in late 1934 or early 1935. Ralph Harlow was born in Colorado on June 29, 1900. He sold this property to Elizabeth D. Sawyer in 1955.						
		In 1963, C. Lee Sparkman purchased this property from Elizabeth Sawyer. By 2000, Calvin C. Miller and Lee S.S. Mille acquired much of the eastern half of Block 35, including this property, and resubdivided it. In 2002, they transferred this property, now Lot 4, into the Calvin C. and Lee S.S. Miller Revocable Trust, which remains the current owner.					
		This cabin is one of g 8th Street.	group of nearly identical buildings occupying the southwest corner of Eldorado Avenue and South				
	36.	Sources of information					
		Boulder County Asse	ssor Records.				
		Deeds 90312973, 90	564545, 90564815, 90733357, 2140076, and 2350688. Boulder County Clerk and Recorder.				
	Eldora Subdivision Exemption Plat Map No. 1. 1 June 2001. Boulder County Clerk and Recorder.						
		World War I Draft Re	gistration Card for Ralph William Harlow.				
	ı Index for Ralph W. Harlow.						
VI. S	SIG	NIFICANCE					
	37.	Local landmark designation authority:	ation: Yes No				
		Date of designation:					
	38.	Applicable National Reg	gister criteria:				
		_	events that have made a significant contribution to the broad patterns of our history.				
			he lives of persons significant in our past.				
			tinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or rtistic values, or that represent a significant and distinguishable entity whose components may lack individual				

Architectural Inventory Form Page 4

5BL.10482 **UNOFFICIAL COPY**

	distinction.						
	☐ D. Has yielded, or may be likely to yield, information important in prehistory or history.						
	☐ Qualifies under Criteria Considerations A through G (see manual).						
	☐ Does not meet any of the above National Register criteria.						
	Applicable Colorado State Register criteria:						
	☐ A. Associated with events that have made a significant contribution to history.						
	□ B. Connected with persons significant in history.						
	☑ C. Has distinctive characteristics of a type, period, method of construction or artisan.						
	D. Is of geographic importance.E. Contains the possibility of important discoveries related to prehistory or history.						
	Does not meet any of the above Colorado State Register criteria.						
	Does not meet any of the above colorado state Register Chiena.						
	Applicable Boulder County landmark criteria:						
	1. the character, interest, or value of the proposed landmark as part of the development, heritage, or cultural characteristics of						
	the county;						
	☐ 2. the proposed landmark as a location of a significant local, county, state, or national event;						
	☐ 3. the identification of the proposed landmark with a person or persons significantly contributing to the local, county, state, or						
	national history;						
	🗵 4. the proposed landmark as an embodiment of the distinguishing characteristics of an architectural style valuable for the study						
	of a period, type, method of construction, or the use of indigenous materials;						
	5. the proposed landmark as identification of the work of an architect, landscape architect, or master builder whose work has						
	influenced development in the county, state, or nation;						
	6. the proposed landmark's archaeological significance;						
	☐ 7. the proposed landmark as an example of either architectural or structural innovation; and						
	8. the relationship of the proposed landmark to other distinctive structures, districts, or sites which would also be determined						
	be of historic significance.						
	☐ Does not meet any of the above Boulder County landmark criteria.						
39.	Areas of significance: Architecture						
40.	Period(s) of Significance: 1935						
	Level of Significance: ☐ National ☐ State ☑ Local						
42.	Statement of Significance:						
	This cabin is architecturally significant as an example of the Rustic style. Character-defining features include the log siding and small-paned windows. However, the levels of architectural and historical significance are not to the extent that this property would qualify for individual listing in the National Register of Historic Places, the Colorado State						
	Register of Historic Properties, or as a Boulder County Landmark.						
43.	Assessment of historic physical integrity related to significance:						
	Constructed in 1935, this cabin exhibits a moderate level of physical integrity relative to the seven aspects of integrity						

Architectural Inventory Form


5BL.10482 UNOFFICIAL COPY

Page 5

as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. An addition in the 1980s was isolated to a secondary elevation and did not result in the loss of character-defining features, such as the windows and wall cladding. This building retains sufficient physical integrity to convey its architectural and historical significance.


VII. NA	TIONAL REGISTER ELIGIBI	LITY ASSES	SSMENT			
44.	44. National Register eligibility field assessment: State Register eligibility field assessment: Local landmark eligibility field assessment:		☐ Individually eligible☐ Individually eligible☐ Individually eligible☐ Individually eligible	■ Not eligib	e 🔲 Need da	ata Previously listed ata Previously listed ata Previously listed
45.	45. Is there National Register district potential:		☐ Yes 🛛 No			
Discuss: This survey inventoried properties surrounding but not included within the Eldora National Register I (5BL.758). Moreover, this inventory was conducted as an intensive-level selective survey and therefore lacks t continuity of resource data necessary to determine any expansion of the existing district boundaries or to rec the creation of a new district.						nd therefore lacks the
	If there is National Register distr	this building contributin	g: 🔲 '	Yes □No 🏻	₫ N/A	
46.	If the building is in existing Nation	istrict, is it contributing:		Yes □ No 🛭	₫ N/A	
VIII. RE	CORDING INFORMATION					
47.	47. Digital photograph file name(s): eldoradoave0824 - 1 to - 4					
Digital photographs filed at: Boulder County Parks and Open Space 5201 St. Vrain Rd Longmont, CO 80503						
48.	Report title:	Eldora Historical and Architectural Survey, 2007-08				
49.	Date(s):	9/5/2007				
50:	Recorder(s):	Adam Thomas, Jeffrey DeHerrera, and Sierra Standish				
51:	Organization:	Historitecture, LLC				
52:	Address:	SS: PO Box 419 Estes Park, CO 80517-0419				
53:	53: Phone number(s): (970) 586-1165					

SKETCH MAP



Page 7

LOCATION MAP



Source: U.S. Geological Survey 7.5' Nederland - 1972