
COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

This survey form represents an UNOFFICIAL COPY and is provided for informational purposes only. All information, particularly determinations of eligibility for the National Register, the State Register, or as a local landmark, can and will change. Please contact the Colorado Historical Society Office of Archaeology and Historic Preservation for an official copy of this document.



I. IDENTIFICATION

1.	Resource number:	5BL.10450			Parce	el number:	158320011005
2.	Temporary resource number:						
3.	County:	Boulder					
4.	City:	Eldora					
5.	Historic building name:	Joyce-Hill C	Cabin				
6.	Current building name:	"Deux West	" Cabin				
7.	Building address:	980 Eldorad	lo Avenue				
8.	Owner name:	Gail Gitin					
	Owner organization:						
	Owner address: 7957 Fisher Island Dr						
		Fisher Islan	d, FL 33109				
44.	National Register eligibility field	l assessment:	☐ Individually eligible	☑ Not eligible	☐ Need data	☐ Previou	usly listed
	State Register eligibility field as:	☐ Individually eligible	☑ Not eligible	■ Need data	☐ Previou	usly listed	
	Local landmark eligibility field a	ssessment:	☐ Individually eligible	Not eligible ■ Not eligible Not eligible ■ Not eligible Not eligible	■ Need data	☐ Previou	usly listed

Architectural Inventory Form

5BL.10450 UNOFFICIAL COPY

Page 2

П	GEC	CR		INFORM	ΙΔΤΙΩΝΙ
	. GEC	JURI	чень	IINLOKIV	ини

9.	P.M.:	6th	Town	ship:	1S	Range:	73	W		
	SW	1/4 N	IW 1/-	4 SE	1/4	NE	1/4	of section	20	Grid aligned on northwest corner of section.
10.	UTM I	Referenc	e Zone:	13						
	Eastin	ıg: 4	50664	Nort	thing:	44220	091			
11.	USGS	quad n	ame:	Neder	land	Scale:	7.	.5		
	Year:	197	2							
12.	Lot(s)	Lot	s 18 an	d 19 a	nd the	eastern	half	of Lot 20 a	nd the w	estern 3.5 feet of Lot 17 and the eastern half of Lot 29
	and a	ll of Lo	ts 30 ar	ıd 31,	less th	e easter	n 3.5	feet of Lot	31; Bloc	ek 40
	Additi	on:	Eldora	Year	of add	dition:	189	8		
13.	Bound	dary des	cription	and jus	tification	on: T l	ne bo	undary, as o	describe	d above, contains but does not exceed the land
	histo	rically a	associat	ed wit	h this	property	/ •			
	□ Ме	tes and	bounds	exist						

III. ARCHITECTURAL DESCRIPTION

14. Building Plan (footprint, shape): L-Shaped Plan

Other building plan descriptions:

15. Dimensions in feet: 654 square feet

16: Number of stories: 1

17: Primary external wall material(s): Wood/Log

Wood/Shingle

Other wall materials:

18: Roof configuration: Gabled Roof/Cross Gabled Roof

Other roof configuration:

19: Primary external roof material: Asphalt Roof/Composition Roof

Other roof materials:

20: Special features: Chimney

Fence

21: General architectural description:

Oriented to the north, this cabin rests on an uncoursed, granite rubble foundation. Horizontal, peeled log siding clads the exterior walls. Square-cut wood shingles cover the gables. A small, shed-roofed addition to the east elevation has wood, vertical board-and-batten siding. Windows are generally paired, 6-light hopper or awning, with red-painted wood frames. They have red-painted, wood-frame screens. Piercing the front (north) gable is a 5-light, vertical hopper or awning window. The west elevation has single-light fixed-frame windows. The principal doorway opens in the center of the front-gabled wing. It hosts a 2-light, vertical plank door, with wrought-iron strap hinges, opening behind a red-painted, wood-frame screen door. Approaching the doorway is a low, stone stoop. Brown asphalt shingles cover the cross-gabled roof, and the rafter ends are exposed. Engaged to the west elevation is an uncoursed sandstone stone hearth and chimney. A brick chimney protrudes from the south end of the roof, just west of the north-south roof ridge.

NOTE: The rear (south) elevation of this cabin could not be surveyed due to inaccessibility and dense foliage.

22. Architectural style: Late 19th And Early 20th Century American Movements/Rustic

Other architectural style:

Building type:

23. Landscape or special setting features:

This property is located in mountainous terrain sloping downward from north to south, at an elevation of around 8,600 feet above mean sea level. Houses are irregularly spaced along Eldorado Avenue, the main east-west thoroughfare through the village of Eldora. The landscaping extending northward between this cabin and Eldorado Avenue includes native plants, shrubs, and trees, as well as granite boulders. Running through it is a gravel driveway. Aspen stands grow to the west and south, overshadowed by large pines and spruces. A wood privacy fence lines the eastern edge of the property.

24. Associated building, features or objects:

Eldora Survey

Architectural Inventory Form

5BL.10450 **UNOFFICIAL COPY**

Page 3

A small shed is located southeast of the house. However, dense foliage largely conceals it. The building has red-painted plywood walls. Sheets of red-gray asphalt cover the gabled roof.

	pry wood wans. Sheet	s of red gray aspirant cover the gasted root.					
IV. ARG	CHITECTURAL HIST	TORY					
25.	Date of Construction:	1943 ☑ Actual ☐ Estimate					
	Source of information:	Boulder County Assessor Records. Current records available on-line.					
26.	Architect:	Unknown					
	Source of information:						
27.	Builder:	J.M. Joyce					
	Source of information:	U.S. Census of 1930. Boulder, Boulder County, Colorado. Roll: 231; Page: 1B; Enumeration District: 49; Image: 146.0.					
28.	Original Owner:	J.M. Joyce					
	Source of information:	Warranty Deed 90379153. From Fred J. Wellerd to J.M Joyce, 6 November 1940. Boulder County Clerk and Recorder, book 694, p. 234.					
29.	Construction history:						
	Ü	r County Assessor records, this cabin was constructed in 1943. An analysis of the style, materials, is corroborates this date. The only notable modification has been the addition of a small, shedast elevation.					
30.	Location: Original I	Location Date of move(s):					
V. HIS	TORICAL ASSOCIA	TIONS					
31.	Original use(s):	Domestic/Cabin					
32.	Intermediate use(s):	Domestic/Cabin					
33.	Current use(s):	Domestic/Cabin					
34.	Site type(s):	Vacation Residence					
35.	Historical background:						
	year he purchased lo in 1940. Joyce appe Hill purchased it fro the H.B. Hill Coal & remained in the Hill	rpenter and house builder J.M. Joyce began assembling the lots he needed to build this cabin. That ots 20 and 21 in block 40 from William T. Harpel. Lots 18 and 19 he acquired from Fred J. Wellerd ars to have built the cabin, completed in 1943, on speculation because Edgar B. Hill Jr. and Elaine m him in 1944. A mining chemist, Hill was the son of Edgar B. Hill Sr., founder and president of Lumber Company and longtime Boulder County commissioner in the 1920s and '30s. The property family for more than 60 years, passing from Elaine Hill's estate to her daughter and son-in-law, obson. The Jacobsons sold the cabin and lots in 1999 to Gail Gitin, the current owner and					
36.	Sources of information	n:					
	Boulder County Assessor Records.						
	U.S. Census of 1930. Boulder, Boulder County, Colorado. Roll: 231; Page: 5A; Enumeration District: 48; Image: 121.0.						
	U.S. Census of 1930. Boulder, Boulder County, Colorado. Roll: 231; Page: 1B; Enumeration District: 49; Image: 140						
	Deeds 2862251, 2791491, 1992181, 1651534, 151877, 90415958, 90379153, and 90344794. Boulder County Clerk and Recorder.						
VI. SIG	NIFICANCE						
37.	Local landmark design	ation: Yes 🛮 No					

V

Designation authority:

Date of designation:

38. Applicable National Register criteria:

Architectural Inventory Form Page 4

5BL.10450 **UNOFFICIAL COPY**

	A. Associated with events that have made a significant contribution to the broad patterns of our history.
	☐ B. Associated with the lives of persons significant in our past.
	🗵 C. Embodies the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or
	that possess high artistic values, or that represent a significant and distinguishable entity whose components may lack individual
	distinction.
	D. Has yielded, or may be likely to yield, information important in prehistory or history.
	☐ Qualifies under Criteria Considerations A through G (see manual).
	☐ Does not meet any of the above National Register criteria.
	Applicable Colorado State Register criteria:
	☐ A. Associated with events that have made a significant contribution to history.
	☐ B. Connected with persons significant in history.
	☑ C. Has distinctive characteristics of a type, period, method of construction or artisan.
	☐ D. Is of geographic importance.
	☐ E. Contains the possibility of important discoveries related to prehistory or history.
	☐ Does not meet any of the above Colorado State Register criteria.
	Applicable Boulder County landmark criteria:
	☐ 1. the character, interest, or value of the proposed landmark as part of the development, heritage, or cultural characteristics of
	the county;
	☐ 2. the proposed landmark as a location of a significant local, county, state, or national event;
	☐ 3. the identification of the proposed landmark with a person or persons significantly contributing to the local, county, state, or
	national history;
	🗵 4. the proposed landmark as an embodiment of the distinguishing characteristics of an architectural style valuable for the study
	of a period, type, method of construction, or the use of indigenous materials;
	5. the proposed landmark as identification of the work of an architect, landscape architect, or master builder whose work has
	influenced development in the county, state, or nation;
	6. the proposed landmark's archaeological significance;
	7. the proposed landmark as an example of either architectural or structural innovation; and
	□ 8. the relationship of the proposed landmark to other distinctive structures, districts, or sites which would also be determined to
	be of historic significance.
	Does not meet any of the above Boulder County landmark criteria.
39.	Areas of significance: Architecture
40.	Period(s) of Significance: 1943
41.	Level of Significance:
42.	Statement of Significance:
	This property is significant as an intact example of the Rustic style often found in Colorado summer retreats such as Eldora. Elements of the style embodied in this cabin are log construction, a stone foundation, small-paned windows,

Architectural Inventory Form

UNOFFICIAL COPY


and a stone chimney. However, the levels of architectural and historical significance are not to the extent that this property would qualify for individual listing in the National Register of Historic Places, the Colorado State Register of Historic Properties, or as a Boulder County Landmark.

43. Assessment of historic physical integrity related to significance:

Constructed in 1943, this cabin exhibits a high level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials.


	workmanship, feeling, and association. It has not been notably altered since its construction. This building retains sufficient physical integrity to convey its architectural and historical significance.							
VII. NA	ATIONAL REGISTER ELIGIB	ILITY ASSES	SSMENT					
44.	National Register eligibility field State Register eligibility field ass Local landmark eligibility field as	☐ Individually eligible☐ Individually eligible☐ Individually eligible☐	☑ Not eligible	■ Need data	☐ Previously listed			
45.	Is there National Register distric	t potential:	☐ Yes 🛛 No					
	Discuss: This survey inventoried properties surrounding but not included within the Eldora National Register District (5BL.758). Moreover, this inventory was conducted as an intensive-level selective survey and therefore lacks the continuity of resource data necessary to determine any expansion of the existing district boundaries or to recommend the creation of a new district.							
	If there is National Register distr	ict potential, is	this building contributin	g: 🔲 Y	Yes □ No ☑ N/A			
46.	If the building is in existing Nation	onal Register d	□Y	☐ Yes ☐ No ☒ N/A				
VIII. RI	ECORDING INFORMATION							
47.	Digital photograph file name(s):	eldoradoave	0980 - 1 to - 2					
	Digital photographs filed at:	Boulder County Parks and Open Space 5201 St. Vrain Rd Longmont, CO 80503						
48. Report title: Eldora Historical and Architectural Survey, 2007-08								
49. Date(s): 9/6/2007								
50:	50: Recorder(s): Adam Thomas, Jeffrey DeHerrera, and Sierra Standish							
51:	Organization:	rganization: Historitecture, LLC						
52:	Address:	PO Box 419 Estes Park,	CO 80517-0419					
53:	Phone number(s):	(970) 586-11	165					

SKETCH MAP



Page 7

LOCATION MAP



Source: U.S. Geological Survey 7.5' Nederland - 1972