5PE.517.9

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

Official Eligibility Determination (OAHP use only)

Date _____ Initials

- ____Determined Eligible-National Register
- ____Determined Not Eligible National Register
- ____Determined Eligible State Register
- ____Determined Not Eligible State Register
- ___Need Data
- ___Contributing to eligible National Register District
- ___Noncontributing to eligible National Register District



I. IDENTIFICATION

1.	Resource number:	5PE.517.9		Parcel number(s):	
2.	Temporary resource number:			525424015	
3.	County:	Pueblo			
4.	City:	Pueblo			
5.	Historic building name:	1101 North Greenwo	od Street		
6.	Current building name:	Engineered Systems, Inc.			
7.	Building address:	1101 N Greenwood Street			
8.	Owner name:	Daniel F. and Valerie T. Henderson			
	Owner organization:				
	Owner address:	PO Box 1880			
		Pueblo, Colorado 81	002		
44.	 National Register eligibility field assessment: Local landmark eligibility field assessment: 		Individually eligible	Not eligible	Need data
			Individually eligible	Not eligible	Need data

Page 2

II. GEOGRAPHIC INFORMATION

9.	P.M.: 6th	Township: 20S	Range: 65W
	SW 1/4 of	SE 1/4 of NW 1/4 of SE	1/4 of Section 25
10.	UTM reference zone:	13	
	Easting:	533888	Northing: 4236478
11.	USGS quad name:	Northeast Pueblo	Scale: 7.5
	Year:	1961 (Photorevised 1970 and 1974)	
12.	Lot(s) :	Lots 15 and 16; Block 36	
	Addition:	County Addition	Year of addition: 1869

13. Boundary description and justification:

The boundary, as described above, contains but does not exceed the land historically associated with this property.

Metes and bounds exist:

III. ARCHITECTURAL DESCRIPTION

14.	Building plan (footprint, shape): Other building plan descriptions:	Rectangular Plan	
15.	Dimensions in feet (length x width):	2,080 square feet	
16.	Number of stories:	2	
17.	Primary external wall material(s):	Synthetics/Vinyl	Other wall materials:
18.	Roof configuration: Other roof configurations:	Gabled Roof/Side Gabled Roof	
19.	Primary external roof material:	Asphalt Roof	
	Other roof materials:		
	Special features:		

21. General architectural description:

Oriented to the east, this office building rests on a high concrete foundation. Gray vinyl siding conceals the foundation. Basement windows are 1-over-1-light, single-hung sash, with brown, aluminum frames. Paired, plate-glass doors access the basement in the east end of the south elevation. Gray vinyl siding clads the exterior walls. Windows are 1-over-1-light, singlehung sash, with brown aluminum frames. Blue vinyl shutters flank the windows and above them are blue-vinyl, fan-shaped decorative elements. A front gabled porch protrudes from the north end of the asymmetrical front (east) façade. It has a concrete floor, steel railing, and blue-painted square wood supports. Seven concrete steps approach the center of the porch's east elevation. A concrete ramp approaches from the west. The principal doorway opens in the north side of the facade. It hosts a plate-glass door, with a brown, aluminum frame. A brown-painted, metal slab door opens in the north side of the west elevation. Approaching from the north is a steel staircase. Brown asphalt shingles cover the side-gabled roof. Blue vinyl fascia and soffit box the eaves.

22. Architectural style: No Style

Other architectural styles:

Building type:

23. Landscape or special setting features:

Page 3

This property is located on terrain sloping downward from west to east, with an elevation of around 4,700 feet above mean sea level. The neighborhood features modest one- and two-story houses and commercial buildings. Setbacks from North Greenwood Street are generally the same on this block. This property is situated on the northwest corner of North Greenwood and West 11th streets. Separating the streets from the sidewalks is a gravel-covered strip. A planted-grass yard, with mature landscaping, covers the southeast corner of the property. Dominating the western portion of the parcel is a macadam parking lot.

24. Associated buildings, features or objects: No associated buildings identified.

IV. ARCHITECTURAL HISTORY

25.	Date of Construction:	Estimate:	Actual:	1995
	Source of Information:	Pueblo County Office of Tax	Assessor. F	Property information card [internet].
26.	Architect:	unknown		
	Source of information:			
27.	Builder:	unknown		
	Source of information:			
28.	Original Owner:	unknown		
	Source of information:			
29.	Construction history:			
	According to Rueblo County	Tax Assessor records this bu	uilding was	constructed in 1995. An analysis of the style in

According to Pueblo County Tax Assessor records, this building was constructed in 1995. An analysis of the style, materials, and historical records corroborates this date. There have been no notable alterations to this building since its construction.

30. Location: original Date of move(s):

V. HISTORICAL ASSOCIATIONS

31.	Original use(s):	Medical Business/Medical Office
32.	Intermediate use(s):	Professional
33.	Current use(s):	Professional
34.	Site type(s):	Engineering Office

35. Historical background:

This office building was constructed in 1995 on the site of a large house dating to around 1889. This house was originally home to prominent Pueblo entrepreneur George L. L. Gann, founder and president of the G.L.L. Gann Mercantile Company. By 1909, the owner was another prominent local businessman, John J. Langdon, founder and general manager of the Pueblo Abstract of Title Company. This house however, was demolished prior to 1995, when the current office building was constructed.

According to the current owner, Valerie Henderson, this building was originally constructed to serve as a billing center for 2 local physicians. However, the property ended up in litigation. Daniel F. and Valerie T. Henderson, owners of Engineered Systems, Inc., (ESI) purchased this property as their headquarters in 1998. ESI is an electrical and mechanical engineering firm founded in 1985.

36. Sources of information:

Pueblo County Office of Tax Assessor. Property information card [internet].

Pueblo City Directory. Pueblo, Co.; Salt Lake City; Kansas City, Mo.; and others: R.L. Polk & Co, consulted 1886 through 2003.

Sanborn Fire Insurance Maps (for Pueblo, Colorado). New York: Sanborn Map and Publishing Co., 1883, 1886, 1889, 1893, 1904-05, 1904-51, and 1904-52.

Henderson, Valerie. Interview with Adam Thomas, 9 August 2005.

Page 4

"About Engineered Systems, Inc." Article available on-line from http://www.esipb.com/about.htm. Internet. Accessed on 10 July 2006.

4

Page 5

VI. S	SIGNIFICANCE	
37.	Local landmark designation: Yes 🔲 No 🔽	
07.	Designation authority:	
	Date of designation:	
38.	Applicable National Register criteria:	
50.		
	 A. Associated with events that have made a significant contribution to the broad pattern of our history. B. Associated with the lives of persons significant in our past. 	
	 B. Associated with the lives of persons significant in our past. C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work 	
	of a master, or that possess high artistic values, or represents a significant and distinguished entity whose	
	components may lack individual distinction. D. Has yielded, or may be likely to yield, information important in history or prehistory. 	
	Qualifies under Criteria Considerations A through G (see manual).	
	Does not meet any of the above National Register criteria.	
	Pueblo Standards for Designation:	
	1a. History	
	Have direct association with the historical development of the city, state, or nation; or	
	1b. History	
	Be the site of a significant historic event; or	
	<u>1c. History</u>	
	Have direct and substantial association with a person or group of persons who had influence on society.	
	2a. Architecture	
	Embody distinguishing characteristics of an architectural style or type; or	
	<u>2b. Architecture</u>	
	Be a significant example of the work of a recognized architect or master builder, or	
	 <u>2c. Architecture</u> Contain elements of architectural design, engineering, materials, craftsmanship, or artistic merit which represent a 	
	significant or influential innovation;	
	2d. Architecture	
	Portray the environment of a group of people or physical development of an area of the city in an era of history characterized by a distinctive architectural style.	
	<u>3a. Geography</u>	
	Have a prominent location or be an established, familiar, and orienting visual feature of the contemporary city, or	
	<u>3b. Geography</u>	
	Promote understanding and appreciation of Pueblo's environment by means of distinctive physical characteristics or rarity; or	
	<u>3c. Geography</u> Make a special contribution to Pueblo's distinctive character.	
	Not Applicable	
	Does not meet any of the above Pueblo landmark criteria.	
39.	Area(s) of Significance: Not Applicable	
40.	Period of Significance: n/a	
41.	Level of significance: National: 🗖 State 🗖 Local 🗖	

Pueblo North Side Neighborhood Survey Historitecture, L.L.C. * PO Box 419 Estes Park, CO 80517-0419 * (970) 586-1165

5

Page 6


42. Statement of significance:

Because this property is less than 50 years old and does not meet any of criteria considerations A through G, it is ineligible for listing in the National Register of Historic Places. Moreover, the architectural and historical significance are not to the extent that the property would qualify for individual listing in the Colorado State Register of Historic Properties or as a City of Pueblo landmark. Given its age, the property should not be considered a contributing resource within any potential historic district.

43. Assessment of historic physical integrity related to significance:

Constructed in 1995, this office building exhibits a high level of physical integrity relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society: location, setting, design, materials, workmanship, feeling, and association. It has not been notably altered since its construction. This property retains sufficient physical integrity to convey its architectural and historical significance.

VII. NATIONAL REGISTER ELIGIBILITY ASSESSMENT



the area's dominant industry, steel manufacturing.

If there is National Register district potential, is this building contributing:

46. If the building is in existing National Register district, is it contributing:

VIII. RECORDING INFORMATION

47.	Photograph numbers):	CD-ROM Photo Disc: North Side Photos File Name(s): greenwoodstn1101
	Negatives filed at:	Special Collections Robert Hoag Rawlings Public Library 100 East Abriendo Avenue Pueblo, CO 81004-4290
48.	Report title:	Pueblo North Side Neighborhood Survey
49.	Date(s):	08/09/05
50.	Recorder(s):	Adam Thomas
51.	Organization:	Historitecture, L.L.C.
52.	Address:	PO Box 419
		Estes Park, CO 80517-0419
53.	Phone number(s):	(970) 586-1165

6

N/A

N/A


Yes

Yes

No


No

Page 7



Page 8

LOCATION MAP



Source: U.S. Geological Survey 7.5' Northeast Pueblo topographic quadrangle - 1961 (Photorevised 1970 and 1974)

8