
COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Page 1

This survey form represents a **DRAFT** only. All information, particularly determinations of eligibility for the National Register, the State Register, or as a local landmark, can and will change. If you would like to make additions or corrections to the information contained in this document, please contact Historitecture.

www.historitecture.com/contactus.html



I. IDENTIFICATION

1. Resource number: 5BL.11026 Parcel number: 158136119006

Temporary resource number: Not Applicable
 County: Boulder
 City: Wondervu

Historic building name: Harold and Loraine Millard Cabin
 Current building name: Eugene and Virginia Caranci Cabin

7. Building address: 27 Millard Road

8. Owner name: Eugene A. and Virginia L. Caranci

Owner organization:

Owner address: 1101 Main Street

Louisville, CO 80027-1727

44.	National Register eligibility field assessment:	☐ Individually eligible	Not eligible	☐ Need data	☐ Previously listed
	State Register eligibility field assessment:	☐ Individually eligible	■ Not eligible	☐ Need data	☐ Previously listed
	Local landmark eligibility field assessment:	☐ Individually eligible	■ Not eligible	☐ Need data	☐ Previously listed

DRAFT

5BL.11026

Architectural Inventory Form

Page 2

DRAFT

II. GEOGRAPHIC INFORMATION

9. P.M.: 6th Township: 1S Range: 72W

SE 1/4 SE 1/4 NW 1/4 NE 1/4 of section 36 Grid aligned on northwest corner of section.

10. UTM Reference Zone: 13

Easting: 466307 Northing: 4419460

11. USGS quad name: Tungsten Scale: 7.5

Year: **1972**

12. Lot(s): Lots 2 through 10 inclusive; Block 7 South

Addition: Wondervu Project Year of addition: 1936

13. Boundary description and justification: The boundary, as described above, contains but does not exceed the land historically associated with this property.

☐ Metes and bounds exist

III. ARCHITECTURAL DESCRIPTION

14. Building Plan (footprint, shape): Rectangular Plan Other building plan descriptions:

15. Dimensions in feet: 420 square feet

16: Number of stories: 1 1/2

17: Primary external wall material(s): Wood/Simulated Log Siding

Other wall materials:

18: Roof configuration: Gabled Roof/Side Gabled Roof

Other roof configuration:

19: Primary external roof material: Asphalt Roof/Composition Roof

Other roof materials:

20: Special features: Chimney

Porch

21: General architectural description:

Oriented to the south, this cabin rests on a random-coursed granite foundation. Unpainted, simulated log siding clads the exterior walls. Windows are 6- to 8-light casement, with brown-painted wood frames and surrounds. The gables host small, 4-light casement windows. The principal doorway opens near the center of the asymmetrical front (south) façade. It hosts a vertical simulated log door, opening behind a wood-framed screen door. Spanning the entire rear (north) elevation is a integral porch, enclosed temporarily for the winter with plywood. A random-coursed granite hearth and chimney are engaged to the center of the west elevation. A small, unsheltered, second-story deck is attached to the east elevation. A wood staircase approaches the deck from the south. Gray, interlocking asphalt shingles cover the side-gabled roof and wrap around the fascia board. The rafter ends are exposed.

22. Architectural style: Late 19th And Early 20th Century American Movements/Rustic

Architectural Inventory Form

5BL.11026 **DRAFT**

Page 3

Other architectural style:

Building type:

23. Landscape or special setting features:

This property is located on an east-west-oriented ridge top, at an elevation of over 8,600 feet above mean sea level. Houses are irregularly spaced along Millard Road, an unpaved street running generally east to west. The terrain slopes steeply downward from south to north. While the lot lacks formal landscaping, it is covered with mature pines and aspens. A circular driveway is located in front (south of) the cabin. Retaining walls of dry-laid granite stones define terraces in front of the cabin and help create paths to the driveway and privy.

24. Associated building, features or objects:

Privy

A privy is located near the southeast corner of the lot. Oriented to the northwest, the building appears to lack a formal foundation. However, dry-laid granite stones cover the lower third to half of the building. The walls consists of unpainted, vertical wood planks. Dominating the front (northwest elevation) is a vertical plank door, on metal strap hinges. Above the doorway is a small vent covered with a wire-mesh screen. Red sheets of asphalt cover the shed roof.

IV. ARCHITECTURAL HISTORY

25. Date of Construction: 1936

☐ Actual ☐ Estimate

Source of Information: Boulder County Assessor Records.

Deed 90727212. Boulder County Clerk and Recorder.

26. Architect: **Unknown** Source of Information:

27. Builder: **Unknown**Source of Information:

28. Original Owner: Harold and Loraine Millard

Source of Information: Deed 90727212. Boulder County Clerk and Recorder.

29. Construction history:

According to Boulder County assessor records, this cabin was constructed in 1936. An analysis of the style, materials, and other historical records corroborates a 1936 date of construction. The only notable modification has been the installation of a deck and staircase on the east elevation.

30. Location: Original Location Date of move(s): Not Applicable

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Domestic/Cabin

32. Intermediate uses(s): Domestic/Cabin

33. Current uses(s): Domestic/Cabin

34. Site type(s): Cabin

DRAFT

Architectural Inventory Form

Page 4

DRAFT

35. Historical background:

This cabin was constructed in 1936 for Harold W. and Loraine H. Millard, namesakes of Millard Road. Harold Millard was born on September 3, 1895, in Battle Creek, Michigan. He and his wife, Loraine, were married around 1926. She was born in Colorado around 1896. In 1930 the couple resided at the Park Dearborn Hotel in Chicago. Harold worked as a department store salesman and Loraine was a church secretary. Soon afterward they moved to Denver, where Harold was a salesman at the Daniels & Fisher department store. The couple retained this cabin and lots until 1963, when they sold them to Elaine R. and Markley "Mark" G. Metzger. Harold Millard died on December 17, 1987, in Denver. David and Ruth V. McGuire acquired the property from the Metzgers in 1972. The current owners, Eugene A. and Virginia Caranci, acquired cabin and lots from the McGuires in 1985.

36. Sources of information:

Boulder County Assessor Records.

Deeds 90727212, 00020231, and 00670268. Boulder County Clerk and Recorder.

U.S. Census of 1930. Chicago, Cook County, Illinois. Roll 484; Page: 25B; Enumeration District: 1597; Image: 953.0.

U.S. Census of 1900. Battle Creek Ward 2, Calhoun County, Michigan. Roll T623_704; Page: 7A; Enumeration District: 31.

Social Security Death Index Record for Harold W. Millard.

VI. SIGNIFICANCE

37.	Local landmark designation: ☐ Yes ☑ No
	Designation authority:
	Date of designation:
38.	Applicable National Register criteria:
	A. Associated with events that have made a significant contribution to the broad patterns of our history.
	☐ B. Associated with the lives of persons significant in our past.
	🗵 C. Embodies the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or that possess high
	artistic values, or that represent a significant and distinguishable entity whose components may lack individual distinction.
	D. Has yielded, or may be likely to yield, information important in prehistory or history.
	Qualifies under Criteria Considerations A through G (see manual).
	☐ Does not meet any of the above National Register criteria.
	Applicable Colorado State Register criteria:
A. Associated with events that have made a significant contribution to history.	
	☐ B. Connected with persons significant in history.
	☑ C. Has distinctive characteristics of a type, period, method of construction or artisan.
	☐ D. Is of geographic importance.
	☐ E. Contains the possibility of important discoveries related to prehistory or history.
	☐ Does not meet any of the above Colorado State Register criteria.
	Applicable Boulder County landmark criteria:
	1. the character, interest, or value of the proposed landmark as part of the development, heritage, or cultural characteristics of the county;
	2. the proposed landmark as a location of a significant local, county, state, or national event;
	3. the identification of the proposed landmark with a person or persons significantly contributing to the local, county, state, or national history;
	🗵 4. the proposed landmark as an embodiment of the distinguishing characteristics of an architectural style valuable for the study of a period, type,
	method of construction, or the use of indigenous materials;

DRAFT

Architectural Inventory Form

Page 5

JUL. I	1020		
DR	ΔFT		

	5. the proposed landmark as identification of the work of an architect, landscape architect, or master builder whose work has influenced development in the county, state, or nation;						
	6. the proposed landmark's archaeological significance;						
	7. the proposed landmark as an example of either architectural or structural innovation; and						
	8. the relationship of the proposed landmark to other distinctive structures, districts, or sites which would also be determined to be of historic significance.						
	☐ Does not meet any of the above Boulder Cour	Does not meet any of the above Boulder County landmark criteria.					
30	. Areas of significance: Social History						
39.	Architecture						
40.		150: Architecture 1036					
то.	. Period(s) of Significance: Social History, 1936-1959; Architecture, 1936						
41.	Level of Significance: ☐ National ☐ State ☑ Local ☐ Not Applicable						
42.	. Statement of Significance:						
	This property is historically significant for its asso	ociation with the developm	ent of Wondervu, a collection	of mountaintop summer cabins. This			
	building is one of the earliest cabins in Wonderv	u. It is also architecturally s	ignificant as an example of th	e Rustic style. Character-defining			
	features include log siding, rough native stonew	•	•				
	historical or architectural significance, this proper		· -	ing in the National Register of Historic			
	Places, the Colorado State Register of Historic Pr	pperties, or as a Boulder Co	ounty Landmark.				
43.	. Assessment of historic physical integrity related to	significance:					
	Constructed in 1936, this cabin exhibits a high level of physical integrity relative to the seven aspects of integrity as defined by the National Park						
	Service and the Colorado Historical Society: loca altered since its construction. This building retai						
NIA			ity to convey its instorical and	a architectural significance.			
. IVA	ATIONAL REGISTER ELIGIBILITY ASSESSM	ALIN I					
44.	. National Register eligibility field assessment:	☐ Individually eligible	■ Not eligible	☐ Previously listed			
	State Register eligibility field assessment:	☐ Individually eligible	Not eligible ☐ Need data	☐ Previously listed			
	Local landmark eligibility field assessment:	☐ Individually eligible	■ Not eligible Need data	☐ Previously listed			
45	. Is there National Register district potential:	☐ Yes 🛛 No					
			ov and therefore lacks the con	tinuity of resource data necessary to			
	Discuss: This inventory was conducted as an intensive-level selective survey and therefore lacks the continuity of resource data necessary to recommend the creation of an historic district.						
	If there is National Register district potential, is this	s building contributing:	☐ Yes ☐ No 🗖 N/A				
			Z				
46.	. If the building is in existing National Register distri	ct, is it contributing:	☐ Yes ☐ No 🗖 N/A				
I RE	ECORDING INFORMATION						
0.115							

5BL.11026 **DRAFT**

Architectural Inventory Form

DRAFT

Page 6

47. Digital photograph file name(s): millardrd0027 - 1.tif to millardrd0027 - 6.tif

Digital photographs filed at: Boulder County Parks and Open Space

5201 St. Vrain Road Longmont, CO 80502

48. Report title: Wondervu Historical and Architectural Survey, 2009-10

49. Date(s): **09/28/2009**

50: Recorder(s): Adam Thomas

51: Organization: Historitecture, LLC

52: Address: PO Box 419

Estes Park, CO 80517-0419

53: Phone number(s): (970) 586-1165


Page 7

SKETCH MAP



Page 8

LOCATION MAP



Source: U.S. Geological Survey 7.5' Tungsten - 1972